

(08/11/13) wet

ASS. REC. BY: Jan

REF:

CS/00122012329/Rvp3

095P

ASSIGNMENT

08/11/14: 2025/MAY

From: _____ Date: _____

Estimated Cost: _____

OB / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKS 8450Bat Workshop m/s TRANSBURKARSof 27A, Tanjong PagarInsured: Uol

Policy No. _____

Claims No. M12D00162212Sum Insured: _____ Excess: TBA 750

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☒
N/S	O/S
☐	☐

Bal. or Market Value: 36k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKS 8450B Yr Regn: 2015 / MAY

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MAZDA 340R SEDAN 1.5L SP c.c 1496Colour: RED A/C: Insured / Std / NI / NASp. Reading: 101250 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6BM42A8G0309944

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 01/12/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

6/3 FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIAT - 15K

15/6/23 RS \$12,000 (Red 305.20, 2%)

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2) 16/6/23-typist

Days Of Repair: 6

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Report Format : OD

Lump Sum / I.B.I. (\$) _____

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	02/12/2022 15:51 (SGT)
Reported by	Driver
Date of Accident	01/12/2022 16:10 (SGT)
Exact Location of Accident	Taman Sentosa, Jchor Bahru, Johor, Malaysia
Additional Location Information	-
Country/State of Loss	Malaysia

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKS8450B
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	TAN LI CHIN
NRIC No	SXXXX095F
Email Address	zilzz@yahoo.com
Mobile Phone No	(Phone) +65-98425263
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Mazda
Model	3
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1496

INSURANCE COMPANY

Name of Insurance Company	United Overseas Insurance Ltd
Policy Number / Cover Note Number	DHOM120050972001

DRIVER

Name of Driver	TAN LAY KOK
NRIC No	SXXXX724D
Date Of Birth	10/08/1952
Occupation	Indoor

Date Of Driving Pass	30/08/1973
Driving experience	49 YEARS AND 4 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96793084
Alt. Phone Number	-
Email Address	zilzz@yahoo.com
Address	BLK 680A JURONG WEST CENTRAL 1 #11-36
Address complement	-
Postcode	641680
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Parent
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Major/Minor Rd
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	Yes
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

FOREIGN VEHICLE 1

Vehicle Registration Number	JLT81
Vehicle Category	Private car

PASSENGER 1

Name	LEE TECK HWEE
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Jurong West Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18002689999
Alt. Police Station Phone No	(Fax) +65-62672438
Police Station Address	700 Corporation Road Singapore 649818
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO POLICE REPORT J/20221202/2002

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	JLT81
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	LEE TECK HWEE
Gender	Female
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	SERIOUS INJURIES
Injured person in which vehicle?	SKS8450B
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

INJURED 2

Name of injured person	TAN LAY KOK
Gender	Male
Phone No	(Phone) +65-96793084
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	SERIOUS INJURIES
Injured person in which vehicle?	SKS8450B
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"); the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

Sketch Plan

Diagram illustrating the accident scene sketch plan. The diagram shows a road layout with a central lane and two side lanes. A vehicle is shown in the central lane, with an arrow pointing to it labeled 'A) SC58450B'. Another vehicle is shown in the side lane, with an arrow pointing to it labeled 'B) JLT 81'. The diagram is titled 'TOWMAN (SAFURA) (MAY 2022)'.

1/2/2022

Describe Circumstance of the Accident

REFER TO POLICE REPORT J/2022/202/2002

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder)
/ Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRBCID card)

Jun 2022

2



**SINGAPORE
POLICE FORCE**



J/20221202/2002

1 of 1

POLICE REPORT (NP299)

Report No. J/20221202/2002

Police Station Of Origin
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

Date/Time Report Made 02/12/2022 00:47	Vide Report No.	Station Diary No. 10	
Name Of Informant TAN LAY KOK	Address APT BLK 680A JURONG WEST CENTRAL 1 #11-36 SINGAPORE 641680		
ID Type / ID No. NRIC NO / S0140724D	Contact No. Home/Office	Mobile 96793084	
Nationality SINGAPORE CITIZEN	Email Address		
Occupation Carpenter	Sex Male	Age 70	Date of Birth 10/08/1952
Institution/School Name	Race Chinese		
Date/Time Of Incident 01/12/2022 16:10	Language English		
	Location Of Incident MALAYSIA		

Brief details.

On 01/12/2022 at about 1610hrs, I was driving my vehicle bearing the plate number SKS8450B at Taman sentosa as I was driving straight and there was a vehicle bearing the plate number JLT81 coming from a filter lane did not give way as such we collided. I wish to state that during the accident my wife namely Lee Teck hwee sustain injuries. Her injuries are broken nose and stich on her right eye brown area. I sustain pain on my shoulder area as well as pain around my neck area.

Signature Of Officer Recording The Report: J / SGT 2 LINUS LEOK YI QUAN 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 02/12/2022 00:47
Officer In-Charge Of Case: J / Jurong Police Divisional Investigation Branch / SR STAFF SGT NEO YING XUAN Contact No.: 63167667	Classification Of Case:



POLIS DIRAJA MALAYSIA
CAWANGAN TRAFIK
IBU PEJABAT POLIS DAERAH JOHOR BAHRU SELATAN,
JALAN TEBRAU, 80250 JOHOR BAHRU
07-2237977

POL.316

Resit Aduan Penerimaan Repot Polis :

Nama Pengadu : TAN LAY KOK
No Kad Pengenalan / Paspot : S0140724D
No Repot Polis : TRAFIK JOHOR BAHRU(S)/025533/22
Tarikh @ Masa Repot Polis : 01/12/2022 @ 17:25
Pengesahan Penerimaan Repot :

Tandatangan Ketua Pejabat Pertanyaan

Pegawai Penyiasat :

Nama Pegawai Penyiasat : (R104724) SJN KAMARUDDIN B YUSOF
Tempat Tugas : JOHOR, J/BAHRU SELATAN
No Telefon Pejabat : No Telefon Bimbit : 013-7495719

Tarikh @ masa Perjumpaan :

Pengesahan Penerimaan Repot :

Tandatangan Pegawai Penyiasat

Juru Gambar :

Nama : No Badan : Pangkat :

Tarikh @ Masa Gambar Diambil :

Pengesahan Gambar Diambil :

Tandatangan Juru Gambar

Unit Pembekalan Dokumen Siasatan :

No Telefon Unit Pembekalan Dokumen :

Waktu Pejabat :

Ahad - Rabu : 08:00 Pagi - 01:00
Tengah Hari 02:00 Petang - 04:00
Petang Khamis : 08:00 Pagi - 01:00
Tengah Hari 02:00 Petang - 02:30
Petang Rehat - 1.00 T/Hari-2.00 Petang
Jumaat, Sabtu-Tutup Cuti

Jenis Dokumen Dibekal Kepada Pengadu :

1. Salinan Repot Polis
2. Gambar Kenderaan
3. Rajah Kasar Kemalangan
4. Keputusan Siasatan
5. Lain-lain Dokumen

Tarikh @ Masa Dokumen Diserah :

Pengesahan Kaunter Pembekalan
Dokumen :

Tandatangan Pegawai Kaunter
Pembekalan Dokumen

12
31

013-4549996

King

97302017

Group A

Name & Address:

UNITED OVERSEAS INSURANCE LTD
3 ANSON ROAD
#28-01 SPRINGLEAF TOWER
SINGAPORE 079909

Vehicle No:

SKS8450B

Date:

9-Dec-22

Brand & Model:

MAZDA 3

Franchise:

Mazda

Email/Fax No.

Contact No:

Chassis/VIN No:

JM6BM42A8G0309944

Contact Person (Eurokars)/Wip No:

SHAWN / 54213

Type of Claim:

Policy No:

Date Of Registration:

12/05/2015

Contact No (Eurokars):

6331 0680

OWN DAMAGE

PARTS / MATERIAL CHARGES			MARK = Survey Marking [Key "A" if item is approved]			
NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	FRONT BUMPER <i>de /</i>	MBHR3-50-031BBB	1		-	\$ 994.32
2	RETAINER RH FRONT <i>ca /</i>	MBHN1-50-0T1F	1		-	\$ 15.77
3	RETAINER LH FRONT <i>X</i>	MBHN1-50-0U1E	1		-	\$ 15.77
4	BRACEKT RH BUMPER <i>?</i>	MBHN1-50-152	1		-	\$ 13.91
5	COVER FOG LAMP RH <i>ms /</i>	MBJE1-50-C11A	1		-	\$ 51.50
6	CHROME COVER FOG LAMP RH <i>ms /</i>	MBJE1-50-C12	1		-	\$ 119.35
7	STIFF'A', BUMPER <i>?</i>	MBHN1-50-0S0B	1		-	\$ 94.57
8	COVER BUMPER (TRIANGLE) <i>?</i>	MBHN1-50-101	1		-	\$ 30.77
9	GROMMET, SCREW <i>m /</i>	MGHP9-50-0Z5	2		-	\$ 4.72
10	NUT, CLIP <i>m /</i>	MC274-50-133	12		-	\$ 28.32
11	FASTENER <i>m /</i>	MB45A-56-146A	2		-	\$ 4.72
12	FRONT GRILLE RADIATOR <i>ms cm /</i>	MBJE1-50-712B	1		-	\$ 656.34
13	CHROME MOULD FRONT RH <i>X</i>	MBHN1-50-7J1A	1		-	\$ 198.92
14	BRACEKT RH FRONT GRILLE <i>X X</i>	MBHN1-50-153	1		-	\$ 13.91
15	BRACKET LH FRONT GRILLE <i>X X</i>	MBHN1-50-163	1		-	\$ 13.91
16	PIN, LOCATOR <i>BS ?</i>	MKD45-50-1K5A	2		-	\$ 4.72
17	GROMMET <i>m /</i>	MKD45-50-ES1	2		-	\$ 4.72
18	FASTENER <i>m /</i>	MEA01-50-037	2		-	\$ 14.68
19	BRACEKT TOP FRONT GRILLE RADIATOR <i>?</i>	MBHN1-50-717D	1		-	\$ 126.69
20	FASTENER <i>m /</i>	MGD7A-50-EA1	8		-	\$ 20.96
21	FRONT GRILLE RADIDATOR TOP <i>X</i>	MBHN1-50-033 13	1		-	\$ 377.94
22	FASTENER <i>m /</i>	MS51S-51-833	6		-	\$ 18.72
23	RIVET <i>m /</i>	MTK21-50-355	4		-	\$ 29.68
24	PLATE SET FRONT REINFORCEMENT <i>?</i>	MBHN3-50-1C0	1		-	\$ 84.80
25	FASTENER <i>?</i>	MGD7A-50-EA1	4		-	\$ 10.48
26	FRONT REINFORCEMENT <i>?</i>	MB45A-50-070A	1		-	\$ 576.77
27	UPPER SUPPORT PANEL FRONT <i>X</i>	MB45A-53-150A	1		-	\$ 133.26
28	PLATE SEAL RH FRONT SUPPORT PANEL <i>?</i>	MBHN1-50-1U1A	1		-	\$ 39.37
29	FASTENER <i>m /</i>	MKD45-50-EA1	4		-	\$ 9.44
30	FRONT FENDER RH <i>ms /</i>	MB45A-52-111B	1		-	\$ 348.10
31	STAY FENDER RH <i>bt /</i>	MB4ZA-52-1R0A	1		-	\$ 58.58
32	MUD GUARD RH FRONT <i>de /</i>	MB45A-56-130H	1		-	\$ 121.80

33	SPLASH SHIELD RH FRONT ?	MB45A-56-114B	1	-	\$	27.06
34	FASTENER m/	MB45A-56-146A	10	-	\$	23.60
35	HEADLAMP RH bro/	MBHT6-51-031A	1	-	\$	2,975.04
36	H I D CONTROL UNIT HEADLAMP ?	MBHN3-51-0H3	1	-	\$	1,112.07
37	O R I N G H I D CONTROL UNIT ?	MC236-51-0B2	1	-	\$	12.98
38	COVER SOCKET HEADLAMP ?	MC514-51-0A1A	1	-	\$	25.21
39	RIVET m/	MB092-51-833	1	-	\$	2.95
40	BULB HEADLAMP ?	M9070-39-350	1	-	\$	621.11
41	TANK WASHER de/	MGHP9-67-481A	1	-	\$	117.50
42	GROMMET, WASHER TANK m/	MKD35-67-491	1	-	\$	5.57
43	GROMMET, WASHER TANK m/	MG22C-67-491	1	-	\$	6.49
44	PUMP WASHER TANK ?	MEG22-67-482	1	-	\$	72.57
45	NOZZLE WASHER HEADLAMP RH mis/	MBHT4-51-82X	1	-	\$	301.16
46	CLAMP m/	MTK33-51-829	1	-	\$	14.84
47	COVER NOZZLE WASHER HEADLAMP RH mis/	MBHT4-51-8G1 62	1	-	\$	105.87
48	PIPE NOZZLE WASHER HEADLAMP ?	MBHT4-51-410	1	-	\$	170.43
49	LAMP SIGNAL TURN FRONT RH bro/	MB45A-51-350A	1	-	\$	185.52
50	BRACEKT FOG LAMP RH ?	MBHR1-51-684A	1	-	\$	15.77
51	FOG LAMP RH ?	MTK21-51-680A	1	-	\$	377.94
52	FRONT WINDSCREEN ?	MBJF7-63-900	1	-	\$	1,170.90
53	TAPE ?	MBHR1-50-898	1	-	\$	7.42
54	SHEET, RAIN SENSOR ?	MC513-66-5G2	1	-	\$	33.21
55	FRONT SUPPORT PANEL ?	MGHR4-53-110B	1	-	\$	479.34
56	IU STICKER ?	M11-ERPBRK-	1	-	\$	8.00
57					\$	-

Sub-Total (Parts Price) \$ - \$ 12,110.06

LABOUR / SERVICES CHARGES

NO	DESCRIPTION	REVISED	PRICE
1	TO REPLACE FRONT BUMPER . FRONT SUPPORT PANEL AND FRONT FENDER RH.	1650	\$ 2,400.00
2	TO RESPRAY FRONT BUMPER , FRONT GRILLE RADIATOR TOP , FRONT FENDER RH , BONNET AND FRONT DOOR RH.	2520	\$ 3,300.00
3	TO TRANSFER / REPLACE FRONT SENSOR.	330	\$ 660.00
4	TO REPLACE FRONT WINDSCREEN AND CONDUCT WATER TEST LEAK	NETT	\$ 560.00
5	TO SUPPLY SEALANT ON THE FRONT WINDSCREEN. ?	NETT	\$? 120.00
6	TO SUPPLY SOLAR FILM FRONT WINDSCREEN. ?	NETT	\$? 280.00
7	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
8	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	250	\$ 300.00
9	SUNDRIES.	20	\$ 50.00

Survey Date & Time:	Repair Days:	Excess:
---------------------	--------------	---------

Surveyor Remarks:

Sub-Total (Labour Price) \$ - \$ 7,620.00

	REVISED	PRICE
Parts Price	\$ -	\$ 12,110.06
Labour Price	\$ -	\$ 7,620.00
Total (Initial Estimate)	\$ -	\$ 19,730.06

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- A fee of \$400 (excl. GST) will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

Supp 1	\$	-	\$	-
Supp 2	\$	-	\$	-
Supp 3	\$	-	\$	-
Total (Before Excess)	\$	-	\$	19,730.06
Less Excess	\$	-	\$	-
TOTAL (After Excess)	\$	-	\$	19,730.06
GST 7%	\$	-	\$	1,381.10
GRAND TOTAL	\$	-	\$	21,111.16

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068
5 days
P/P
09/12/22 @ 1610
EXCESS: TBA
Revert
Resurvey before part.

Vin's

Vin's Motor Pte Ltd

160 Sin Ming Drive

#03-03 Sin Ming Autocity

Singapore 575722

Tel : 6453 2121 Fax : 6459 9795

GST Registration No. 199906067G

Estimated Cost of Repair

Key mind
\$ 8563.7

Attention To : United Overseas Insurance

3 Anson Road
#28-01 Springleaf Tower
Singapore 079909

Claim Details

Case Ref. No. : OD/122022/5852

Date : 16-12-2022

Accident Date : 01-12-2022

Vehicle Details

Make & Model : Mazda MAZDA3 4-DOOR SEDAN
1.5L SP.6EAT

Chassis No : JM6BM42A8G0309944

Registration No : SKS8450B

S/N	Description	Qty	Amount (\$\$)
1	FRONT BUMPER (ORDER) <i>de</i>	1.00	\$850.00 ✓
2	FRONT RH RETAINER <i>ne</i>	1.00	\$10.00 ✓
3	FRONT LH RETAINER <i>ne</i>	1.00	\$10.00 ✓
4	FRONT BUMPER RH BRACKET <i>ne</i>	1.00	\$10.00 ✓
5	RH FOG LAMP COVER <i>me</i>	1.00	\$30.00 ✓
6	RH FOG LAMP COVER CHROME <i>me</i>	1.00	\$70.00 ✓
7	STIFF 'A' BUMPER <i>ne</i>	1.00	\$50.00 ✓
8	BUMPER COVER (TRIANGLE) <i>ne</i>	1.00	\$20.00 ✓
9	FRONT BUMPER CLIPS <i>ne</i>	10.00	\$20.00 ✓
10	FRONT GRILLE RADIATOR <i>br</i>	1.00	\$420.00 ✓
11	FRONT RH CHROME MOULDING <i>im</i>	1.00	\$110.00 ✓
12	FRONT RH GRILLE BRACKET <i>ne</i>	1.00	\$10.00 ✓
13	FRONT LH GRILLE BRACKET <i>me</i>	1.00	\$10.00 ✓
14	FRONT GRILLE BRACKET CLIPS <i>me</i>	1.00	\$10.00 ✓
15	FRONT GRILLE RADIATOR TOP BRACKET <i>ne</i>	1.00	\$80.00 ✓
16	FRONT GRILLE RADIATOR TOP BRACKET CLIPS <i>me</i>	8.00	\$16.00 ✓
17	FRONT GRILLE TOP RADIATOR <i>cro</i>	1.00	\$280.00 ✓
18	FRONT GRILLE TOP RADIATOR CLIPS <i>ne</i>	6.00	\$12.00 ✓
19	RIVET <i>ne</i>	4.00	\$8.00 <i>\$14.00</i> ✓
20	FRONT REINFORCEMENT PLATE SET <i>ne</i>	1.00	\$40.00 ✓
21	FRONT REINFORCEMENT <i>bf</i>	1.00	\$380.00 ✓
22	FRONT UPPER SUPPORT PANEL <i>cro</i>	1.00	\$80.00 ✓
23	FRONT RH SUPPORT PANEL PLATE SEAL <i>me</i>	1.00	\$20.00 ✓
24	FRONT RH FENDER <i>bf</i>	1.00	\$220.00 ✓
25	STAY RH FENDER <i>ne</i>	1.00	\$30.00 ✓
26	FRONT RH MUD GUARD <i>de</i>	1.00	\$80.00 ✓
27	FRONT RH SPLASH SHIELD <i>de</i>	1.00	\$20.00 ✓
28	FRONT RH SPLASH SHIELD CLIPS <i>ne</i>	10.00	\$20.00 ✓
29	RH HEADLAMP (ORDER) <i>br</i>	1.00	\$2,400.00 ✓
30	HEADLAMP HID CONTROL UNIT <i>br</i>	1.00	\$850.00 ✓

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

31	HEADLAMP COVER SOCKET <i>mis</i>	1.00	\$20.00 ✓
32	HEADLAMP BULB <i>short</i>	1.00	\$450.00 ✓
33	WASHER TANK <i>de</i>	1.00	\$80.00 ✓
34	WASHER TANK PUMP <i>de</i>	1.00	\$50.00 ✓
35	RH HEADLAMP NOZZLE WASHER <i>mis</i>	1.00	\$200.00 ✓
36	RH HEADLAMP NOZZLE WASHER COVER <i>mis</i>	1.00	\$60.00 ✓
37	HEADLAMP NOZZLE WASHER PIPE <i>cut</i>	1.00	\$90.00 ✓
38	FRONT RH TURN SIGNAL LAMP <i>bo</i>	1.00	\$110.00 ✓
39	FOGLAMP RH <i>cm</i>	1.00	\$260.00 ✓
40	FRONT WINDSCREEN <i>2 cm</i>	1.00	\$750.00 ✓
41	RAIN SENSOR SHEET <i>2 cm</i>	1.00	\$20.00 ✓
42	FRONT SUPPORT PANEL <i>cm</i>	1.00	\$320.00 ✓

8582
+ 10%
9440.20

\$8,576.00
\$857.60

Margin: 10%

\$9,433.60 ✓

43	FRONT WINDSCREEN GUM <i>cm</i>	1.00	\$80.00 ✓
44	FRONT WINDSCREEN ERP BRACKET <i>new</i>	1.00	\$15.00 ✓
45	COOLANT <i>new</i>	1.00	\$80.00 ✓
46	TO REFIL AIRCON GAS <i>new</i>	1.00	\$150.00 ✓
47	TO REMOVE AND REPLACE FRONT WINDSCREEN <i>new</i>	1.00	\$180.00 ✓
48	TO RESET HEADLAMP SYSTEM <i>new</i>	1.00	\$280.00 ✓
49	TO REPAIR DAMAGES	1.00	\$980.00 ✓
50	TO SPRAY PAINTING	1.00	\$1,100.00 ✓

2865

Subtotal w/o GST:

\$12,298.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

9440.20
2865.00
12305.20

12K

Resue
Hp 90010068

6 days

L/S

12/05/23

Resue after repair

Issued by Raymond Teo

This is a computer-generated document. No signature is required.



日美汽車私人有限公司

JAE AUTO PTE LTD

BLK 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
80 JALAN LAM HUAT GARROS CENTRE #B1-05/06 SINGAPORE 737869
TEL: 63625226 / 62569633 FAX: 63626977



Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

PAYNOW UEN: 199307741M. PLEASE INDICATE THE INVOICE NUMBER.

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9929



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792

TOYOTA
GENUINE PARTS

LEXUS

DAIHATSU



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

VIN'S MOTOR PTE LTD
160 SIN MING DRIVE #08-09
SIN MING AUTOCITY
SECTOR B
SINGAPORE 575722
TEL: 64532121 VINCENT
ATTN: 4532121

TAX INVOICE : AR202301-00812
DATE : 03/01/2023
CUSTOMER ID : VIN002
VEH REG. NO. : SKS8450B
TERMS : 30 DAYS
PO NO. :
PAGE NO. : Page 1 of 6
CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	BHR3-50-031BB (BWJV) MZ3 BM 2014-	F BUMPER	U1 MZ-B1	1	850.00	850.00 ✓
2.	BHN1-50-0T1F MZ3 BM 2014-	RETAINER.F BUMPER RH	U1 MZ-A32-B	1	10.00	10.00 ✓
3.	BHN1-50-0U1F MZ3 BM 2014-	RETAINER F BUMPER LH	U1 MZ-A32-A	1	10.00	10.00 ✓
4.	BHN1-50-152 MZ3 BM 2014-	BRACKET.H LAMP LOW RH	U1 MZ-C4-B8	1	10.00	10.00 ✓
5.	BJE1-50-C11A MZ3 BM 2014-	GRILLE.F BUMPER RH	U1 MZ-A46	1	30.00	30.00 ✓
6.	BJE1-50-C12 MZ3 BM 2014-	RING.F FOGLAMP OUT RH	U1 MZ-C4-B7	1	70.00	70.00 ✓
7.	BHN1-50-0S0B MZ3 BM BN	STIFF FRT BUMPER	U1 MZ-A105	1	50.00	50.00 ✓

CONTINUE NEXT PAGE

[P] 04/01/2023 10:32:31

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

A



日美汽車私人有限公司

JAE AUTO PTE LTD

BLK 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

60 JALAN LAM HUAT CARROS CENTRE #B1-05/06 SINGAPORE 737869
TEL: 63625226 / 62569633 FAX: 63626977



Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

PAYNOW UEN: 199307741M. PLEASE INDICATE THE INVOICE NUMBER.

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9929



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795



Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

VIN'S MOTOR PTE LTD
160 SIN MING DRIVE #08-09
SIN MING AUTOCITY
SECTOR B
SINGAPORE 575722
TEL: 64532121 VINCENT
ATTN: 4532121

TAX INVOICE : AR202301-00812
DATE : 03/01/2023
CUSTOMER ID : VIN002
VEH REG. NO. : SKS8450B
TERMS : 30 DAYS
PO NO. :
PAGE NO. : Page 2 of 6
CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
8.	BHN1-50-101	COVER.F BUMPER LOW RH(STD)	U1	1	20.00	20.00 ✓
	MZ3 BM 2014-		MZ-C3-C2			
9.	BJE1-50-712B	F GRILLE	U1	1	420.00	420.00 ✓
	MZ3 BM 14-		MZ-B52			
10.	BHN1-50-7J1A	FRT RADIATOR MOULD RH	U1	1	110.00	110.00 ✓
	MZ3 BM 1.5		MZ-B47			
11.	BHN1-50-153	FRT BUMPER BRACKET RH	U1	1	10.00	10.00 ✓
	MZ3 BM 1.5		MZ-A26-J			
12.	BHN1-50-163	FRT BUMPER BRACKET LH	U1	1	10.00	10.00 ✓
	MZ3 BM 1.5		MZ-A35-F			
13.	KD45-50-1K5A	FRT GRILLE CLIP (WHITE PIN)	U1	1	10.00	10.00 ✓
	CX5 KE/MZ6 GJ/ MZ3 BM		MZ-C2-D5			
14.	BHN1-50-717D	GARNISH RADIATOR GRILLE TOP	U1	1	80.00	80.00 ✓
	MZ3 BM		MZ-B44			

CONTINUE NEXT PAGE

[P] 04/01/2023 10:32:31

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

1



日美汽車私人有限公司

JAE AUTO PTE LTD

BLK 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

80 JALAN LAM HUAT CARROS CENTRE #B1-05/06 SINGAPORE 737869
TEL: 63625226 / 62569633 FAX: 63626977



Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

PAYNOW UEN: 199307741M. PLEASE INDICATE THE INVOICE NUMBER.

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9838



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

VIN'S MOTOR PTE LTD
160 SIN MING DRIVE #08-09
SIN MING AUTOCITY
SECTOR B
SINGAPORE 575722
TEL : 64532121 VINCENT
ATTN : 4532121

TAX INVOICE : AR202301-00812
DATE : 03/01/2023
CUSTOMER ID : VIN002
VEH REG. NO. : SKS8450B
TERMS : 30 DAYS
PO NO. :
PAGE NO. : Page 3 of 6
CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
15.	GD7A-50-EA1 ALL MODEL	F.BUMPER/GRILLE CLIPS	U1 MZ-C3-C1	8	2.00	16.00 ✓
16.	BHN1-50-033B50 MZ3 BM	PANEL RADIATOR GRILLE	U1 MZ-B40	1	280.00	280.00 ✓
17.	S51S-51-833 ALL NEW MODEL	CLIP F BUMPER TOP (RIVET)	U1 MZ-C2-C6	6	2.00	12.00
18.	BHN1-50-1C0B MZ3 BM 2.0	F.SUPPORT PANEL SEAL PLATE CTR	U1 MZ-A105	1	40.00	40.00 ✓
19.	B45A-50-070A MZ3 BM 2014-	F.REINFORCEMENT	U1 BM-A16	1	380.00	380.00 ✓
20.	B45A-53-150A MZ3 BM 2014-	PANEL SUPPORT TOP PANEL	U1 MZ-B64	1	80.00	80.00 ✓
21.	BHN1-50-1U1A MZ3 BM 2014-	F.SUPPORT PANEL SEAL PLATE RH	U1 MZ-A66-D	1	20.00	20.00 ✓

CONTINUE NEXT PAGE

[P] 04/01/2023 10:32:31

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).



日美汽車私人有限公司

JAE AUTO PTE LTD

BLK 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
60 JALAN LAM HUAT CARROS CENTRE #B1-05/06 SINGAPORE 737869
TEL: 63625226 / 62569633 FAX: 63626977



Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

PAYNOW UEN: 199307741M. PLEASE INDICATE THE INVOICE NUMBER.



Dept Direct: 6417 9791 / 6745 9639



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795



Dept Direct: 6417 9796



Dept Direct: 6417 9793

Arrange by

LIT/VER

TOYOTA
GENUINE PARTS

LEXUS

DAIHATSU

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

VIN'S MOTOR PTE LTD
160 SIN MING DRIVE #08-09
SIN MING AUTOCITY
SECTOR B
SINGAPORE 575722
TEL : 64532121 VINCENT
ATTN : 4532121

TAX INVOICE : AR202301-00812
DATE : 03/01/2023
CUSTOMER ID : VIN002
VEH REG. NO. : SKS8450B
TERMS : 30 DAYS
PO NO. :
PAGE NO. : Page 4 of 6
CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
22.	B45A-52-111B MZ3 BM 2014-	F FENDER RH	U1 MZ-B61	1	220.00	220.00 ✓
23.	B45A-56-130H MZ3 BM 2014-	F FEND SHIELD RH	U1 MZ-A73-SD	1	80.00	80.00 ✓
24.	B4ZA-52-1R0 MZ3 BM 1.5	STAY F FENDER FRT RH	U1 MZ-B59-D	1	30.00	30.00 ✓
25.	B45A-56-114B MZ3 BM 14-	SHIELD F FENDER RH	U1 MZ-A55-SD	1	20.00	20.00 ✓
26.	B45A-56-146A MZ3 BM /MZ2 DJ HB	F BUMPER/ FENDER INNER SHIELD CLIPS	U1 MZ-A23-L	10	2.00	20.00 ✓
27.	BHT6-51-031A MZ3 BM 1.5	FH LAMP RH (HTD)	U1 MZ-A5	1	2400.00	2,400.00 ✓
28.	BHN3-51-0H3(KD53) CX5/CX9 /MZ3 BM	HID UNIT 2	U1 MZ-C4-A	1	850.00	850.00 ✓

CONTINUE NEXT PAGE

[P] 04/01/2023 10:32:31

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

1



日美汽車私人有限公司

JAE AUTO PTE LTD

BLK 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

80 JALAN LAM HUAT CARROS CENTRE #B1-05/06 SINGAPORE 737869
TEL: 63625226 / 62569633 FAX: 63626977



Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

PAYNOW UEN: 199307741M. PLEASE INDICATE THE INVOICE NUMBER.

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9630



Dept Direct: 6305 9610



Dept Direct: 6417 9794



Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

VIN'S MOTOR PTE LTD
160 SIN MING DRIVE #08-09
SIN MING AUTOCITY
SECTOR B
SINGAPORE 575722
TEL : 64532121 VINCENT
ATTN : 4532121

TAX INVOICE : AR202301-00812
DATE : 03/01/2023
CUSTOMER ID : VIN002
VEH REG. NO. : SKS8450B
TERMS : 30 DAYS
PO NO. :
PAGE NO. : Page 5 of 6
CURR. : SGD

SQ	STOCKID	DESCRIPTION	SikLee	QTY	U/PRICE	AMOUNT
29.	C514-51-0A1A MZ3 BM 2014-	COVER.H/LAMP 2	U1 MZ-A23-G	1	20.00	20.00 ✓
30.	9070-39-350 MZ3 BM 2.0L	BLUB 12V35 D4S	U1 MZ-C2-B1	1	450.00	450.00 ✓
31.	GHP9-67-481A MZ3 ONLY BM LUXURY 1.5	TANK F WIPER W/O MOTOR	U1 MZ-A42-SD	1	80.00	80.00 ✓
32.	EG22-67-482 MZ3 BL/BM 1 MOTOR 14-	MOTOR.F WIPER TANK	U1 MZ-C3-C5	1	50.00	50.00 ✓
33.	BHT4-51-8G162 MZ3 BM 1.5	NOZZLE.CLEANER F BUMP RH(RED)	U1 MZ-A23-F	1	60.00	60.00 ✓
34.	BHT4-51-82X MZ3 BM 1.5	MOTOR.F BUMP RH	U1 MZ-C3-D6	1	200.00	200.00 ✓
35.	BHT4-51-4J0 MZ3 BM 2014-	PIPE	U1 MZ-A48-A	1	90.00	90.00 ✓

CONTINUE NEXT PAGE

[P] 04/01/2023 10:32:31

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).



日美汽車私人有限公司

JAE AUTO PTE LTD

BLK 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
60 JALAN LAM HUAT CARROS CENTRE #B1-05/06 SINGAPORE 737869
TEL: 63625226 / 62569633 FAX: 63626977

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

PAYNOW UEN : 199307741M. PLEASE INDICATE THE INVOICE NUMBER.



WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9930



Dept Direct: 6305 9910

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

VIN'S MOTOR PTE LTD
160 SIN MING DRIVE #08-09
SIN MING AUTOCITY
SECTOR B
SINGAPORE 575722
TEL : 64532121 VINCENT
ATTN : 4532121

TAX INVOICE : AR202301-00812
DATE : 03/01/2023
CUSTOMER ID : VIN002
VEH REG. NO. : SKS8450B
TERMS : 30 DAYS
PO NO. :
PAGE NO. : Page 6 of 6
CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
36	B45A-51-350A MZ3 BM 2014-	LAMP FRT TURN RH	U1 MZ-A52	1	110.00	110.00✓
37	TK21-51-680A BM/DJ/MZ6 GJ/CX5	F FOG LAMP RH	U1 MZ-A38	1	260.00	260.00✓
38	BJF7-63-900 BM42 MZ3 13"4D/5D	FRT W/S GLASS W/MLD? W/SENSOR	U1	1	750.00	750.00✓
39	GHR5-53-110B MZ 3/6 GJ-GL BM BN	SUPPORT PANEL	SUPPLIER U1 MZ-A94	1	320.00	320.00✓
40	C274-50-133 MZ3 BM/ MX5 ND	F BUMPER NUT, CLIP 8	U1 MZ-A23-M	10	2.00	20.00✓
41	TK21-50-355 MZ3 BM/ CX3 DK	RIVET,RAD.GRILLE 4	U1 MZ-C3-D8	4	3.50	14.00

SUB-TOTAL : 8,562.00
ADD GST 8.00 % 684.96

E & OE

TOTAL AMOUNT SGD : 9,246.96

[P] 04/01/2023 10:32:31

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : JOO

This is computer generated document.

No signature is required



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date