

Name & Address:

UNITED OVERSEAS INSURANCE LTD
3 ANSON ROAD
#28-01 SPRINGLEAF TOWER
SINGAPORE 079909

Vehicle No:

SKS8450B

Date:

9-Dec-22

Brand & Model:

MAZDA 3

Franchise:

Mazda

Email/Fax No:

Contact No:

Chassis/VIN No:

JM6BM42A8G0309944

Contact Person (Eurokars)/Wip No:

SHAWN / 54213

Type of Claim:

Policy No:

Date Of Registration:

12/05/2015

Contact No (Eurokars):

6331 0680

OWN DAMAGE

PARTS / MATERIAL CHARGES

MARK = Survey Marking [Key "A" if item is approved]

NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	FRONT BUMPER <i>de/</i>	MBHR3-50-031BBB	1		-	\$ 994.32
2	RETAINER RH FRONT <i>ca/</i>	MBHN1-50-0T1F	1		-	\$ 15.77
3	RETAINER LH FRONT <i>X</i>	MBHN1-50-0U1E	1		-	\$ 15.77
4	BRACEKT RH BUMPER <i>?</i>	MBHN1-50-152	1		-	\$ 13.91
5	COVER FOG LAMP RH <i>ms/</i>	MBJE1-50-C11A	1		-	\$ 51.50
6	CHROME COVER FOG LAMP RH <i>ms/</i>	MBJE1-50-C12	1		-	\$ 119.35
7	STIFF'A', BUMPER <i>?</i>	MBHN1-50-0S0B	1		-	\$ 94.57
8	COVER BUMPER (TRIANGLE) <i>?</i>	MBHN1-50-101	1		-	\$ 30.77
9	GROMMET, SCREW <i>m/</i>	MGHP9-50-0Z5	2		-	\$ 4.72
10	NUT, CLIP <i>m/</i>	MC274-50-133	12		-	\$ 28.32
11	FASTENER <i>m/</i>	MB45A-56-146A	2		-	\$ 4.72
12	FRONT GRILLE RADIATOR <i>ca/</i>	MBJE1-50-712B	1		-	\$ 656.34
13	CHROME MOULD FRONT RH <i>X</i>	MBHN1-50-7J1A	1		-	\$ 198.92
14	BRACEKT RH FRONT GRILLE <i>X</i>	MBHN1-50-153	1		-	\$ 13.91
15	BRACKET LH FRONT GRILLE <i>X</i>	MBHN1-50-163	1		-	\$ 13.91
16	PIN, LOCATOR <i>BS?</i>	MKD45-50-1K5A	2		-	\$ 4.72
17	GROMMET <i>m/</i>	MKD45-50-ES1	2		-	\$ 4.72
18	FASTENER <i>m/</i>	MEA01-50-037	2		-	\$ 14.68
19	BRACEKT TOP FRONT GRILLE RADIATOR <i>?</i>	MBHN1-50-717D	1		-	\$ 126.69
20	FASTENER <i>m/</i>	MGD7A-50-EA1	8		-	\$ 20.96
21	FRONT GRILLE RADIDATOR TOP <i>X</i>	MBHN1-50-033 13	1		-	\$ 377.94
22	FASTENER <i>m/</i>	MS515-51-833	6		-	\$ 18.72
23	RIVET <i>m/</i>	MTK21-50-355	4		-	\$ 29.68
24	PLATE SET FRONT REINFORCEMENT <i>?</i>	MBHN3-50-1C0	1		-	\$ 84.80
25	FASTENER <i>?</i>	MGD7A-50-EA1	4		-	\$ 10.48
26	FRONT REINFORCEMENT <i>?</i>	MB45A-50-070A	1		-	\$ 576.77
27	UPPER SUPPORT PANEL FRONT <i>X</i>	MB45A-53-150A	1		-	\$ 133.26
28	PLATE SEAL RH FRONT SUPPORT PANEL <i>?</i>	MBHN1-50-1U1A	1		-	\$ 39.37
29	FASTENER <i>m/</i>	MKD45-50-EA1	4		-	\$ 9.44
30	FRONT FENDER RH <i>lm/</i>	MB45A-52-111B	1		-	\$ 348.10
31	STAY FENDER RH <i>b+</i>	MB4ZA-52-1R0A	1		-	\$ 58.58
32	MUD GUARD RH FRONT <i>de/</i>	MB45A-56-130H	1		-	\$ 121.80

33	SPLASH SHIELD RH FRONT ?	MB45A-56-114B	1	-	\$ 27.06
34	FASTENER m/	MB45A-56-146A	10	-	\$ 23.60
35	HEADLAMP RH bno/	MBHT6-51-031A	1	-	\$ 2,975.04
36	H I D CONTROL UNIT HEADLAMP ?	MBHN3-51-0H3	1	-	\$ 1,112.07
37	O R I N G H I D CONTROL UNIT ?	MC23G-51-0B2	1	-	\$ 12.98
38	COVER SOCKET HEADLAMP ?	MC514-51-0A1A	1	-	\$ 25.21
39	RIVET m/	MB092-51-833	1	-	\$ 2.95
40	BULB HEADLAMP ?	M9070-39-350	1	-	\$ 621.11
41	TANK WASHER de/	MGHP9-67-481A	1	-	\$ 117.50
42	GROMMET, WASHER TANK m/	MKD35-67-491	1	-	\$ 5.57
43	GROMMET, WASHER TANK m/	MG22C-67-491	1	-	\$ 6.49
44	PUMP WASHER TANK ?	MEG22-67-482	1	-	\$ 72.57
45	NOZZLE WASHER HEADLAMP RH mis/	MBHT4-51-82X	1	-	\$ 301.16
46	CLAMP m/	MTK33-51-829	1	-	\$ 14.84
47	COVER NOZZLE WASHER HEADLAMP RH mis/	MBHT4-51-8G1 62	1	-	\$ 105.87
48	PIPE NOZZLE WASHER HEADLAMP ?	MBHT4-51-4J0	1	-	\$ 170.43
49	LAMP SIGNAL TURN FRONT RH bno/	MB45A-51-350A	1	-	\$ 185.52
50	BRACEKT FOG LAMP RH ?	MBHR1-51-684A	1	-	\$ 15.77
51	FOG LAMP RH ?	MTK21-51-680A	1	-	\$ 377.94
52	FRONT WINDSCREEN ?	MBJF7-63-900	1	-	\$ 1,170.90
53	TAPE ?	MBHR1-50-898	1	-	\$ 7.42
54	SHEET, RAIN SENSOR ?	MC513-66-5G2	1	-	\$ 33.21
55	FRONT SUPPORT PANEL ?	MGHR4-53-110B	1	-	\$ 479.34
56	IU STICKER ?	M11-ERPBRK-	1	-	\$ 8.00
57					\$ -

Sub-Total (Parts Price) \$ - \$ 12,110.06

LABOUR / SERVICES CHARGES

NO	DESCRIPTION	REVISED	PRICE
1	TO REPLACE FRONT BUMPER . FRONT SUPPORT PANEL AND FRONT FENDER RH.	1650	\$ 2,100.00
2	TO RESPRAY FRONT BUMPER , FRONT GRILLE RADIATOR TOP , FRONT FENDER RH , BONNET AND FRONT DOOR RH.	2520	\$ 3,380.00
3	TO TRANSFER / REPLACE FRONT SENSOR.	330	\$ 660.00
4	TO REPLACE FRONT WINDSCREEN AND CONDUCT WATER TEST LEAK	NETT	\$ 560.00
5	TO SUPPLY SEALANT ON THE FRONT WINDSCREEN. ?	NETT	\$? 120.00
6	TO SUPPLY SOLAR FILM FRONT WINDSCREEN. ?	NETT	\$? 280.00
7	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
8	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	250	\$ 300.00
9	SUNDRIES.	20	\$ 50.00

Survey Date & Time:	Repair Days:	Excess:
---------------------	--------------	---------

Surveyor Remarks:

Sub-Total (Labour Price) \$ - \$ 7,620.00

	REVISED	PRICE
Parts Price	\$ -	\$ 12,110.06
Labour Price	\$ -	\$ 7,620.00
Total (Initial Estimate)	\$ -	\$ 19,730.06

REPAIR ESTIMATE

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- A fee of \$400 (excl. GST) will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

Supp 1	\$	-	\$	-
Supp 2	\$	-	\$	-
Supp 3	\$	-	\$	-
Total (Before Excess)	\$	-	\$	19,730.06
Less Excess	\$	-	\$	-
TOTAL (After Excess)	\$	-	\$	19,730.06
GST 7%	\$	-	\$	1,381.10
GRAND TOTAL	\$	-	\$	21,111.16

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasm

Hp 90010068

5 days

P/P

09/12/22 @ 1610

EXCESS: TBA

Revert

Resurvey before part.