

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012330/KWP3Q2**Date:** 12/01/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00182972205
Claimant Vehicle No :	GBF3503R	Insured Vehicle No :	SDW1725S
Date of Loss:	07/12/2022	Nature of Claim: TP	Claim No: SNM22D208832/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF3503R		
Make & Model:	NISSAN NV350, 2.5 5MT 5DR EURO V (A)	Engine No:	YD25390691A
Reg. Date:	14/09/2016 (Man. Year: 2015)	Chassis No:	JN1MC2E26Z0006132
Colour:	Blue	Odometer:	153764 km
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8
Front Left Side:	DURATURN 8 mm	Rear Left Side:	DURATURN 8 mm
Front Right Side:	DURATURN 8 mm	Rear Right Side:	DURATURN 8 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,373.50	3,046.50	3,327.00	52.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,350.00	1,430.00	920.00	39.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,723.50	4,476.50	4,247.00	48.68
Approved Total (Overridden) (S\$)		3,550.00		
(S\$)	8,723.50	3,550.00	5,173.50	59.31
+ GST 8.00/8.00% (S\$)	697.88	284.00	413.88	59.31
Nett Amount (S\$)	9,421.38	3,834.00	5,587.38	59.31

INSPECTION

Date of Assignment:	11/12/2022	
Date Inspected:	14/12/2022	Inspected At: 566 Woodlands Road (Mandai Estate) S 728697
Estimated Period of Repair:	4.0 days	Repairer:Connect3 (HQ)

Adjuster: KENNETH KONG**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 12 Jan 2023)	
Parts:	N/A	NISSAN NV350 2.5 5MT 5DR EURO V (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF3503R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	3,698.70 F	*2,101.00 FL
2	1		*REAR BUMPER	Bent	1,248.40 F	*687.00 FL
3	1		*REAR BUMPER CENTER PLASTIC GARNISH	Not Necessary	236.70 F	*- FL
4	1		*TAILGATE RUBBER	Serviceable	214.90 F	*- FL
5	1		*TAILGATE CENTRE EMBLEM	Not Necessary	42.80 F	*- FL
6	1		*REAR BUMPER CLIPS	Necessary	20.00 F	*20.00 FL
7	1		*70KM/H STICKER	Necessary	15.00 F	*15.00 FL
8	1		*EMERGENCY DOOR STICKER	Not Necessary	15.00 F	*- FL
9	1		*REAR NISSAN NV 350 EMBLEM	Necessary	89.00 F	*89.00 FL
10	1		*REAR NISSAN SMALL EMBLEM	Necessary	73.00 F	*73.00 FL
11	1		*COMPANY LOGO STICKER	Necessary	300.00 FS	*120.00 FS
12	1		*SEALANT (3 PCS)	Necessary	120.00 FS	*40.00 FS
13	1		*REVERSE SENSOR	Scratched	300.00 FS	*200.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					6,373.50	3,345.00
- List Item Discount on L Items 0.00/10.00% (\$\$)					0.00	298.50
Total Parts (\$\$)					6,373.50	3,046.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	APPLY ANTI RUST	New	120.00	30.00
2	CHECK WIRING	New	60.00	20.00
3	TRANSFER TAILGATE FITTINGS	New	150.00	60.00
4	LABOUR TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
5	LABOUR CHARGES	New	1,000.00	600.00
6	SPRAY PAINTING	New	900.00	600.00
Gross Labour Cost (S\$)			2,350.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >