

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Cecilia Lee

Date: 12 Jan 2023

**Preliminary Advice**

Insured Vehicle No	: SDW1725S	Accident Date	: 07/12/2022
TP Vehicle No	: GBF3503R	Assignment Date	: 11/12/2022
Make	: NISSAN NV350	Est. Duration of Repair	: 4
Date of Inspection	: 14/12/2022		
Inspection At	: 7 OLD TOH TUCK ROAD SINGAPORE 597648 REPAIRER:CONNECT3 (HQ)		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,723.50
Revised Amount	:S\$	4,476.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,476.50
 Lump Sum Repair	 :S\$	 3,550.00

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : The above survey was conducted on a 'Without Prejudice' basis.  
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.