

Not Authorized
11 Rm @ 3550/-
Paying After Paying
4 days

CONNECT 3
566 Woodlands Road (Mandai Estate) Singapore 728697
Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

Roc: 53360061L
GST: 53360061L

QT22/GBF3503R/TPC

China Taiping Insurance (Singapore) Pte Ltd
3 Anson Rd #15-02
Springleaf Tower
Singapore 079909

Dear Sir,

QUOTATION

Cost of Repair to Vehicle GBF3503R

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (\$S)	AMOUNT (\$S)
1.	Tailgate <i>2101.00</i>	1	<i>By</i> 3,698.70	3,698.70
2.	Rear bumper <i>687</i>	1	<i>By</i> 1,248.40	1,248.40
3.	Rear bumper center plastic garnish	1	<i>nn</i> 236.70	236.70
4.	Tailgate rubber	1	<i>h</i> 214.90	214.90
5.	Tailgate centre emblem	1	<i>nn n</i> 42.80	42.80
6.	Rear bumper clips	1	<i>nn</i> 20.00	20.00
7.	70KM/H sticker	1	<i>nn</i> 15.00	15.00
8.	Emergency door sticker	1	<i>nn</i> 15.00	15.00
9.	Rear Nissan NV350 emblem	1	<i>nn</i> 89.00	89.00
10.	Rear Nissan small emblem	1	<i>nn</i> 73.00	73.00
11.	Apply anti rust <i>105</i>	1	120.00	120.00
12.	Company logo sticker	1	<i>nn</i> 300.00	300.00
13.	Check wiring	1	60.00	60.00
14.	Sealant	3	<i>nn</i> 40.00	120.00
15.	Transfer tailgate fittings	1	150.00	150.00
16.	Labour to remove & refit rear windscreen	1	120.00	120.00


* Reverse sensor - \$300 (SIN) per 2000/-

17.	Labour charges	1	1,000.00	1,000.00	8001
18.	Spray painting	1	900.00	900.00	6001
SUB-TOTAL				SS8,423.50	

- Price before 7% gst

Thank you.

Yours faithfully,


Winnie Chai
HP: 9850-9666



LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: