

GREEN FOREST AUTOMOBILE PTE LTD

8 KAKI BUKIT AVE 4 #05-25 PREMIER @ KB SINGAPORE 415875

Sunnybay Transport Pte Ltd
8 KAKI BUKIT AVE 4
05-25 PREMIER @ KB
Singapore 415875

09th DECEMBER 2022

Accident date: 07th December 2022
Estimated repair cost for vehicle no: PC9341B TOYOTA HIACE

S/n	Qty	Items	U/price	Amount	
1	1	Rear boot lid		\$2,500.00	bt - 2245
2	1	Rear boot lid HIACE logo		\$55.00	nei
3	1	Rear boot lid Emble logo		\$75.00	nei
4	1	Rear boot lid 60Km/h logo		\$20.00	nei
5	1	Rear boot lid body logo /sticker		\$550.00	250SN
6	1	boot lid wheel chair sticker		\$35.00	nei SN
7	1	Rear boot lid center moulding		\$258.00	x nu
8	1	Rear boot lid inner lock		\$385.20	bt - 332.70
9	1	Rear boot lid inner trim board		\$550.00	dl - 450
10	10	Rear boot lid inner clips	\$12.90	\$129.00	30 nei SN
11	1	Rear boot lid inner rubber		\$255.20	cut
12	2	Rear boot lid number plate lamp	\$83.20	\$166.40	x 7
13	1	Rear boot lid number plate		\$50.00	x 5 nu
14	1	boot lid windscreen rubber		\$285.10	nei - 185
15	1	windscreen seal		\$255.00	nei - 155
16	2	Rear tail lamp	\$425.00	\$850.00	LH x nu, RH cre - 425
17	2	Rear tail lamp lower panel	\$252.20	\$504.40	LH x nu, RH cre
18	2	Rear tail lamp lower panel bracket	\$131.75	\$263.50	x nu
19	2	tail lamp lower cover	\$121.20	\$242.40	LH x RH de - 121.20
20	2	tail lamp inner panel	\$855.00	\$1,710.00	Rv
21	1	Rear bumper		\$755.00	de - 490
22	2	Rear bumper side bracket	\$125.00	\$250.00	x nu
23	1	rear bumper side retainer	\$185.00	\$185.00	de - 110
24	1	Rear bumper reverse sensor- set		\$450.00	200 nu SN
25	6	Rear bumper clips	\$12.90	\$77.40	30 nei SN
26	1	Rear air filter		\$188.00	x nu
27	1	rear speaker assy		\$855.00	x nu
28	1	Rear end panel		\$925.20	bt - 542
29	1	end panel top garnish		\$315.20	x nu
30	1	Rear spare tire bracket		\$358.20	x nu
31	1	Rear step panel		\$322.00	x nu

Subtotal :- \$13,820.20

5461.10
25% - 4095.83
SN 545

Labour charges	
To remove & re-fix rear windscreen	\$120.00 ✓
Gum	\$50.00 400
to remove & re-fix rear speaker	\$120.00 X ⁿⁿ
To remove & re-fix rear reverse sensor	\$120.00 30
To remove & re-fix rear exhaust	\$180.00 X ⁿⁿ
To remove & re-fix rear cushion	\$120.00 60
To check wiring system	\$60.00 30
Panel beating	\$1,000.00 700
Spray painting	\$1,000.00 700
Subtotal :-	<u>\$2,770.00</u>
Total:-	<u>\$16,590.20</u> 1680

Tanfim 97415749
 'WP' 9/12/22 @ 530pm 4095.83
 c/s Perry after report 545
 Tanfich @ 1khantowin 1680
 v. 6 days 6320.83
 c/s \$5050
 26 days
 #

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: