

The Motor Claims Department
M/s Lonpac Insurance Bhd
300 Beach Road, #17-04/07
The Concourse
Singapore 199555

Not Notified
L1 Pump &
Pressure Air Paint
Today



File No : SH/2022/323/12/007/OD
Date : 09-December-2022

Estimated cost of repair for vehicle no : SDA9899L Mercedes E250
Policy no: Z22VP05030835 Accident Date: 30.11.2022

Description	Quantity	Cost Price
Front bumper	1	\$ <i>TA</i> 1,050.00 ✓
Front bumper lower grille	1	\$ <i>CM</i> 120.00 ✓
LH Front bumper side cover	1	\$ <i>MT</i> 65.00 ✓
LH Front bumper side lamp	1	\$ 360.00 ?
Front bumper centre sponge	1	\$ <i>CM</i> 70.00 ✓
RH Front bumper sponge	1	\$ <i>R</i> 70.00 X
LH Front bumper sponge	1	\$ <i>MT</i> 70.00 ✓
Front bumper lower air guide	1	\$ <i>CM</i> 120.00 ✓
LH Front bumper spray jet	1	\$ <i>MT</i> 150.00 ✓
LH Front bumper spray jet bracket	1	\$ <i>MT</i> 25.00 ✓
LH Front bumper spray jet cover	1	\$ <i>MT</i> 55.00 ✓
RH Front bumper spray jet bracket	1	\$ 25.00 ?
RH Front bumper spray jet cover	1	\$ <i>MT</i> 55.00 ✓
Front bumper lower reinforcement	1	\$ <i>R</i> 130.00 X
Front bumper reinforcement	1	\$ <i>R</i> 380.00 X
LH Front bumper reinforcement bracket	1	\$ 250.00 ?
LH Front bumper reinforcement side bracket	1	\$ 55.00 ?
LH Front bumper reinforcement bracket	1	\$ 190.00 ?
LH Front bumper reinforcement bracket	1	\$ 30.00 ?
LH Front bumper spacer	1	\$ <i>R</i> 20.00 ✓
RH Front bumper spacer	1	\$ 20.00 ?
LH Front bumper centre sensor	1	\$ <i>MT</i> 190.00 ✓ ?
LH Front bumper inner sensor	1	\$ <i>MT</i> 190.00 ✓
LH Front bumper outer sensor	1	\$ <i>MT</i> 190.00 ✓
Front sensor wiring harness	1	\$ 480.00 ?
Bonnet	1	\$ <i>R</i> 1,400.00 X
Bonnet seal	1	\$ <i>R</i> 25.00 X
LH bonnet actuator sensor	1	\$ 350.00 ?
Front grille	1	\$ <i>CM</i> 750.00 ✓
Front centre top panel	1	\$ 280.00 ?
LH front side top panel	1	\$ 190.00 ?
LH front side panel bracket	1	\$ 45.00 ?
RH headlamp		\$ 1,950.00 ?
LH headlamp	1	\$ <i>BR</i> 1,950.00 ✓
LH headlamp cover	1	\$ <i>MT</i> 85.00 ✓
Wiper tank	1	\$ <i>R</i> 135.00 X

LH horn	1	\$	145.00	✓
RH front fender	1	\$	750.00	✓
LH front fender	1	\$	750.00	✓
LH front fender reinforcement	1	\$	25.00	✓
LH front fender cowling	1	\$	160.00	✓
LH front fender cowling clips (1 set)	1	\$	18.00	✓
LH front fender emblem	1	\$	60.00	✓
LH front fender lower moulding	1	\$	35.00	✓
RH front fender emblem	1	\$	65.00	✓
RH front fender lower moulding	1	\$	35.00	✓
		\$	13,563.00	
		Add 15%	\$	2,034.45
		\$	15,597.45	

To remove and check air con condenser, dryer, aluminium pipes, valves and reinstall components and vacuum and charge refrigerant R134a and check for leakage and full functionality

\$ 120.00 ¹⁰⁰¹

To remove front damaged parts, to jack out front support panel, front body, and cut out damaged parts, to straighten out front chassis, to reweld, reshape and repair bonnet hinge panel, front fender and inner panel, head lamp inner panel, front support panel, front chassis member, to replace damaged parts and adjust body panel alignment

\$ 950.00 ⁶⁰⁰¹

To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality

\$ 50.00 ²⁰¹

To spray paint affected front and inner damaged portion inclusive of preparatory works and material

\$ 850.00 ⁸⁰⁰¹

To perform computer diagnostic on drivetrain, ABS systems, parking system, headlamp systems, and clear fault codes

\$ 150.00 ⁷

\$ 17,717.45

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: