



The Motor Claims Department
M/s Lonpac Insurance Bhd
300 Beach Road, #17-04/07
The Concourse
Singapore 199555

File No : SH/2022/323/12/007/OD
Date : 12-December-2022

Supplementary estimated cost of repair for vehicle no: SDA9899L Mercedes E250
Policy No: Z22VP05030835 Accident Date: 30.11.2022

Description	Quantity	Cost Price
Front top air guid		\$ <i>mjm</i> 90.00 ✓
Front bumper left side retainer panel		\$ <i>cm</i> 80.00 ✓
		\$ 170.00
	Add 15%	\$ 25.50
		\$ 195.50