

ASS. REC. BY:

REF:

LPL / 22012335 / kv

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No. 22/22/22/VP05/026651

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$113K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

6/32

Person Contacted:

Vehicle: IN / OUT

Veh No:

SOA 98992

Yr Regn:

08, 12

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mer A 2250

c.c.

1796

Colour

M. Brown

A/C:

Insured / Std / NI / NA

Sp. Reading

105647

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

W002120472A 618240

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/R/m / STD A/R/m or

Tyre Size:

F:

245/40R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

mm

D.O.A.

30/11/22

D.O.I.

9/12/2022

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

FR N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

31/123

T/Rp @ 8200k Cahr

(red 9712.95, 54%)

Date/Time, File Pass to?



: Prel. Report



: Final Report

1)

Date/Time, File Return to?

2) 4/1/23-typist

Report Format : OD

Lump Sum / L.B. (\$) 8200

Days Of Repair: 7

Resurvey No. of Trip: 2

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Survey Fee:

Transportation:

) S - RS. SI

) Parking

) Others

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	353I
Vehicle Details	
Vehicle No.:	SDA9899L
Vehicle to be Exported:	Yes
Intended Deregistration Date:	01 Dec 2022
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E 250
Primary Colour:	Brown
Manufacturing Year:	2012
Engine No.:	27186030467089
Chassis No.:	WDD2120472A618240
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$54,005.00
Original Registration Date:	29 Aug 2012
First Registration Date:	29 Aug 2012
Transfer Count:	1
Actual ARF Paid:	\$54,005.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jun 2032
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$95,025.00
COE Rebate Amount:	\$91,039.00
Total Rebate Amount:	\$91,039.00

The information contained herein is correct as at 01 Dec 2022

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	01/12/2022 13:31 (SGT)
Reported by	Driver
Date of Accident	30/11/2022 15:45 (SGT)
Exact Location of Accident	Upper Thomson Rd, Singapore
Additional Location Information	Upper Thomson Road towards Sembawang Road
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDA9899L
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	Ng Swee Kuan
NRIC No	SXXXX353I
Email Address	chin_chungc@hotmail.com
Mobile Phone No	(Phone) +65-84849021
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	E250
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1800

INSURANCE COMPANY

Name of Insurance Company	Lonpac Insurance Bhd
Policy Number / Cover Note Number	Z22VP05030835

DRIVER

Name of Driver	Chong Chin Chung
NRIC No	SXXXX232H
Date Of Birth	01/01/1955
Occupation	Indoor

Date Of Driving Pass	11/03/1983
Driving experience	39 YEARS AND 8 MONTHS
Gender	Male
Mobile Number	(Phone) +65-98354795
Alt. Phone Number	-
Email Address	chin_chungc@hotmail.com
Address	319 Choa Chu Kang Ave 3 #03-20
Address complement	-
Postcode	689863
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Spouse
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Major/Minor Rd
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

refer attached report.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMR907K
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	Zheng Lixia
NRIC No	SXXXX570J

Contact Number	(Phone) +65-94513086
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

Describe Circumstance of the Accident

Refer attached statement.

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC40 card)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan

The sketch plan is drawn on a grid. At the top, there are labels: 'Driver' with an arrow pointing right, 'Passenger' with an arrow pointing left, 'Temple' in the center, and 'CBR' on the right. Below these, there are two horizontal lines representing a road. On the left side of the road, there is a label 'A' with an arrow pointing right. On the right side of the road, there is a label 'B' with an arrow pointing left. To the right of the road, there are two handwritten notes: 'A - 52A 9899L' and 'B - 5MR 907A'.

SKETCH PLAN

SKETCH PLAN #3

I was driving straight on 3rd lane along Upper Thomson Road near OCBC Building heading towards Sembawang Road, it was a 4-lane road. The traffic light was green and all vehicles were moving slowly & I also followed suit, suddenly I felt a great impact from my car's front left side. Vehicle B who drove from opposite direction just cut across into my direction while I was moving straight. Vehicle B did not check to see clear traffic but dashed across the road when it tried to turn into the slip road from the other side of Upper Thomson Road. As a result my car's front left portion was damaged, fortunately no one was injured and we have exchanged particulars for claim and repair purpose.

J. Hoins

Not Authorized
 61 Rmp @ 8200/h
 Recovery After Paint



The Motor Claims Department
 M/s Lonpac Insurance Bhd
 300 Beach Road, #17-04/07
 The Concourse
 Singapore 199555

File No : SH/2022/323/12/007/OD
 Date : 09-December-2022

Today,

Estimated cost of repair for vehicle no : SDA9899L Mercedes E250
 Policy no: Z22VP05030835 Accident Date: 30.11.2022

Description	Quantity	Cost Price
Front bumper	1	\$ Ta 1,050.00 ✓
Front bumper lower grille	1	\$ CM 120.00 ✓
LH Front bumper side cover	1	\$ m1 65.00 ✓
LH Front bumper side lamp	1	\$ m1/cm 360.00 ✓
Front bumper centre sponge	1	\$ CM 70.00 ✓
RH Front bumper sponge	1	\$ B 70.00 ✓
LH Front bumper sponge	1	\$ m1 70.00 ✓
Front bumper lower air guide	1	\$ CM 120.00 ✓
LH Front bumper spray jet	1	\$ m1 150.00 ✓
LH Front bumper spray jet bracket	1	\$ m1 25.00 ✓
LH Front bumper spray jet cover	1	\$ m1 55.00 ✓
RH Front bumper spray jet bracket	1	\$ m1 25.00 ✓
RH Front bumper spray jet cover	1	\$ m1 55.00 ✓
Front bumper lower reinforcement	1	\$ R 130.00 X
Front bumper reinforcement	1	\$ R 380.00 X
LH Front bumper reinforcement bracket	1	\$ CM 250.00 ✓
LH Front bumper reinforcement side bracket	1	\$ R 55.00 ✓
LH Front bumper reinforcement bracket	1	\$ R 190.00 X
LH Front bumper reinforcement bracket	1	\$ CM 30.00 ✓
LH Front bumper spacer	1	\$ R 20.00 ✓
RH Front bumper spacer	1	\$ R 20.00 X
LH Front bumper centre sensor	1	\$ R m1 190.00 ✓ X
LH Front bumper inner sensor	1	\$ m1 190.00 ✓
LH Front bumper outer sensor	1	\$ m1 190.00 ✓
Front sensor wiring harness	1	\$ CM 480.00 ✓
Bonnet	1	\$ R 1,400.00 X
Bonnet seal	1	\$ R 25.00 X
LH bonnet actuator sensor	1	\$ R 350.00 X
Front grille	1	\$ CM 750.00 ✓
Front centre top panel	1	\$ R 280.00 X
LH front side top panel	1	\$ R 190.00 ✓
LH front side panel bracket	1	\$ R 45.00 X
RH headlamp	1	\$ R 1,950.00 X
LH headlamp	1	\$ B 1,950.00 ✓
LH headlamp cover	1	\$ m1 85.00 ✓
Wiper tank	1	\$ R 135.00 X

LH horn	1	\$	<i>Sm</i> 145.00	<i>X</i>
RH front fender	1	\$	<i>R</i> 750.00	<i>X</i>
LH front fender	1	\$	<i>R</i> 750.00	<i>✓</i>
LH front fender reinforcement	1	\$	<i>R</i> 25.00	<i>X</i>
LH front fender cowling	1	\$	<i>Di</i> 160.00	<i>✓</i>
LH front fender cowling clips (1 set)	1	\$	<i>nn</i> 18.00	<i>✓</i>
LH front fender emblem	1	\$	<i>nn</i> 60.00	<i>✓</i>
LH front fender lower moulding	1	\$	<i>nn</i> 35.00	<i>✓</i>
RH front fender emblem	1	\$	<i>nn</i> 65.00	<i>X</i>
RH front fender lower moulding	1	\$	<i>Sm</i> 35.00	<i>X</i>
		\$	13,563.00	
Add 15%		\$	2,034.45	
		\$	15,597.45	

To remove and check air con condenser, dryer, aluminium pipes, valves and reinstall components and vacuum and charge refrigerant R134a and check for leakage and full functionality

\$ 120.00 *100*

To remove front damaged parts, to jack out front support panel, front body, and cut out damaged parts, to straighten out front chassis, to reweld, reshape and repair bonnet hinge panel, front fender and inner panel, head lamp inner panel, front support panel, front chassis member, to replace damaged parts and adjust body panel alignment

\$ 950.00 *600*

To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality

\$ 50.00 *200*

To spray paint affected front and inner damaged portion inclusive of preparatory works and material

\$ 850.00 *800*

To perform computer diagnostic on drivetrain, ABS systems, parking system, headlamp systems, and clear fault codes

\$ *nn* 150.00 *X*

\$ 17,717.45

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



The Motor Claims Department
M/s Lonpac Insurance Bhd
300 Beach Road, #17-04/07
The Concourse
Singapore 199555

File No : SH/2022/323/12/007/OD
Date : 12-December-2022

Supplementary estimated cost of repair for vehicle no: SDA9899L Mercedes E250
Policy No: Z22VP05030835 Accident Date: 30.11.2022

Description	Quantity	Cost Price
Front top air guid		\$ <i>m/cm</i> 90.00 ✓
Front bumper left side retainer panel		\$ <i>cm</i> 80.00 ✓
		\$ 170.00
	Add 15%	\$ 25.50
		\$ 195.50