



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: KHOR SAW THENG		Ref: CS3/ASM22012337/Dvp3e2 Date: 15/02/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 7874G	Veh. Inspected	SNB 1879Z
Policy No.	VFX/P2419138	Coverage (\$)	0.00
Claim No.	S2M04G5Q	Excess (\$)	0.00
Assign From	KHOR SAW THENG	Assign Date	08/12/2022
2. Vehicle Particulars & Condition			
Make & Model	HONDA ODYSSEY 2.4 EXV	c.c	2356
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JHMRC1890KC201120	Colour	BLACK
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/55 R17	DUNLOP	5 mm
L/H Front Tyre	215/55 R17	DUNLOP	5 mm
R/H Rear Tyre	215/55 R17	MICHELIN	5 mm
L/H Rear Tyre	215/55 R17	MICHELIN	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	06/12/2022	Inspection Date	12/12/2022
Survey held at	ANN JOO MOTOR PL BLK 176 SIN MING DRIVE #02-17 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	