



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/ALLIANZ
Policy No:	SP2002139009-01	Date of Loss:	03/12/2022
Vehicle Reg. No.:	SMN2559P	Driveable?	
Driver Age/Info:	69 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHAN ZHENG HAO		
Driver:	LEONG SOOK YING		
Make/Model:	HONDA CITY, 1.5 SV CVT (A)	Vehicle Reg. Date:	30/07/2019
Vehicle Colour:	BLUE		
Engine No:	L15Z16930711	Chassis No:	MRHGM6660LT000066
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		
Description of Accident/Loss	REFER TO GIA REPORT		
Remarks:	VEHICLE DRIVE INTO ANG MO KIO WORKSHOP ON 06/12/2022 EVENING		
Present Location:	CHENG HOE MOTOR PTE LTD (AMK)		

COST OF CLAIMS	Amount
Parts	5,095.20
Miscellaneous Items	70.00
Labour	2,270.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	7,435.20
- Excess (S\$)	1,100.00
(S\$)	6,335.20
+ GST 7.00% (S\$)	443.46
Nett Amount (S\$)	6,778.66

This claim is handled by: **DORLYN LI YAZHU**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Dec 2022)

Parts: 143 HONDA CITY 1.5 SV CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Cheng Hoe Motor Pte Ltd/SMN2559P/08/12/2022 10:11

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 pc front bumper ✓ DIS	0.00	0.00	*210.00 F
2	1		*1 pc front bumper reinforcement ?	0.00	0.00	*245.00 F
3	1		*2 pcs front bumper side retainers @ \$12/pc ?	0.00	0.00	*24.00 F
4	1		*1 pc front bumper RH fog lamp cover CUT	0.00	0.00	*18.00 F
5	1		*1 pc front bumper tow cover XNN	0.00	0.00	*12.00 F
6	1		*6 pcs front bumper clips @ \$2/pc NEC	0.00	0.00	*12.00 F
7	1		*1 pc front bumper lower centre grille ?	0.00	0.00	*60.00 F
8	1		*1 pc bonnet BUC	0.00	0.00	*320.00 F
9	1		*1 pc bonnet inner lock ?	0.00	0.00	*80.00 F
10	1		*2 pcs bonnet hinges @ \$34/pc XNN	0.00	0.00	*68.00 F
11	1		*2 pcs headlamps @ \$460/pc RH-CUT, LH-?	0.00	0.00	*920.00 F
12	1		*2 pcs headlamp lower brackets @ \$34/pc XNN	0.00	0.00	*68.00 F
13	1		*1 pc RH horn XNN	0.00	0.00	*40.00 F
14	1		*1 pc front grille housing CRA	0.00	0.00	*160.00 F
15	1		*1 pc front grille outer chrome CRA	0.00	0.00	*98.00 F
16	1		*1 pc front grille lower chrome CRA	0.00	0.00	*55.00 F
17	1		*1 pc front grille stay ?	0.00	0.00	*15.00 F
18	1		*1 pc front grille logo NEC	0.00	0.00	*18.00 F
19	1		*1 pc front grille inner top garnish ?	0.00	0.00	*25.00 F
20	1		*2 pcs frt fenders @ \$150/pc XR	0.00	0.00	*300.00 F
21	1		*1 pc frt RH fender inner shield ?	0.00	0.00	*35.00 F
22	1		*12 pcs frt fender inner shield clips @ \$3/pc ?	0.00	0.00	*36.00 F
23	1		*1 pc front support panel XR	0.00	0.00	*290.00 F
24	1		*1 pc air-con condenser ?	0.00	0.00	*390.00 F
25	1		*1 pc air-con outer temp sensor T-bracket (front) ?	0.00	0.00	*12.00 F
26	1		*1 pc front RH door BUC	0.00	0.00	*440.00 F
27	1		*1 pc front RH door checker XNN	0.00	0.00	*50.00 F
28	1		*1 pc front RH door lower hinge XNN	0.00	0.00	*36.00 F
29	1		*1 set front RH door frame sticker NEC	0.00	0.00	*15.00 F
30	1		*1 pc front RH door power window motor regulator XNN	0.00	0.00	*220.00 F
31	1		*1 pc frt RH rim 16 XNN	0.00	0.00	*360.00 F

F=Franchise part.

Sub Total (\$\$) 4,632.00
+ Margin on L,N Items 10.00% (\$\$) 463.20

Total Parts (\$\$) 5,095.20

Cheng Hoe Motor Pte Ltd/SMN2559P/08/12/2022 10:11. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	1 pc front number plate ^{BT}	35.00
2	1	1 unit coolant ^{X NN}	35.00
Sub Total (S\$)			70.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Remove & refix air-con condenser,check,vacuum & refill gas	New	100.00 X
2	Remove & refix front bumper & attachments,grille,headlamps,bonnet & attachments,both fenders,frt RH door & attachments;to cut,weld & renew frt support panel;knocking & repair frt chassis frames & realign the same	New	1,000.00 600
3	Putty & respray frt bumper,reinforcement,bonnet & attachments,both fenders,frt support panel,frt chassis frames,frt RH door & side mirror,RH rocker panel & all affected areas	New	1,000.00 800
4	Remove & refix frt RH door window glass & reset central locking	New	60.00 ✓
5	Remove & refix frt RH rim,tyre,balance & realign the same	New	50.00 X
6	To conduct computerised wheel alignment	New	60.00 X
Gross Labour Cost (S\$)			2,270.00

Cheng Hoe Motor Pte Ltd/SMN2559P/08/12/2022 10:11. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

L/S or P/P ?

6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: