

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012351/UQP3Q2**Date:** 23/12/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00038622201	
Claimant Vehicle No :	SLD8646X	Insured Vehicle No :	GBK3142Y	
Date of Loss:	17/08/2022	Nature of Claim:	TP	Claim No: SNM22D208815/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD8646X		Engine No:	P520369482
Make & Model:	MAZDA 3, 1.5 L (A)		Chassis No:	JM6BM42A8G0343497
Reg. Date:	29/06/2016 (Man. Year: 2016)		Odometer:	176057 km
Colour:	Red			
Engine Capacity:	1496 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,255.36	899.84	2,355.52	72.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,030.00	430.00	1,600.00	78.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,285.36	1,329.84	3,955.52	74.84
Approved Total (Overridden) (S\$)		1,050.00		
(S\$)	5,285.36	1,050.00	4,235.36	80.13
+ GST 7.00/7.00% (S\$)	369.98	73.50	296.48	80.13
Nett Amount (S\$)	5,655.34	1,123.50	4,531.84	80.13

INSPECTION

Date of Assignment:	08/12/2022		
Date Inspected:	09/12/2022	Inspected At:	ETHOZ Protect Pte Ltd (Tampines) 22 Tampines St 92 Singapore 528876
Estimated Period of Repair:	2.0 days		

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 23 Dec 2022)	
Parts:	N/A	MAZDA 3 1.5 L (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLD8646X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	1,074.80 FL	*1,074.80 FL
2	1		*REAR BUMPER REINFORCEMENT	Not Necessary	537.80 FL	*- FL
3	2		*REAR BUMPER RETAINER	Not Necessary	96.00 FL	*- FL
4	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
5	1		*END PANEL	Repair	505.10 FL	*- FL
6	1		*END PANEL TOP GARNISH	Not Necessary	85.10 FL	*- FL
7	1		*BOOT LID	Not Necessary	957.40 FL	*- FL
8	1		*BOOT LID LOCK	Not Necessary	153.00 FL	*- FL
9	1		*BOOT LID WEATHERSTRIP	Not Necessary	143.60 FL	*- FL
10	1		*REAR LOGO	Not Necessary	74.40 FL	*- FL
11	1		*EMBLEM -MAZDA 3	Not Necessary	53.40 FL	*- FL
12	1		*EMBLEM -SKYACTIV	Not Necessary	63.60 FL	*- FL
13	1		*REVERSE SENSOR	Serviceable	220.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,014.20	1,124.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	758.84	224.96
Total Parts (\$\$)	3,255.36	899.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO FACILITATE REPAIR	New	1,000.00	200.00
2	TO RESPRAY AFFECTED AREAS	New	1,000.00	200.00
3	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	30.00	30.00
Gross Labour Cost (S\$)			2,030.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >