

BHSANKV

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair Estimate

Vehicle number: SLM7228D

Make & Model: Mercedes Benz S300L

Chassis number: WDD2211542A146466

Date of survey:

Name of surveyor:

Contacts:

No.	Description of spare parts	Qty	Amount S\$
1	Bootlid	1	\$ 1,928.00
2	Bootlid "S300" emblem	1	\$ 93.00
3	Bootlid centre emblem	1	\$ 75.00
4	Bootlid "7G-Tronic" emblem	1	\$ 89.00
5	Bootlid chrome moulding	1	\$ 158.00
6	Bootlid weatherstrip	1	\$ 273.00
7	Bootlid lock	1	\$ 496.00
8	Bootlid lock garnish	1	\$ 59.00
9	Rear bumper	1	\$ 1,728.00
10	Rear bumper RH side retainer	1	\$ 56.00
11	Rear bumper RH side retainer rivets	1set	\$ 22.00
12	Rear bumper LH side retainer	1	\$ 56.00
13	Rear bumper LH side retainer rivets	1set	\$ 22.00
14	Rear bumper RH side reverse sensor	1	\$ 198.00
15	Rear bumper RH centre reverse sensor	1	\$ 198.00
16	Rear bumper LH centre reverse sensor	1	\$ 198.00
17	Rear bumper LH side reverse sensor	1	\$ 198.00
18	Rear bumper reverse sensor rubber seal	4	\$ 56.00
19	Rear bumper reverse sensor wire harness	1	\$ 277.00
20	Rear bumper reinforcement	1	\$ 721.00
21	Rear bumper reinforcement RH bracket	1	\$ 162.00
22	Rear bumper reinforcement LH bracket	1	\$ 162.00
23	Rear bumper inner garnish	1	\$ 204.00
24	Rear bumper lower cover	1	\$ 232.00
25	Rear bumper RH lower bracket	1	\$ 78.00
26	Rear bumper LH lower bracket	1	\$ 78.00
27	RH taillamp assy	1	\$ 802.00
28	RH taillamp panel	1	\$ 197.00
29	LH taillamp assy	1	\$ 802.00
30	LH taillamp panel	1	\$ 197.00
31	End panel	1	\$ 943.00
32	End panel inner garnish	1	\$ 214.00
33	Rear RH fender inner trim	1	\$ 466.00
34	Rear LH fender inner trim	1	\$ 466.00
35	RH exhaust chrome finisher	1	\$ 231.00
36	LH exhaust chrome finisher	1	\$ 231.00
37	Exhaust silencer	1	\$ 1,732.00
38	Exhaust silencer gasket	1	\$ 78.00

			\$ 14,176.00
		Parts less 10%	\$ 1,417.60
		Total	\$ 12,758.40

No.	Special Nett Items	Qty	Amount S\$
1	Bootlid "C&C" emblem	1	\$ 80.00
2	Bootlid inner trim clips	1set	\$ 80.00
3	Rear bumper clips	1set	\$ 80.00
4	RH taillamp panel joint sealant	1	\$ 50.00
5	LH taillamp panel joint sealant	1	\$ 50.00
6	End panel joint sealant	1	\$ 80.00
7	End panel inner garnish clips	1	\$ 60.00
8	Rear RH fender inner trim clips	1set	\$ 60.00
9	Rear LH fender inner trim clips	1set	\$ 60.00
		Total:	\$ 600.00

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 1,600.00
2	Spray painting on affected areas and panels	\$ 1,400.00
3	Check wiring and lighting system on affected areas	\$ 80.00
4	Apply rust coating chemical on affected areas and panels	\$ 80.00
5	Remove and replace bootlid inner mechanism to new bootlid	\$ 120.00
6	Remove and replace rear bumper reverse sensors to assist repair	\$ 100.00
7	Remove and replace rear inner trims, garnish and boards to assist repair	\$ 350.00
8	Remove and replace exhaust silencer, gaskets and chrome finishers to assist repair	\$ 220.00
		Total: \$ 3,950.00

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

Tan Kim 97495749
 WP 2/12/22 CSW
 4/5 Resing after repair
 Tan Kim @ lkhands.com
 06 days
 - To check consistency of accident
 - To check part prices

Spare Parts: \$ 12,758.40
 Special Nett: \$ 600.00
 Labour: \$ 3,950.00
Total Amount: \$ 17,308.40