



Your Ref : AVS22/3437

Date: 06th Jan 2023

Our Ref : CS/LIP22012359/Uqp3e2

M/s Liberty Insurance Pte Ltd

51 Club Street, #03-00

Liberty House

Singapore 069428

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SMM 4487E
INSURED VEHICLE: SNH 7580M
ACCIDENT ON 07/12/2022**

Instruction was received to inspect the vehicle Reg. No. SMM 4487E. The inspection was conducted on 09/12/2022 at the premises of M/s 15 Kaki Bukit Road #01-53, Singapore 417808, Repairer: Zoom Autowerks Pte Ltd

The following vehicle information was recorded:

Registration Number	: SMM 4487E
Make/Model	: Volkswagen Touran 1.6 TDI AT 1T332Z HID FL
Registration Date	: 31 Aug 2015
Body Colour	: Blue
Chassis Number	: WVGZZZ1TZFW083853
Engine Capacity	: 1598 cc
Speedometer Reading	: 310377 km

The vehicle sustained damages at the front and rear portion. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 44,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 29,429.00
Nett Liability	<u>S\$ 14,571.00</u> =====

Vehicle Inspected By:



CHUA KANG SENG
Licensed Appraiser



K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.