

(03/1/13) wof  
ASS. REC. BY:

REF:

CC4/AIS 22012361/Rpa3

2077

### ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SNB 8813S

at Workshop m/s CYCLE & CARRIAGE

of 188, PANDORA LOOP

Insured:

AIS

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

193K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SNB 8813S

Yr Regn:

2020 / July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MERCEDES BENZ GLC 200

C.C

1991

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

52779

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WIN 2539802F 806552

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

235/60R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

16/11/22

D.O.I.

15/12/22

Survey held at

CYCLE & CARRIAGE (PL)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 126K

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) S + RS \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$





Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

# ESTIMATE FOR SNB8813S\*RA

ALLIANZ INSURANCE SINGAPORE PTE.  
LTD.  
MOTOR CLAIM DEPARTMENT  
79 ROBINSON ROAD  
#09-01  
SINGAPORE 068897  
67143369

## Vehicle & Document Information

WIP No 61036  
Reg No/Reg Date SNB8813S\*RA / 09/07/2020  
Date In/Mileage / 0  
Chassis No W1N2539802F8065526  
Engine No 26492030283820  
Make/Model MB/GLC 200  
Colour/Trim 028 890 Cavansite B/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
WA000001	Credit	15/12/2022/ 09:24		356 / Vincent Seah				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z REQUEST								
Customer Request								
M BPNSUN								
POLICY NO/ACC DATE :5128583072								
DRIVE IN/EXCESS : 17.11.2022 // TP CAR NO.:SNB8157C=ALLIANZ INS								
DATE IN/DATE SURVEY:15.12.2022 //								
DIRECT SETTLEMENT MEI KWAN- LKK								15.00
M BPNSUN								
SUNDRIES							0.10	380.00
A BPILAB								
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO								
IDENTIFICATION STANDARD. NETT								960 1200.00
A BPILAB								
PANEL BEAT TO REPAIR AFFECTED AREAS , REMOVE AND REPLACE WITH NEW								800 1200.00
BODY PANELS WITH REFINISH.								
A BPIRES								
RESPRAY ON REAR BUMPER AND ACCIDENT AFFECTED AREA					1.00	1002.77	00.00	1002.77
M REAR BUMPER					1.00	535.33	00.00	535.33
M REAR LOWER BUMPER					1.00	780.48	00.00	780.48
M REAR BUMPER CHROME					1.00	61.79	00.00	61.79
M COVER, TOWING EYE					6.00	195.43	00.00	1172.58
M DISTANCE SENSOR					6.00	7.10	00.00	42.60
M SPACER RING					1.00	190.21	00.00	190.21
M CTR BASIC MOUNTING FOR BUMPER					1.00	340.78	00.00	340.78
M COVER, REAR LOWER BUMPER					1.00	97.41	00.00	97.41
M LHR EXHAUST CHROME TRIM					1.00	98.26	00.00	98.26
M RIGHT EXHAUST CHROME RIM					1.00	71.62	00.00	71.62
M STIFFENER					1.00	1655.71	00.00	1655.71
M REAR END PANEL					1.00	850.57	00.00	850.57
M CROSSMEMBER, REAR					1.00			
LKK Auto Consultants hence notify								
the Repairer of the following:								
• To resurvey before/after spray painting								
• To display damaged part(s) during resurvey								
• Parts prices are subject to confirmation								
• Third party survey is on a "Without Prejudice" basis								
• No illegal modification(s) is allowed								
• Supplementary item(s) must be resurveyed and								
is subject to final approval from Insurance Company								
Acknowledged by Repairer								
Signature:								
Date:								

Confirmed & accepted by

Nett 9,695.11  
7% GST on 9695.11 678.66  
Total Payable 10,373.77

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg





Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

# ESTIMATE FOR SNB8813S\*RA

ALLIANZ INSURANCE SINGAPORE PTE.  
LTD.  
MOTOR CLAIM DEPARTMENT  
79 ROBINSON ROAD  
#09-01  
SINGAPORE 068897  
67143369

WIP No  
Reg No/Reg Date  
Date In/Mileage  
Chassis No  
Engine No  
Make/Model  
Colour/Trim

## Vehicle & Document Information

61036  
SNB8813S\*RA / 09/07/2020  
15/12/2022/ 52779  
W1N2539802F8065526  
26492030283820  
MB/GLC 200  
028 890 Cavansite B/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
WA000001	Credit	03/02/2023/ 15:07		356 / Vincent Seah				
Description of Goods / Services								

### Z REQUEST

Customer Request

M-BPNSUN  
POLICY NO/ACC DATE : 5128583072 // 16.11.2022  
DRIVE IN/EXCESS : 17.11.2022 // TP CAR NO.: SNB8157C=ALLIANZ INS  
DATE IN/DATE SURVEY: 15.12.2022 // 15.12.2022 rasul-lkk 15:00pm  
DIRECT SETTLEMENT MEI KWAN- LKK  
X LEFT EXHAUST COVER, BUMPER AREA *ca*  
X CLAMP *an*  
X LH/REAR BUMPER BOTTOM HOLDER *de*  
X RH/REAR BUMPER BOTTOM HOLDER *de*

1.00	109.79	00.00	109.79
6.00	7.45	00.00	44.70
1.00	45.30	00.00	45.30
1.00	66.53	00.00	66.53

SUPPLEMENTARY

Confirmed & accepted by

8% GST on	Nett	266.32	266.32
			21.31
	Total Payable		287.63

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG