

ASS. REC. BY:

REF:

CCG/CTI 22012362/Dpc³

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 10 8 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 3171J

Yr Regn: Oct 2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Tail / Prime Mover /

Truck / Trailer or

Make: Hyundai Ioniq

C.C. 1580

Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 395369

T/Radio: Insured / Std / NI / NA

Eng/No: G4LEKU400858

C/No: KMHG851GVLU187643

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: —

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal: S mm

R/Bal: S mm

L/Bal: S mm

L/Bal: S mm

D.O.A. 08/12/2022

D.O.I. 12/12/2022

*Survey held at Buprost Sin Mng

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front & Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

China Tipping YQ 7424D

14/3/23

Finalized H/S 15,500/- with 10 days of rep

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. \$

Photos

Others

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)

Report Format: _____

1 series, 3 copies & 1 P. to 1st

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 9-Dec-22

INSURANCE: China Topy

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHC 3171 J

Description	Qty	List Price	Amount
Radiator Grille NEW MODEL <i>crack / distal</i>	1	\$ 1,568.60	\$ 1,568.60
Flap Assy Active Air Upper, (LH/RH) <i>q/s HH n/s many crack</i>	2	\$ 824.60	\$ 1,649.20
Speaker Assy-VESS <i>many broken</i>	1	\$ 554.40	\$ 554.40
Front Number Plate garnish <i>aligned</i>	1	\$ 188.00	\$ 188.00
Front Bumper Cover <i>distal / many broken</i>	1	\$ 481.10	\$ 481.10
Front bumper top cover <i>HH</i>	1	\$ 476.30	\$ 476.30
Front Bumper Sponge <i>HH</i>	1	\$ 186.90	\$ 186.90
Front Bumper Reinforcement <i>Dente</i>	1	\$ 1,136.70	\$ 1,136.70
Front Bumper Reinforcement ABSORBER (LH/RH) <i>HH</i>	2	\$ 186.50	\$ 373.00
Front Bumper Moulding Centre Upper <i>distal</i>	1	\$ 368.50	\$ 368.50
Front Bumper Moulding <i>HH</i>	1	\$ 93.60	\$ 93.60
Front Bumper Lower Stiffner <i>HH</i>	1	\$ 285.10	\$ 285.10
Front bumper lower grille <i>HH</i>	1	\$ 365.30	\$ 365.30
front bumper lower grille moulding <i>HH</i>	1	\$ 127.60	\$ 127.60
Front Bumper Lip <i>HH</i>	1	\$ 35.10	\$ 35.10
Front Bumper Bracket Top (LH/RH) <i>HH</i>	2	\$ 35.00	\$ 70.00
Front Bumper Bracket (LH/RH) <i>HH</i>	2	\$ 28.00	\$ 56.00
Front Bumper Retainer Mounting (LH/RH) <i>HH</i>	2	\$ 65.30	\$ 130.60
Front Bumper Clips 10 pcs <i>HH</i>	1	\$ 25.00	\$ 25.00
Front Bumper Grille (LH/RH) <i>HH</i>	2	\$ 186.90	\$ 373.80
Front bumper air duct (LH/RH) <i>HH</i>	2	\$ 153.80	\$ 307.60
Day Light ,LH <i>many broken</i>	1	\$ 642.50	\$ 642.50
Day Light , RH <i>HH</i>	1	\$ 642.50	\$ 642.50
Headlamp Support Panel Assy <i>crack / BH</i>	1	\$ 1,139.30	\$ 1,139.30
Headlamp(LH/RH) <i>crack 2110-30 x 2</i>	2	\$ 3,987.30	\$ 7,974.60

4220-60

Horn Unit (LH/RH) <i>HH</i>	2	\$ 72.80	\$ 145.60	X
Radiator Inverter <i>money broken</i>	1	\$ 884.80	\$ 884.80	✓
Radiator <i>money broken</i>	1	\$ 710.50	\$ 710.50	✓
Radiator fan blower motor assy <i>HH</i>	1	\$ 1,459.60	\$ 1,459.60	X
Radiator Air Guard (LH/RH) <i>HH</i>	2	\$ 76.40	\$ 152.80	X
Radiator Air Guard, Upr (LH/RH) <i>HH</i>	2	\$ 127.50	\$ 255.00	X
Aircon Condenser <i>HH</i>	1	\$ 663.60	\$ 663.60	✓
Boot Lid <i>HH / Distal</i>	1	\$ 2,549.70	\$ 2,549.70	✓
Boot Lid Rubber <i>HH</i>	1	\$ 187.40	\$ 187.40	X
Boot Lid Hinge (LH/RH) <i>HH</i>	2	\$ 71.30	\$ 142.60	X
Boot Lid Absorber (LH/RH) <i>HH</i>	2	\$ 86.70	\$ 173.40	X
Boot Lid Lock Upper <i>Distal</i>	1	\$ 224.00	\$ 224.00	✓
Boot Lid 'H' Emblem <i>HH</i>	1	\$ 28.00	\$ 28.00	✓
Emblem-Hybrid <i>HH</i>	1	\$ 24.30	\$ 24.30	✓
Emblem-Ioniq <i>HH</i>	1	\$ 31.30	\$ 31.30	✓
Rear Spoiler <i>HH reg</i>	1	\$ 665.40	\$ 665.40	X
Third Brake Light <i>HH</i>	1	\$ 385.60	\$ 385.60	X
BOOT HANDLE <i>HH</i>	1	\$ 31.80	\$31.80	X
Boot Lid Lamp(LH/RH) <i>money code</i>	2	\$ 822.00	\$ 1,644.00	✓
Boot Lid Trimboard <i>HH</i>	1	\$ 259.70	\$ 259.70	X
Boot Lid Trimboard Clips (10pcs) <i>HH</i>	1	\$ 11.00	\$ 11.00	X
Boot Lid Trimboard, Centre <i>HH</i>	1	\$ 159.60	\$ 159.60	X
Boot Lid Trimboard SIDE (LH/RH) <i>HH</i>	2	\$ 92.50	\$ 185.00	X
Boot Lid Trimboard REAR <i>HH</i>	1	\$ 124.80	\$ 124.80	X
Boot Lid Glass, Lower <i>SHAWNEE</i>	1	\$ 584.90	\$ 584.90	✓
Boot Lid Glass Upper Moulding <i>HH</i>	1	\$ 186.30	\$ 186.30	X
Boot Lid Glass Lower Moulding <i>HH</i>	1	\$ 145.20	\$ 145.20	X
Rear Bumper <i>distal</i>	1	\$ 459.40	\$ 459.40	✓
Rear Bumper Reinforcement <i>code</i>	1	\$ 394.80	\$ 394.80	✓
Rear Bumper Reinforcement Bracket (LH/RH) <i>HH / Distal</i>	2	\$ 188.10	\$ 376.20	✓
Antenna Assy-SMARTK outer <i>money broken</i>	1	\$ 689.50	\$ 689.50	✓
Rear Bumper Centre Moulding Assy <i>distal</i>	1	\$ 451.25	\$ 451.25	✓
Rear Bumper Lower Centre Moulding Assy <i>HH</i>	1	\$ 155.00	\$ 155.00	X
Rear Bumper Stay <i>HH</i>	1	\$ 138.10	\$ 138.10	X

Rear Bumper Side retainer (LH/RH) <i>HH</i>	2	\$ 85.80	\$ 171.60
Rear Bumper Cover Clips <i>HCC</i>	1	\$ 22.00	\$ 22.00
Rear Bumper Under Centre <i>HH</i>	1	\$ 123.85	\$ 123.85
Rear Bumper Side Under(LH/RH) <i>HH</i>	2	\$ 123.10	\$ 246.20
Rear Bumper Reflector Lamp(LH/RH) <i>HH</i>	2	\$ 82.90	\$ 165.80
Rear Bumper Reserve Light (Parking Brake Light) <i>Soclet</i>	1	\$ 328.60	\$ 328.60
Licence Lamp <i>HH</i> <i>broken</i>	1	\$ 193.53	\$ 193.53
Tail Lamp(LH/RH) <i>HH</i>	2	\$ 935.40	\$ 1,870.80
Tail Lamp Quarter Panel(LH/RH) <i>HH</i>	2	\$ 208.90	\$ 417.80
Rear Panel <i>HH</i>	1	\$ 532.00	\$ 532.00
Rear Panel Garnish <i>HH</i>	1	\$ 346.80	\$ 346.80
SUB TOTAL			\$ 38,350.43
LESS 20%			\$ 7,670.09
DISCOUNTED TOTAL			\$ 30,680.34
Front Number Plate <i>SN</i>	1	\$ 25.00	\$ 25.00
Front No Plate Trim Cover <i>SN</i>	1	\$ 30.00	\$ 30.00
COOLANT <i>SN</i>	1	\$ 45.00	\$ 45.00
Reverse camera ASSY <i>SN</i>	1	\$ 983.20	\$ 983.20
Boot Lid Comfort Logo & Tel No. Sticker <i>HCC</i>	1	\$ 35.00	\$ 35.00
Rear No. Plate + Trim Cover <i>SN</i>	1	\$ 45.00	\$ 45.00
Rear Windscreen Sealant <i>HCC</i>	2	\$ 46.00	\$ 92.00
Rear Bumper Reverse Sensor <i>DM</i>	1	\$ 180.00	\$ 180.00
SUB TOTAL			\$ 1,435.20
Labour Charge			
Panel Beating	1	\$2,000.00	\$2,000.00
Spray Painting Charge	1	\$1,800.00	\$1,800.00
Wiring Charge	1	\$100.00	\$100.00
Tuff Kote	1	\$100.00	\$100.00
Towing Charge	1	\$80.00	\$80.00

21,403.05

17,122.44

3451

397.00

700/-

700/-

30/-

40/-

HH

Remove/Refix Rear Windscreen Glass	2	\$120.00	\$240.00
Remove/Refix Reverse Sensor	1	\$120.00	\$120.00
Remove/Refix Radiator	1	\$90.00	\$90.00
Remove/Refix Aircon & Refill Gas	1	\$130.00	\$130.00
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00
TOTAL LABOUR			\$5,210.00
ESTIMATE TOTAL			\$37,325.54

80/-
40/-
50/-
80/-
150/-

1870.00

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. Please send your book value request to: claims_ltr@bifrostauto.com


19,389.44

L/S 15,500/-

12/12/2022 0930h

Mr. Andrew

2/5m 10 8 days.



2Kk And

Check part prices.



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: