



Section A - Accident Details

Registration Number	SHB952Y
Case Reference Number	TAX/12/22/2026
Registration Date	1/12/2020
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	CHUA CHIT MENG
Type of Accident	Side Swipe
Accident Date and Time	9/12/2022 12:40 AM
Accident Reported Date and Time	9/12/2022 12:16 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24117107
Special Instruction to ARC, if any	TP/RIGHT PORTION/AIG - LKK
Prepared Date and Time	9/12/2022 2:28 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,352.00	\$400.00
Total Spray Cost	\$1,872.00	\$900.00
Total Spare Part Cost	\$7,727.95	\$1,587.23
Total Other Cost	\$1,000.00	\$60.00
TOTAL COST	\$11,951.95	\$2,947.23 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	10.0	5.0
Prepared / Adjusted By	Boon Chew Tay	GuoQiang (LKK) / AIG
ARC / Surveyor Sign Off Date	09/12/2022 4:21 PM	09/12/2022 4:08 PM
Signature		
Remarks	PART BY PART / BEFORE PAINT PHOTO ,FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR quoqiang (LKK) & Email :quoqiang@lkkauto.com HP:82880282	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2301-0259	Invoice Number	
Quotation Date	18.01.2023	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$1,352.00	\$400.00 ✓
Total Labour	\$1,352.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00 ✓
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00 ✓
TO RESPRAY RH REAR DOOR	\$378.00	\$200.00 ✓
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00 ✓
TO RESPRAY REAR BUMPER	\$378.00	\$200.00 ✓
TO RESPRAY RIM	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,872.00	\$900.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00 ✓
TO TRANSFER DOOR MECHANISM	\$240.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO REMOVE AND REFIX UNDERCARRIAGE	\$200.00	\$0.00
Total Other Costs	\$1,000.00	\$60.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47927	COVER, RR BUMPER ASSY	1.00	\$525.40	100.00	\$0.00	Replace	Repair
		52462-47130	PAD, RR BUMPER, RH & LH , 3	0.00	\$12.00	0.00	\$0.00	Replace	Not Given
		52462-47030	PAD, RR BUMPER, RH & LH , 2	0.00	\$4.30	0.00	\$0.00	Replace	Not Given
		52462-47020	PAD, RR BUMPER, RH & LH , 1	0.00	\$4.30	0.00	\$0.00	Replace	Not Given
		52461-47070	PAD, RR BUMPER, CTR	0.00	\$12.00	0.00	\$0.00	Replace	Not Given
		52191-47030	SEAL, RR BUMPER ARM, RH & LH	0.00	\$12.30	0.00	\$0.00	Replace	Not Given
		52599-68030	STOPPER, RR BUMPER, RH & LH	0.00	\$4.80	0.00	\$0.00	Replace	Not Given

R
X
X
X
X
X
X

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 18/01/2023

User ID : PohSuan

		52575-47060	RETAINER, RR BUMPER, RH	0.00	\$143.60	0.00	\$0.00	Replace	Not Given	X
		52591-47080	SEAL, RR BUMPER , RH	0.00	\$128.00	0.00	\$0.00	Replace	Not Given	X
		52161-16010	CLIPS PIECE, FRT & RR BUMPER	0.00	\$4.80	0.00	\$0.00	Replace	Not Given	X
		52453-47900	GUARD, RR BUMPER, LOWER	0.00	\$405.00	0.00	\$0.00	Replace	Not Given	X
		81910-47030	REAR BUMPER REFLECTOR ASSY, REFLEX, RH	0.00	\$42.20	0.00	\$0.00	Replace	Not Given	X
		58398-47050	COVER, REAR FLOOR UNDER, RH	0.00	\$189.20	0.00	\$0.00	Replace	Not Given	X
		81551-47481	LENS & BODY, REAR COMBINATION LAMP , RH	0.00	\$367.30	0.00	\$0.00	Replace	Not Given	X
		81580-47070	LAMP ASSY, REAR, RH	0.00	\$317.80	0.00	\$0.00	Replace	Not Given	X
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X
		89997-30100	ANTENNA, ELECTRICAL KEY	0.00	\$78.00	0.00	\$0.00	Replace	Not Given	X
		67001-47153	PANEL SUB-ASSY, FRONT DOOR RH	1.00	\$1,407.80	100.00	\$0.00	Replace	Repair	R
			STICKER STRIDES TAXI (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	√ NEC
		67003-47211	PANEL SUB-ASSY, REAR DOOR , RH	1.00	\$1,401.70	100.00	\$0.00	Replace	Repair	R
		75850-47910	MOULDING ASSY, BODY ROCKER PANEL , RH	1.00	\$649.10	100.00	\$0.00	Replace	Repair	R
		61601-47150	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$943.10	100.00	\$0.00	Replace	Repair	R
		65637-47060	LINER, REAR FENDER , RH	0.00	\$151.10	0.00	\$0.00	Replace	Not Given	X
		4261147450	WHEEL, DISC	1.00	\$2,036.30	25.00	\$1,527.23	Replace	Replace	√ CUT
		43550-47020	HUB & BEARING ASSY, RH & LH	0.00	\$722.10	0.00	\$0.00	Replace	Not Given	X
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
Total					\$9,928.94		\$1,587.23			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1,587.23
+ 400.00
+ 960.00
2,947.23

*All X = NN