



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP22012375/Kny3e2 Date: 26/04/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLF 6240K	Veh. Inspected	SJZ 7442G	
Policy No.		Coverage (\$)	0.00	
Claim No.	AVS22/3446	Excess (\$)	0.00	
Assign From	TED SEAH	Assign Date	09/12/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA CAMRY (A)	c.c	2362	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	MR053BK4007044149	Colour	METALLIC BLACK	
Odometer	216206 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	FARROAD	9 mm	
L/H Front Tyre	215/60 R16	FARROAD	9 mm	
R/H Rear Tyre	215/60 R16	YOKOHAMA	6 mm	
L/H Rear Tyre	215/60 R16	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/12/2022	Inspection Date	12/12/2022	
Survey held at	FULCO AUTOCARE PTE LTD 176 SIN MING DRIVE# 03-02 SIN MING AUTOCARE, SINGAPORE 575721			
5a. Remarks				
A)REGISTRATION DATE: 23 DEC 2010 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		