



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD

INV No. AC2207956

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV Date 27/12/2022
Reference CS/EQI22012380/Uvy3m4
Code EQI

PROFESSIONAL SERVICE FEE

Vehicle No. SMZ 5829C
Insured Veh. GX 5787X
Claim No. DM22HO02132/JT
Policy No. DMCPHQ22-000046
Accident Date 06/12/2022
Inspection Date 12/12/2022

Description	Total
Survey Inspection	230.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	230.00
GST (7%)	16.10
Grand Total	246.10

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

SML



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Ref: CS/EQI22012380/Uvy3m4 Date: 27/12/2022 Code: EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GX 5787X	Veh. Inspected	SMZ 5829C	
Policy No.	DMCPHQ22-000046	Coverage (\$)	0.00	
Claim No.	DM22HO02132/JT	Excess (\$)	0.00	
Assign From	NEO JIE SI	Assign Date	12/12/2022	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN SYLPHY (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	MNTBBAB17Z0037888	Colour	BLUE	
Odometer	7461 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R16	BRIDGESTONE	7 mm	
L/H Front Tyre	195/60 R16	BRIDGESTONE	7 mm	
R/H Rear Tyre	195/60 R16	BRIDGESTONE	7 mm	
L/H Rear Tyre	195/60 R16	BRIDGESTONE	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/12/2022	Inspection Date	12/12/2022	
Survey held at	AUTOLUTION INDUSTRIAL PTE LTD 19 UBI ROAD 4 SINGAPORE 408623			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMZ 5829C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	EMBLEM TRUNKLID SYLPHY (N)	NECESSARY	102.90	102.90
1	EMBLEM REAR NISSAN (N)	NECESSARY	54.50	54.50
1	LH REFLECTOR RR BUMPER (N)	CUT	66.90	66.90
4	GROMET LH RR COMB LAMP @SGD\$5.30 EACH (N)	NOT NECESSARY	21.20	-
2	CLIP LH RR COMB LAMP @ SGD\$5.80 EACH (N)	NOT NECESSARY	11.60	-
1	RR TRUNKLID LAMP (N)	NOT NECESSARY	164.00	-
1	LH RR COMB LAMP (N)	NOT NECESSARY	422.70	-
1	TRUNKLID CHROME CENTER FINISHER (N)	NOT NECESSARY	199.40	-
1	LOCK ASSY-TRUNK LID (N)	BENT	76.50	76.50
1	STRIKER-TRUNK L (N)	NOT NECESSARY	68.70	-
2	HINGE TRUNK LID @SGD\$44.20 EACH (N)	TO REPAIR SEE LABOUR	88.40	-
1	W/STRIP T/LID (N)	TWISTED	94.90	94.90
1	TRUNK LID (N)	BENT	722.80	722.80
1	LH RR BUMPER LOWER CLOSING PLATE (N)	BENT	35.40	35.40
1	LH RR FENDER (N)	TO REPAIR SEE LABOUR	1,541.00	-
1	REAR END PANEL (N)	BADLY DENTED	475.90	475.90
1	LH RR COMB LAMP (N)	CRACKED	375.00	375.00
1	LH TRUNKLID LAMP (N)	CRACKED	250.00	250.00
1	LH SIDE BRACKET RR BUMPER (N)	BENT	18.00	18.00
1	ENERGY ABSORBER RR BUMPER (N)	TORN	205.00	205.00
1	REAR BUMPER (N)	TORN	773.00	773.00
1	PLATE LUGGAGE REAR GARNISH (N) (ADDITIONAL)	TWISTED	106.00	106.00
	LESS 20% DISCOUNT		-1,174.76	-671.36
			4,699.04	2,685.44
<u>SPECIAL NETT ITEMS</u>				
8	NUT TRUNKLID LAMP @ SGD\$1.70 EACH (SN)	NOT NECESSARY	13.60	-
1	REAR W/SCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	SUNDRIES (SN)	NOT NECESSARY	50.00	-
1	REAR LICENCE PLATE (SN)	SCRATCHED	60.00	60.00

Report Ref No. CS/EQI22012380/Uvy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	LH RR FENDER GLASS (SN)	NOT NECESSARY	553.80	-
1	SENSOR-REVERSE (SN)	SHORTED	250.00	250.00
			1,007.40	310.00
	LABOUR			
	LABOR CHARGES TO REPAIR TRUNKFLOOR, TRENEW LH TAIL LAMP PANEL, LH RR FENDER, RR END PANEL & RR BMPER AND TRUNKLID. INCLUSIVE OF THE REPAIR OF HINGE TRUNK LID AND LH RR FENDER.		2,730.00	2,340.00
	CHARGES TO SPRAY PAINTING SAME.		1,950.00	1,250.00
	RENEW LH RR FENDER GLASS.	NOT NECESSARY	120.00	-
	RENEW LH RR FENDER GLASS SOLAR FILM.	NOT NECESSARY	140.00	-
	REMOVE AND INSTALL REAR WINDSCREEN GLASS.	NOT NECESSARY	180.00	-
	APPLY SEALANT TO RR END PANEL AND TRUNKLID @SGD\$100.00 EACH.		200.00	200.00
	REMOVE AND TRANSFER TRUNKLID MECHANISM.		120.00	80.00
	REMOVE AND INSTALL REVERSE CAMERA.		160.00	120.00
	RENEW REVERSE SENSOR.		110.00	110.00
	RENEW LH RR COMB LAMP R/INSTALL RH RR COMB LAMP BOTH HATCHBACK DOOR LAMP AND CHECK LIGHTING.		80.00	48.00
	TO REMOVE AND INSTALL BOTH INNER TRIM FENDER TO FACILITATE REAR END PANEL REPLACEMENT.		195.00	130.00
	TO REMOVE AND INSTALL REAR SEAT TO FACILITATE LH RR FENDER REPLACEMENT.	NOT NECESSARY	390.00	-
	CHECK AND INSPECT EXHAUST MUFFLER REPLACE IF DAMAGED.	NOT NECESSARY	180.00	-
	COMPUTER CHECK DIAGNOSIS.	NOT NECESSARY	180.00	-
	PERFORM WHEEL ALIGNMENT.	NOT NECESSARY	95.00	-
	PULL AND STRAIGHTENED REPAIR LEFT REAR CHASSIS.	NOT NECESSARY	350.00	-
	PERFROM RUSTPROOFING LH RR FENDER, LH RR TAIL LAMP PANEL AND REAR END PANEL.		360.00	120.00
			7,540.00	4,398.00
GRAND TOTAL			13,246.44	7,393.44

Report Ref No. CS/EQI22012380/Uvy3m4



RECOMMENDED COST OF REPAIRS			7,393.44
-----------------------------	--	--	-----------------

Report Ref No. CS/EQI22012380/Uvy3m4

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



Autolution Industrial Pte Ltd

Tan Chong Motor Sales Pte Ltd's Authorized Dealer
19 Ubi Road 4
Singapore 408623
Tel: (65) 64909666 / 67038650
Fax: (65) 68467483
Business Reg. No.: 199503871W

20/12/2022

INS/IC/EA/0482/22

EQ INSURANCE COMPANY LIMITED
5 MAXWELL ROAD
#17-00 TOWER BLOCK
S(069110)
Attn : Motor Claim Manager
Claim Dept

Dear Sir

SUPPLEMENTARY CLAIM

REGN. NO. : SMZ5829C
CLAIM NO: INS/IC/EA/0482/22


Further to our claim INS/IC/EA/0482/22 we are submitting a supplementary claim for the below mentioned part for the above mentioned case.

1	PARTS NEED TO CHANGE PLATE LUGGAGE REAR GARNISH	7w1	\$	106.00	NETT
---	--	-----	----	--------	------

We trust the above supplementary claim will meet with your kind approval and we will forward to you the final repair bill together with the satisfaction note on completion repairs.

Yours faithfully

AUTOLUTION INDUSTRIAL PTE LTD


ELMER ALFONSO
Insurance Claim Dept

Cc: SURVEYOR MARCUS

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 06/12/2022 12:15 (SGT)
Reported by Driver
Date of Accident 06/12/2022 09:30 (SGT)
Exact Location of Accident Singapore
Additional Location Information SLIP ROAD OF BEDOK NORTH RD
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMZ5829C

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner YEO AH LIM
NRIC No S0730838H
Email Address rongmomo@umpire.com
Mobile Phone No (Phone) +65-91432273
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Nissan
Model Sylphy
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1600

INSURANCE COMPANY

Name of Insurance Company AIG Asia Pacific Insurance Pte. Ltd.
Policy Number / Cover Note Number 7210041472

DRIVER

Name of Driver YEO MIN SI, GRACE (YANG MINSI, GRACE)
NRIC No S8213753Z
Date Of Birth 18/05/1982
Occupation Indoor

Date Of Driving Pass	04/12/2009
Driving experience	13 YEARS
Gender	Female
Mobile Number	(Phone) +65-91432273
Alt. Phone Number	-
Email Address	rongmomo@umpire.com
Address	APT BLK 312C SUMANG LINK
Address complement	#07-157
Postcode	823312
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Child
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	EDEN LIM
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

SEE ATTACHED SKETCH PLAN, PHOTO AND VIDEO FOOTAGE

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GX5787X
Vehicle Manufacturer	Toyota
Vehicle Model	-
Vehicle Variant	-

Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	YAZID
NRIC No	S7234869I
Contact Number	(Phone) +65-97868992
Address	-
Address complement	-
Postcode	-
Insurance Company Name	EQ Insurance Company Ltd
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

ROTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD #4
SINGAPORE 408423
TEL: 6490 9856 FAX: 6446 7483

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

Sketch Plan

A - SMZ5892C
B - GX5787X

Describe Circumstance of the Accident

I was checking for traffic at the slip road at Bedok North Jct. My car was in stationary position as I wait for traffic to pass when a vehicle bumped into my boot/back of my car.

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)



06/12/2022
12:03 pm

EVOLUTION INDUSTRIAL PTE LTD
5 UBI ROAD
SINGAPORE 408624
TEL: 6490 9698 FAX: 6496 7483



EMER AIFM50
GXXXXX2241L



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMZ 5829C

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMZ 5829C

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

