



FALCON-AIR

FALCON - AIR AUTO SERVICES PTE LTD
CO. REG. No.: 1995-01140-D

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2000729631	Date of Loss:	07/12/2022
Vehicle Reg. No.:	SJV1129Y	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	RAJESHKUMAR MADAWLAL SHARMA		
Driver:	SUNISHA RAJESHKUMAR SHARMA		
Make/Model:	HYUNDAI AVANTE, 1.6 (A)	Vehicle Reg. Date:	12/01/2010
Vehicle Colour:	SILVER	Chassis No:	KMH DU41BMAU933391
Engine No:	G4FC9U775761		
Odometer:	150000 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	FALCON-AIR AUTO SERVICES PTE LTD (TAMPINES)		

COST OF CLAIMS	Amount
Parts	599.50
Miscellaneous Items	0.00
Labour	1,000.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	1,599.50
+ GST 7.00% (S\$)	111.97
Nett Amount (S\$)	1,711.47

This claim is handled by: JOSHUA NG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 12 Dec 2022)

Parts: 143

HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: Falcon-Air Auto Services Pte Ltd/SJV1129Y/12/12/2022 09:17

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*N/S WING MIRROR <i>Down</i>	0.00	0.00	*285.00 F ✓
2	1		*N/S WING MIRROR GLASS <i>white</i>	0.00	0.00	*85.00 F ✓
3	1		*N/S WING MIRROR GLASS COVER <i>white</i>	0.00	0.00	*60.00 F ✓
4	1		*N/S WING MIRROR LAMP <i>white</i>	0.00	0.00	*85.00 F ✓
5	1		*N/S WING MIRROR EMBLEM <i>blue</i>	0.00	0.00	*30.00 F ✓
F=Franchise part.						
Sub Total (S\$)						545.00
+ Margin on L,N Items 10.00% (S\$)						54.50
Total Parts (S\$)						599.50

Falcon-Air Auto Services Pte Ltd/SJV1129Y/12/12/2022 09:17. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO CHECK WIRING	New	50.00 20/-
2	TO REPAIR INNER PANEL, ACCIDENT DAMAGE AREA, REPLACEMENT OF PARTS AND ALIGN THE SAME	New	350.00 300/-
3	TO PUTTY AND SPRAY PAINT ON ACCIDENT DAMAGE AREA	New	600.00 450/-
Gross Labour Cost (\$\$)			1,000.00

Falcon-Air Auto Services Pte Ltd/SJV1129Y/12/12/2022 09:17. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches : Tampines S(93 Blk 9006 #01-200 S(528340) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg

13/12/2022



2 days.

LKK Auto




Photo after sign
with damaged parts.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: