

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Richard Ang Wei Guang

Date: 27 Dec 2022

Preliminary Advice

| | | | |
|--------------------|--|-------------------------|--------------|
| Insured Vehicle No | : SMF2849U | Accident Date | : 08/12/2022 |
| TP Vehicle No | : SML6902R | Assignment Date | : 13/12/2022 |
| Make | : HONDA SHUTTLE HYBRID | Est. Duration of Repair | : 3 |
| Date of Inspection | : 12/12/2022 | | |
| Inspection At | : QUAN DE MOTOR TRADING BLK 1 KAKI BUKIT AVENUE 6 #01-67 AUTOBAY SINGAPORE 417883 SINGAPORE 417883 | | |

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| | | |
|-----------------------------|----------|--------------|
| Repairer's Estimate (Gross) | :S\$ | 6,971.36 |
| Revised Amount | :S\$ | 4,504.56 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 4,504.56 |
| Lump Sum Repair | :S\$ | 3,600.00 |

Total Loss Consideration

| | |
|--------------------|------|
| New for Old Value | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 (X) Lump Sum repair
- (X) The above survey was conducted on a 'without prejudice' basis. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.