



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188

Auto Consultants hence notify
Repairer of the following:
• To resurvey before/after spray painting
• To display damaged parts, during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: **ESTIMATE**
Date:



TOYOTA

*Not Allowed
for
EXCESS \$4200?
areas
Tel: 62563561
Tel: pho before repair.*

Account Details		Account No.	Customer Details	
Ergo Insurance Pte Ltd 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 Attn: Motor Claims Dept		S1000010 / ICN13	Mr Sathanantham Nagarajan 487 Yio Chu Kang Road #13-06 Singapore 787059 Mobile: 93891717	
		Document No. 0		
		Document Date 09/12/2022		

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	ASU60R	ANTGT P1	26/04/2019	SMZ7744A	0	22226	67/OD/SMZ7744A

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTEKB3GH80J004366	8ARZ154993	60	Sam San Joi	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES OD CLAIM POLICY NO.:DMPG22012433 ACC DATE:08/12/2022 TOW IN:09/12/2022 EXCESS:TBA DATE-IN:09/12/2022 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				30.00
2	B	BP-LAB2 DRILL HOLE & ININSTALL FRT SENSOR				- 198.00
3	B	BP-LAB2 CHECK LIGHTING & WIRING SYSTEM				- 134.64
4	B	BP-MECH2 TO CONDUCT ADJUSTMENT ON FRT WAVE RADAR SENSOR				- 198.00
5	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				- 198.00
6	S	BP-SUBLET REPLACE SPORT RIM AND CONDUCT WHEEL BALA NCING				- 99.00
7	B	BP-MECH2 REPLAACE RH FRT SUSPENSION SYSTEM				- 792.00
8	B	BP-MECH2 CONDUCT FULL WHEEL ALIGNMENT				- 198.00
9	B	BP-LAB2 REPLACE FRT RH ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN FRT RH ACCIDENT AFFECTED AREAS	792		1980	3168.00
10	B	BP-RES2 RESPRAY JOB ON FRT RH ACCIDENT AFFECTED AREAS	656		2296	3280.00
11	1	T52119-4D946 COVER, FR BUMPER	1.00	811.30		811.30

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details	
Ergo Insurance Pte Ltd 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 Attn: Motor Claims Dept		S1000010 / ICNI3	Mr Sathanantham Nagarajan	
		Document No. 0	487 Yio Chu Kang Road #13-06 Singapore 787059	
		Document Date 09/12/2022	Mobile: 93891717	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	ASU60R	ANTGT P1	26/04/2019	SMZ7744A	0	22226	67/OD/SMZ7744A
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTEKB3GH80J004366	8ARZ154993	60	Sam San Joi	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
12	2	T52536-48030 RETAINER, FR BUMPER <i>LH</i>	1.00	115.20	X	115.20 X
13	3	T52535-48040 RETAINER, FR BUMPER <i>RH</i>	1.00	115.20	X	115.20 X
14	4	L47749-50090 CLIP, PIN HOLD	2.00	2.10	X	4.20 X
15	5	L53879-30050 RETAINER, FR FENDER	2.00	17.00	X	34.00 X
16	6	T52611-48210 ABSORBER, FR BUMPER	1.00	54.40 53.90	X	54.40 53.90 X
17	7	T52537-48040 RETAINER, FR BUMPER	1.00	117.40	X	117.40 X
18	8	T52029-48010 REINFORCEMENT	1.00	301.10	X	301.10 X
19	9	T52618-48030 ABSORBER, FR BUMPER,	1.00	185.00	X	185.00 X
20	0	T52701-48010 MOULDING SUB-ASSY,	1.00	465.60	X	465.60 X
21	1	T52411-48050 GUARD, FR BUMPER	1.00	340.20	X	340.20 X
22	2	T48691-48040 DAMPER, SUSPENSION	1.00	1533.00	X	1533.00 X
23	3	S52161-0K040 PIECE, RR BUMPER	10.00	4.90	X	49.00 X
24	4	T53102-48081 GRILLE SUB-ASSY,	1.00	497.30	X	497.30 X
25	5	L90467-07220 CLIP	1.00	3.00	X	3.00 X
26	6	T53811-48210 PANEL, FR FENDER, RH	1.00	1446.30	X	1446.30 X
27	7	T53875-48120 LINER, FR FENDER, RH	1.00	522.50	X	522.50 X
28	8	T90467-07201 CLIP	10.00	4.30	X	43.00 X
29	9	T53827-48020 PROTECTOR, FR FENDER	1.00	109.30	X	109.30 X
30	0	T53410-48140 HINGE ASSY, HOOD, RH	1.00	87.10	X	87.10 X
31	1	T67001-48150 PANEL SUB-ASSY, FR <i>door</i>	1.00	2035.90	X	2035.90 X

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details	
Ergo Insurance Pte Ltd 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 Attn: Motor Claims Dept		S1000010 / ICNI3	Mr Sathanantham Nagarajan	
		Document No. 0	487 Yio Chu Kang Road #13-06 Singapore 787059	
		Document Date 09/12/2022	Mobile: 93891717	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	ASU60R	ANTGT P1	26/04/2019	SMZ7744A	0	22226	67/OD/SMZ7744A
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTEKB3GH80J004366	8ARZ154993	60	Sam San Joi	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
32	2	T81145-48E40 UNIT, HEADLAMP	1.00	7996.60		7996.60
33	3	T52133-48060 REINFORCEMENT, FR	1.00	69.80		69.80
34	4	T81116-48E30 BRACKET, HEADLAMP, A	1.00	36.10		36.10
35	5	T81107-47560 COMPUTER SUB-ASSY,	1.00	1342.50		1342.50
36	6	T81016-48E30 COMPUTER SUB-ASSY,	1.00	1294.80		1294.80
37	7	T81210-48051 LAMP ASSY, FOG	1.00	516.00		516.00
38	8	T81430-48010 LAMP ASSY, DAYTIME	1.00	966.30		966.30
39	9	T89348-58120 RETAINER, ULTRASONIC	2.00	18.50		37.00
40	0	T89341-58060 A0 SENSOR, ULTRASONIC,	2.00	481.90		963.80
41	1	T89348-58150 A0 RETAINER, ULTRASONIC	2.00	24.20		48.40
42	2	T89348-58130 CLIP, ULTRASONIC	1.00	143044.20		143044.20
43	3	T85315-42360 JAR, WASHER, A	1.00	173.20		173.20
44	4	T85316-48230 CAP, WASHER, A	1.00	93.00		93.00
45	5	T42611-48A10 WHEEL, DISC	1.00	2970.70		2970.70
46	6	T48510-80866 ABSORBER ASSY,	1.00	683.80		683.80
47	7	T48820-42030 LINK ASSY, FR	1.00	196.20		196.20
48	8	L48068-42060 ARM SUB-ASSY,	1.00	969.10		969.10
49	9	T43330-19275 JOINT ASSY, LWR BALL	1.00	314.60		314.60
50	0	L43211-78010 KNUCKLE, STEERING,	1.00	875.10		875.10
51	1	T43550-42020 HUB&BEARING ASSY,	1.00	794.30		794.30

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total	37,520.64
	Please acknowledge receipt of vehicle	Parts 29,225.00 Labour 8,196.64 Sublet 99.00 Lubrication/Fluid 0.00 Others 0.00	GST 7.00% Less	2,626.44 0.00
			Amount Due	40,147.08

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details		Account No.	Customer Details	
Ergo Insurance Pte Ltd 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 Attn: Motor Claims Dept		S1000010 / ICN13	Mr Sathanantham Nagarajan	
		Document No. 39013189	487 Yio Chu Kang Road #13-06 Singapore 787059	
		Document Date 30/12/2022	Mobile: 93891717	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	ASU60R	ANTGT P1	26/04/2019	SMZ7744A	47693	22226	67/OD/SMZ7744A

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTEKB3GH80J004366	8ARZ154993	60	Sam San Joi	09/12/2022 10.11	27/12/2022 15.05

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES OD CLAIM POLICY NO.:DMPG22012433 ACC DATE:08/12/2022 TOW IN:09/12/2022 EXCESS:\$3700 DATE-IN:09/12/2022 DATE SURVEY:12/12/2022 NO OF REPAIR DAYS:9 DAYS BY:MARCUS(LKK) AUTHORISED ON:19/12/2022				30.00
2	S	BP-SUBLET REPLACE SPORT RIM AND CONDUCT WHEEL BALANCING	0239			99.00
3	S	BP-SUBLET DRILL HOLE & INISTALL FRT SENSOR	0742			198.00
4	S	BP-SUBLET CHECK LIGHTING & WIRING SYSTEM	0742			134.64
5	S	BP-SUBLET TO CONDUCT ADJUSTMENT ON FRT WAVE RADAR SENSOR	0742			198.00
6	S	BP-SUBLET TO RESET ECU AND REPROGRAMME	0742			198.00
7	S	BP-SUBLET REPLACE RH FRT SUSPENSION SYSTEM	0742			792.00
8	S	BP-SUBLET CONDUCT FULL WHEEL ALIGNMENT	0742			198.00
9	S	BP-SUBLET REPLACE FRT RH ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN FRT RH ACCIDENT AFFECTED AREAS	0742			1980.00
10	S	BP-SUBLET RESPRAY JOB ON FRT RH ACCIDENT AFFECTED AREAS	0742			2296.00

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy



Borneo Motors

inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details		Account No.	Customer Details	
Ergo Insurance Pte Ltd 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 Attn: Motor Claims Dept		S1000010 / ICN13	Mr Sathanantham Nagarajan	
		Document No. 39013189	487 Yio Chu Kang Road #13-06 Singapore 787059	
		Document Date 30/12/2022	Mobile: 93891717	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	ASU60R	ANTGT P1	26/04/2019	SMZ7744A	47693	22226	67/OD/SMZ7744A

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTEKB3GH80J004366	8ARZ154993	60	Sam San Joi	09/12/2022 10.11	27/12/2022 15.05

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
11	V	EXC Excess element of insurance repair to be paid by the insured party	8888			-3700.00
12	1	T52119-4D946 COVER, FR BUMPER	1.00	811.30		811.30
13	2	T52535-48040 RETAINER, FR BUMPER	1.00	115.20		115.20
14	3	L47749-50090 CLIP, PIN HOLD	2.00	2.10		4.20
15	4	L53879-30050 RETAINER, FR FENDER	2.00	17.00		34.00
16	5	T52618-48030 ABSORBER, FR BUMPER,	1.00	185.00		185.00
17	6	T52701-48010 MOULDING SUB-ASSY,	1.00	465.60		465.60
18	7	T52411-48050 GUARD, FR BUMPER	1.00	340.20		340.20
19	8	S52161-0K040 PIECE, RR BUMPER	10.00	4.90		49.00
20	9	T53102-48081 GRILLE SUB-ASSY,	1.00	497.30		497.30
21	0	L90467-07220 CLIP	1.00	3.00		3.00
22	1	T53811-48210 PANEL, FR FENDER, RH	1.00	1446.30		1446.30
23	2	T53875-48120 LINER, FR FENDER, RH	1.00	522.50		522.50
24	3	T90467-07201 CLIP	10.00	4.30		43.00
25	4	T81145-48E40 UNIT, HEADLAMP	1.00	7996.60		7996.60
26	5	T81430-48010 LAMP ASSY, DAYTIME	1.00	966.30		966.30
27	6	T89348-58120 RETAINER, ULTRASONIC	2.00	18.50		37.00
28	7	T89341-58060 A0 SENSOR, ULTRASONIC,	1.00	481.90		481.90
29	8	T89348-58150 A0 RETAINER, ULTRASONIC	2.00	24.20		48.40

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due


Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details		Account No.	Customer Details	
Ergo Insurance Pte Ltd 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 Attn: Motor Claims Dept		S1000010 / ICN13	Mr Sathanantham Nagarajan	
		Document No. 39013189	487 Yio Chu Kang Road #13-06 Singapore 787059	
		Document Date 30/12/2022	Mobile: 93891717	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	ASU60R	ANTGT P1	26/04/2019	SMZ7744A	47693	22226	67/OD/SMZ7744A

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTEKB3GH80J004366	8ARZ154993	60	Sam San Joi	09/12/2022 10.11	27/12/2022 15.05

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
30	9	L89348-58130 CLIP, ULTRASONIC	1.00	14.30		14.30
31	0	T85315-42360 JAR, WASHER, A	1.00	173.20		173.20
32	1	T42611-48A10 WHEEL, DISC	1.00	2970.70		2970.70
33	2	T48510-80866 ABSORBER ASSY,	1.00	683.80		683.80
34	3	T48820-42030 LINK ASSY, FR	1.00	196.20		196.20
35	4	L48068-42060 ARM SUB-ASSY,	1.00	969.10		969.10
36	5	T43330-19275 JOINT ASSY, LWR BALL	1.00	314.60		314.60
37	6	L43211-78010 KNUCKLE, STEERING,	1.00	875.10		875.10
38	7	T43550-42020 HUB&BEARING ASSY,	1.00	794.30		794.30
39	8	T52611-48210 ABSORBER, FR BUMPER	1.00	54.40		54.40
40	9	T52537-48040 RETAINER, FR BUMPER	1.00	117.40		117.40

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			23,633.54
	Please acknowledge receipt of vehicle	Parts 21,209.90	GST 7.00% 1,654.35
		Labour 30.00	Less 0.00
		Sublet 6,093.64	
		Lubrication/Fluid 0.00	
		Others 0.00	Amount Due 25,287.89

Customer Copy

Customer

Vehicle ident no.

Repair order no.
R002030

Technician

194

Date/Time

19.12.22 13:06

License plate no.
SMZ7744A

First reg. date

Model
TOYOTA HARRIER (ASU60R)Odometer reading: km/miles
56138

Complaints or reason for alignment check

			Before	Target Data	Actual	
Rear axle	Camber	left	-1°30'	-1°15' +/-0°45'	-1°30'	
		right	-1°48'		-1°48'	
		cross	0°18'	0°00' +/-0°45'	0°17'	
	Toe	left	0°08'	0°05' +/-0°05'	0°09'	
		right	-0°03'		-0°03'	
		total	0°05'	0°10' +/-0°10'	0°05'	
	Geometrical driving axis			0°05'	0°00'	0°06'
Front axle	Camber	left	-0°39'	-0°10' +/-0°45'	-0°32'	
		right	-0°31'		-0°38'	
		cross	-0°09'	0°00' +/-0°45'	0°06'	
	Caster	left	5°34'	6°00' +/-0°45'	5°34'	
		right	5°49'		5°49'	
		cross	-0°15'	0°00' +/-0°45'	-0°15'	
	SAI	left	12°33'	11°35' +/-0°45'	12°26'	
		right	11°56'		12°03'	
		cross	0°37'	0°00'	0°23'	
	Track differential angle					
	Toe	left	1°21'	0°02' +/-0°05'	0°04'	
		right	1°13'		2°30'	
		total	2°33'	0°05' +/-0°10'	2°34'	
Setback				0°00'		
Max steering lock	left steer	left		-36°00' +/-2°00'		
		right		30°00' +/-2°00'		
	right steer	left		30°00' +/-2°00'		
		right		-36°00' +/-2°00'		

Customer

Vehicle ident no.

Repair order no.
R002036Technician
194Date/Time
21.12.22 14:22License plate no.
SMZ7744A

First reg. date

Model
TOYOTA HARRIER (ASU60R)Odometer reading: km/miles
56138

Complaints or reason for alignment check

			Before	Target Data	Actual	
Rear axle	Camber	left	-1°21'	-1°15' +/-0°45'	-1°21'	
		right	-1°55'		-1°53'	
		cross	0°33'	0°00' +/-0°45'	0°32'	
	Toe	left	-0°02'	0°05' +/-0°05'	0°06'	
		right	0°03'		0°05'	
		total	0°01'	0°10' +/-0°10'	0°10'	
Geometrical driving axis			-0°02'	0°00'	0°00'	
Front axle	Camber	left	-0°12'	-0°10' +/-0°45'	-0°05'	
		right	-0°18'		-0°25'	
		cross	0°06'	0°00' +/-0°45'	0°20'	
	Caster	left	5°25'	6°00' +/-0°45'	5°25'	
		right	5°40'		5°40'	
		cross	-0°15'	0°00' +/-0°45'	-0°15'	
	SAI	left	11°58'	11°35' +/-0°45'	11°51'	
		right	11°50'		11°57'	
		cross	0°07'	0°00'	-0°06'	
	Track differential angle		left			
			right			
	Toe	left	0°09'	0°02' +/-0°05'	0°03'	
right		0°12'	0°03'			
total		0°21'	0°05' +/-0°10'	0°06'		
Setback				0°00'		
Max steering lock	left steer	left		-36°00' +/-2°00'		
		right		30°00' +/-2°00'		
	right steer	left		30°00' +/-2°00'		
		right		-36°00' +/-2°00'		

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	09/12/2022 13:22 (SGT)
Reported by	Driver
Date of Accident	08/12/2022 22:30 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	UNDERPASS OF TPE TOWARDS SENKANG
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMZ7744A
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	SATHANANTHAM NAGARAJAN
NRIC No	SXXXX782B
Email Address	Naga@axissoft.com.sg
Mobile Phone No	(Phone) +65-93891717
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	HARRIER G GRADE
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1956

INSURANCE COMPANY

Name of Insurance Company	ERGO Insurance Pte. Ltd.
Policy Number / Cover Note Number	DMPG22012433

DRIVER

Name of Driver	RISHIKUMAR NAGARAJAN
NRIC No	TXXXX963H
Date Of Birth	05/12/2001
Occupation	Indoor

Date Of Driving Pass	05/05/2022
Driving experience	7 MONTHS
Gender	Male
Mobile Number	(Phone) +65-93891717
Alt. Phone Number	-
Email Address	naga@myasset.com.sg
Address	Castle Green, 487 Yio Chu Kang Road
Address complement	#13-06
Postcode	787059
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Child
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collided into Property
Weather Conditions	Raining
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	1
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

ON THE DATE AND TIME MENTIONED I WAS DRIVING ALONG THE SAID MENTIONED ROAD ON THE EXTREME RIGHT LANE WHEN I ACCIDENTALLY HIT THE WALL OF THE UNDERPASS. NO ONE WAS INJURED. STATEMENT WAS READ TO ME AND I ACKNOWLEDGED IT.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	-
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	NA / Unknown

Name of Driver -
Contact Number -
Address -
Address complement -
Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident UNDERPASS SIDE WALL
No. Of Passenger (Including Driver) -

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed By Reporting Officer
Hashim Bin Kamari


Witnessed by Reporting Centre
Personnel

Sketch Plan

REFER TO ATTACHED ACCIDENT DIAGRAM



ACCIDENT DIAGRAM



Policyholder's Signature / Date & Time

[Signature]

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed By Reporting Officer
Hashim Bin Kamari

Witnessed by Reporting Centre
Personnel

AJAX MARS PTE LTD

Describe Circumstances of the Accident

ON THE DATE AND TIME MENTIONED I WAS DRIVING ALONG THE SAID MENTIONED ROAD ON THE EXTREME RIGHT LANE WHEN I ACCIDENTALLY HIT THE WALL OF THE UNDERPASS. NO ONE WAS INJURED. STATEMENT WAS READ TO ME AND I ACKNOWLEDGED IT.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed By Reporting Officer
Hashim Bin Kamari

Witnessed by Reporting Centre Personnel

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	782B
Vehicle Details	
Vehicle No.:	SMZ7744A
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Dec 2022
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER G GRADE
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	8ARZ154993
Chassis No.:	JTEK83CH80J004366
Maximum Power Output:	170.0 kW (227 bhp)
Open Market Value:	\$33,306.00
Original Registration Date:	26 Apr 2019
First Registration Date:	26 Apr 2019
Transfer Count:	1
Actual ARF Paid:	\$38,629.00
Intended PARF Rebate Details	193.4
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Apr 2029
PARF Rebate Amount:	\$28,971.00
Intended COE Rebate Details	
COE Expiry Date:	25 Apr 2029
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$41,000.00
COE Rebate Amount:	\$25,096.00
Total Rebate Amount:	\$54,067.00

The information contained herein is correct as at 12 Dec 2022

OK

Singapore Reckless Drivers XIII


'This is the worst I have seen in 20 years': Quic...

Unusual or Rare Cars - Part 3

Post an Advertisement
Sell it yourself! Advertise it at just **\$68 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

Probably the only Manual Boxster registered in town.



Christmas Sale! Free iPad for cars purchased for a limited period only**
Purpose Automobiles StarAd



Sort by results/page

13 vehicles

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Harrier	Any	Any	2019	Any	Any	Any	Available
	Toyota Harrier Turbo 2.0A M	\$129,800	\$17,150 /yr	28-Jun-2019	1,998 cc	55,000 km	SUV	Available
Nice Bidded Number Plate Comes With It! Fully Agent Serviced By Borneo Motors! Low Genuine Mileage! Pristine Condition With Original... Posted: 10-Dec-2022								
	Toyota Harrier Turbo 2.0A M	\$131,800	\$17,300 /yr	19-Jul-2019	1,998 cc	45,000 km	SUV	Available
1 owner only! 100% accident free! Agent serviced since day 1! 5 years warranty coverage by Borneo Motors! Well taken care by careful... Posted: 10-Dec-2022								
	Toyota Harrier Turbo 2.0A M	\$124,800	\$17,680 /yr	04-Jan-2019	1,998 cc	81,002 km	SUV	Available
Sporty And Elegant Pearl White! 1 Owner, Agent Unit, Accident Free, Original Mint Condition, Flexible Financing Available, Trade In Welco... Posted: 09-Dec-2022								
	Toyota Harrier Turbo 2.0A G Panoramic Roof	\$135,800	\$17,500 /yr	02-Jul-2019	1,998 cc	58,188 km	SUV	Available
High Spec Model! High ARF \$42000, 5 years Borneo Motors agent warranty! Full agent serviced with records since day 1, Accident free! o... Posted: 09-Dec-2022								
	Toyota Harrier Turbo 2.0A M	\$123,800	\$17,400 /yr	18-Jan-2019	1,998 cc	58,590 km	SUV	Available
Immediate Transfer of Ownership Upon Collection. 1 Owner. Under 5 Years Manufacturer Warranty by Borneo Motor till Jan 2024. Elegan... Esteem Performance Pte Ltd Posted: 07-Dec-2022								
	Toyota Harrier Turbo 2.0A G Panoramic Roof	\$133,800	\$17,270 /yr	29-Jul-2019	1,998 cc	55,000 km	SUV	Available
1 owner, mileage only 55000km, upgraded audio system and apple carplay. 5 years Borneo Motors agent warranty! Fully agent serviced... Posted: 04-Dec-2022								
	Toyota Harrier Turbo 2.0A G	\$139,800	\$17,990 /yr	22-Aug-2019	1,998 cc	77,538 km	SUV	Available
Most Popular Toyota SUV For Your Family. Well Maintained And Service With Warranty From Agent Borneo Motors. Spacious And Reliable... Herly Enterprises Co Posted: 03-Dec-2022								
	Toyota Harrier Turbo 2.0A M	\$128,800	\$17,890 /yr	28-Feb-2019	1,998 cc	80,000 km	SUV	Available
1 owner! Agent unit with 5 years warranty and free servicing! 100% accident free unit! In house financing and high trade in given! Imm... Hui Hua Credit Pte Ltd Posted: 25-Nov-2022								

Compare