



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188

Auto Consultants hence notify

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

ESTIMATE

Date:



TOYOTA

Not Allowed
HUR
EXCESS \$4200?
nearby
Tel: 62563561
Tel: phb before party.

Account Details

Ergo Insurance Pte Ltd
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Attn: Motor Claims Dept

Account No.

S1000010 / ICN13

Document No.

0

Document Date

09/12/2022

Customer Details

Mr Sathanantham Nagarajan

487 Yio Chu Kang Road
#13-06
Singapore 787059

Mobile: 93891717

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	ASU60R	ANTGT P1	26/04/2019	SMZ7744A	0	22226	67/OD/SMZ7744A

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTEKB3GH80J004366	8ARZ154993	60	Sam San Joi	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES OD CLAIM POLICY NO.:DMPG22012433 ACC DATE:08/12/2022 TOW IN:09/12/2022 EXCESS:TBA DATE-IN:09/12/2022 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				30.00
2	B	BP-LAB2 DRILL HOLE & INISTALL FRT SENSOR				- 198.00
3	B	BP-LAB2 CHECK LIGHTING & WIRING SYSTEM				- 134.64
4	B	BP-MECH2 TO CONDUCT ADJUSTMENT ON FRT WAVE RADAR SENSOR				- 198.00
5	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				- 198.00
6	S	BP-SUBLET REPLACE SPORT RIM AND CONDUCT WHEEL BALA NCING				- 99.00
7	B	BP-MECH2 REPLAACE RH FRT SUSPENSION SYSTEM				- 792.00
8	B	BP-MECH2 CONDUCT FULL WHEEL ALIGNMENT				- 198.00
9	B	BP-LAB2 REPLACE FRT RH ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN FRT RH ACCIDENT AFFECTED AREAS	792 656		1980	3168.00
10	B	BP-RES2 RESPRAY JOB ON FRT RH ACCIDENT AFFECTED AREAS	656		2296	3280.00
11	1	T52119-4D946 COVER, FR BUMPER	1.00	811.30		811.30

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details					
Ergo Insurance Pte Ltd 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 Attn: Motor Claims Dept		S1000010 / ICN13	Mr Sathanantham Nagarajan 487 Yio Chu Kang Road #13-06 Singapore 787059 Mobile: 93891717					
		Document No. 0						
		Document Date 09/12/2022						
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	ASU60R	ANTGT P1	26/04/2019	SMZ7744A	0	22226	67/OD/SMZ7744A	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTEKB3GH80J004366		8ARZ154993	60	Sam San Joi	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
12	2	T52536-48030	RETAINER, FR BUMPER	217	1.00	115.20	X	115.20 X
13	3	T52535-48040	RETAINER, FR BUMPER	217	1.00	115.20	X	115.20 X
14	4	L47749-50090	CLIP, PIN HOLD	217	2.00	2.10	X	4.20 X
15	5	L53879-30050	RETAINER, FR FENDER	217	2.00	17.00	X	34.00 X
16	6	T52611-48210	ABSORBER, FR BUMPER	217	1.00	54.40	X	54.40 X
17	7	T52537-48040	RETAINER, FR BUMPER	217	1.00	117.40	X	117.40 X
18	8	T52029-48010	REINFORCEMENT	217	1.00	301.10	X	301.10 X
19	9	T52618-48030	ABSORBER, FR BUMPER,	217	1.00	185.00	X	185.00 X
20	0	T52701-48010	MOULDING SUB-ASSY,	217	1.00	465.60	X	465.60 X
21	1	T52411-48050	GUARD, FR BUMPER	217	1.00	340.20	X	340.20 X
22	2	T48691-48040	DAMPER, SUSPENSION	217	1.00	1533.00	X	1533.00 X
23	3	S52161-0K040	PIECE, RR BUMPER	217	10.00	4.90	X	49.00 X
24	4	T53102-48081	GRILLE SUB-ASSY,	217	1.00	497.30	X	497.30 X
25	5	L90467-07220	CLIP	217	1.00	3.00	X	3.00 X
26	6	T53811-48210	PANEL, FR FENDER, RH	217	1.00	1446.30	X	1446.30 X
27	7	T53875-48120	LINER, FR FENDER, RH	217	1.00	522.50	X	522.50 X
28	8	T90467-07201	CLIP	217	10.00	4.30	X	43.00 X
29	9	T53827-48020	PROTECTOR, FR FENDER	217	1.00	109.30	X	109.30 X
30	0	T53410-48140	HINGE ASSY, HOOD, RH	217	1.00	87.10	X	87.10 X
31	1	T67001-48150	PANEL SUB-ASSY, FR	217	1.00	2035.90	X	2035.90 X
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd								
		Please acknowledge receipt of vehicle		Parts		Less		
				Labour				
				Sublet				
				Lubrication/Fluid				
				Others		Amount Due		

Customer Copy



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
Ergo Insurance Pte Ltd 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 Attn: Motor Claims Dept	S1000010 / ICNI3	Mr Sathanantham Nagarajan 487 Yio Chu Kang Road #13-06 Singapore 787059 Mobile: 93891717
	Document No. 0	
	Document Date 09/12/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	ASU60R	ANTGT P1	26/04/2019	SMZ7744A	0	22226	67/OD/SMZ7744A
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTEKB3GH80J004366	8ARZ154993	60	Sam San Joi	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
32	2	T81145-48E40 UNIT, HEADLAMP	1.00	7996.60		7996.60
33	3	T52133-48060 REINFORCEMENT, FR	1.00	69.80		69.80
34	4	T81116-48E30 BRACKET, HEADLAMP, A	1.00	36.10		36.10
35	5	T81107-47560 COMPUTER SUB-ASSY,	1.00	1342.50		1342.50
36	6	T81016-48E30 COMPUTER SUB-ASSY,	1.00	1294.80		1294.80
37	7	T81210-48051 LAMP ASSY, FOG	1.00	516.00		516.00
38	8	T81430-48010 LAMP ASSY, DAYTIME	1.00	966.30		966.30
39	9	T89348-58120 RETAINER, ULTRASONIC	2.00	18.50		37.00
40	0	T89341-58060 A0 SENSOR, ULTRASONIC,	2.00	481.90		963.80
41	1	T89348-58150 A0 RETAINER, ULTRASONIC	2.00	24.20		48.40
42	2	T89348-58130 CLIP, ULTRASONIC	1.00	1430.44		1430.44
43	3	T85315-42360 JAR, WASHER, A	1.00	173.20		173.20
44	4	T85316-48230 CAP, WASHER, A	1.00	93.00		93.00
45	5	T42611-48A10 WHEEL, DISC	1.00	2970.70		2970.70
46	6	T48510-80866 ABSORBER ASSY,	1.00	683.80		683.80
47	7	T48820-42030 LINK ASSY, FR	1.00	196.20		196.20
48	8	L48068-42060 ARM SUB-ASSY,	1.00	969.10		969.10
49	9	T43330-19275 JOINT ASSY, LWR BALL	1.00	314.60		314.60
50	0	L43211-78010 KNUCKLE, STEERING,	1.00	875.10		875.10
51	1	T43550-42020 HUB&BEARING ASSY,	1.00	794.30		794.30

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			37,520.64
	Please acknowledge receipt of vehicle	Parts 29,225.00	GST 7.00% 2,626.44
		Labour 8,196.64	Less 0.00
		Sublet 99.00	
		Lubrication/Fluid 0.00	
		Others 0.00	Amount Due 40,147.08

Customer Copy