

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

|            |   |                     |
|------------|---|---------------------|
| ESTIMATE   | : | ACCIDENT REPAIRS    |
| WORKSHOP   | : | UBI ROAD 1          |
| CONTACT NO | : | 6366 2323           |
| FAX NO     | : | 6841 1183           |
| REFERENCE  | : | PA/OD/01095/2022/EQ |
| DATE       | : | 7-Dec-22            |
| WIP        | : | 53753               |

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 9/12/2022

**AIG Asia Pacific Insurance Pte Ltd**  
 78 Shenton Way  
 #07-16 AIG Building  
 Singapore 079120  
 Attn: Motor Claims Dept  
 Tel: 6880 4602 - Fax: 6880 4838

|                   |   |                                             |
|-------------------|---|---------------------------------------------|
| OWNER'S NAME      | : | MS AW SUAT HUAY                             |
| ADDRESS           | : | 87 AMBER ROAD<br>#14-21<br>SINGAPORE 439897 |
| TELEPHONE         | : | HP +65 96988729                             |
| TYPE OF CLAIM     | : | OWN DAMAGE CLAIM                            |
| POLICY NO         | : | 2070109311-01                               |
| VEHICLE NO        | : | SLP 838 Z                                   |
| MODEL CODE        | : | AUDI A5 SPORTBACK 2.0 TFS                   |
| MODEL YEAR        | : | 29/7/2020                                   |
| ENGINE NO         | : | DEM 024112                                  |
| CHASSIS NO        | : | WAUZZZF50LA018353                           |
| MILEAGE           | : | 14,512                                      |
| DATE IN           | : | 6-Dec-22                                    |
| ESTIMATED BY      | : | JOHNNY BOO / ALLAN WU                       |
| ACCIDENT DATE     | : | 6-Dec-22                                    |
| PLACE OF ACCIDENT | : | ENTRANCE TO THE SHORE RESIDENCES            |

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLP 838 Z**

| S/N                         | NATURE OF JOBS                                                                                                                                   | ESTIMATED CHARGES              | SURVEYOR'S RECOMMENDATIONS |
|-----------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------|----------------------------|
| 1                           | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID. | S/N \$ <del>480.00</del> ✓     | ✓                          |
| 2                           | TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.                                                                            | S/N \$ <del>400.00</del> 250 ✓ | ✓                          |
| 3                           | TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR.         | S/N \$ 280.00 ✓                | ✓                          |
| 4                           | TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.   | \$ <del>2,400.00</del> 1000 ✓  | ✓                          |
| 5                           | TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND RHS FRONT DOOR.                                                                                    | \$ <del>3,000.00</del> 1650 ✓  | ✓                          |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                  | <b>: \$ <u>6,560.00</u></b>    |                            |

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLP 838 Z**

| S/N                         | NATURE OF JOBS                                        | ESTIMATED<br>CHARGES | SURVEYOR'S<br>RECOMMENDATIONS |
|-----------------------------|-------------------------------------------------------|----------------------|-------------------------------|
| 6                           | TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT. | S/N \$ 280.00        | X                             |
| 7                           | TO CARRY OUT DIAGNOSTIC CHECK.                        | S/N \$ 192.00        | ✓                             |
| <b>TOTAL LABOUR CHARGES</b> |                                                       | <b>: \$ 7,032.00</b> |                               |



55 UBI ROAD 1, SINGAPORE 408699  
TEL: 6366 2323 FAX: 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLP 838 Z**

**DAMAGED PARTS & PRICES**

| S/N                          | PARTS DESCRIPTION                                                        | QTY | S/NETT             | REMARKS |
|------------------------------|--------------------------------------------------------------------------|-----|--------------------|---------|
| 1                            | FRONT BUMPER <i>de</i>                                                   | 1   | \$ 2,493.00        | 1994.40 |
| 2                            | FRONT BUMPER SECURING STRIP - LH/RH <i>X</i> <i>?</i> <i>X</i> <i>nn</i> | 2   | \$ 79.00           |         |
| 3                            | FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>?</i> <i>X</i> <i>nn</i>  | 1   | \$ 293.00          |         |
| 4                            | FRONT BUMPER AIR GUIDE - RH <i>?</i> <i>✓</i> <i>cm</i> <i>/</i>         | 1   | \$ 72.00           | 57.20   |
| 5                            | FRONT BUMPER AIR GUIDE GRILLE - RH <i>?</i> <i>X</i> <i>nn</i>           | 1   | \$ 151.00          |         |
| 6                            | FRONT BUMPER OUTER GRILLE HOLE COVER - RH <i>X</i> <i>nn</i>             | 1   | \$ 54.00           |         |
| 7                            | FRONT BUMPER GUIDE SECTION - RH <i>?</i> <i>✓</i> <i>cm</i> <i>/</i>     | 1   | \$ 41.00           | 32.24   |
| 8                            | FRONT BUMPER TOP COVER <i>X</i> <i>nn</i>                                | 1   | \$ 143.00          |         |
| 9                            | CAUTION SIGN STICKER <i>X</i> <i>nn</i>                                  | 1   | \$ 16.00           |         |
| 10                           | AIR CONDITIONER STICKER <i>X</i> <i>nn</i>                               | 1   | \$ 9.00            |         |
| 11                           | FRONT PARKING AID SENSOR - OUTER <i>?</i> <i>X</i> <i>nn</i>             | 1   | \$ 266.00          |         |
| 12                           | FRONT PARKING AID SEAL RING <i>X</i> <i>X</i> <i>nn</i>                  | 4   | \$ 10.00           |         |
| 13                           | FRONT FENDER - RH <i>✓</i>                                               | 1   | \$ 1,189.00        | 951.20  |
| 14                           | FRONT FENDER ATTACHMENT PARTS <i>X</i> <i>nn</i>                         | 1   | \$ 55.00           |         |
| 15                           | FRONT FENDER CLOSING ELEMENT - RH <i>rec</i> <i>/</i>                    | 1   | \$ 83.00           | 65.84   |
| 16                           | FRONT FENDER BRACKET - RH FRONT <i>m</i> <i>/</i>                        | 1   | \$ 41.00           | 32.72   |
| 17                           | FRONT FENDER RIVET <i>m</i> <i>/</i>                                     | 6   | \$ 23.00           | 18.24   |
| 18                           | FRONT FENDER BRACE - RH <i>?</i> <i>✓</i> <i>✓</i> <i>✓</i>              | 1   | \$ 132.00          | 105.20  |
| 19                           | FRONT FENDER DEFORMATION ELEMENT BRACKET - RH <i>X</i> <i>nn</i>         | 1   | \$ 55.00           |         |
| 20                           | FRONT FENDER BRACKET - RH CENTER <i>X</i> <i>nn</i>                      | 1   | \$ 40.00           |         |
| <b>SUB TOTAL SPARE PARTS</b> |                                                                          | :   | <b>\$ 5,245.00</b> |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLP 838 Z

|                      |                                                         |     | DAMAGED PARTS & PRICES |                |
|----------------------|---------------------------------------------------------|-----|------------------------|----------------|
| S/N                  | PARTS DESCRIPTION                                       | QTY | S/NETT                 | REMARKS        |
| 21                   | FRONT WHEEL HOUSING LINER - RH <i>form -</i>            | 1   | \$ 299.00              | <i>238.80</i>  |
| 22                   | FRONT WHEEL SPOILER <i>ca -</i>                         | 1   | \$ 82.00               | <i>65.12</i>   |
| 23                   | FRONT WHEEL SPOILER END PLATE - RH <i>? x nn</i>        | 1   | \$ 40.00               |                |
| 24                   | FRONT WHEEL SPOILER STONE CHIP GUARD - RH <i>? x nn</i> | 1   | \$ 57.00               |                |
| 25                   | FRONT WHEEL SPOILER TRIM BRACKET - RH <i>x nn</i>       | 1   | \$ 27.00               |                |
| 26                   | FRONT FENDER CHROME TRIM - RH <i>m -</i>                | 1   | \$ 171.00              | <i>136.40</i>  |
| 27                   | FRONT DOOR CHROME TRIM - RH <i>m -</i>                  | 1   | \$ 171.00              | <i>136.40</i>  |
| 28                   | FRONT FENDER LEDGE COVER - LONG <i>? ✓ cm -</i>         | 1   | \$ 40.00               | <i>31.44</i>   |
| 29                   | FRONT FENDER LEDGE COVER - RH SHORT <i>? x nn</i>       | 1   | \$ 18.00               |                |
| 30                   | HEADLIGHT COVER - RH <i>? ✓ cm -</i>                    | 1   | \$ 49.00               | <i>38.64</i>   |
| 31                   | HEADLIGHT - RH <i>ca -</i>                              | 1   | \$ 8,172.00            | <i>6537.60</i> |
| 32                   | LIFT CYLINDER - RH <i>? x nn</i>                        | 1   | \$ 217.00              |                |
| 33                   | LIFT CYLINDER BRACKET - RH <i>? ✓ cm -</i>              | 1   | \$ 17.00               | <i>12.88</i>   |
| 34                   | LIFT CYLINDER CORRUGATED PIPE <i>? x nn</i>             | 1   | \$ 107.00              |                |
| 35                   | LIFT CYLINDER CORRUGATED HOSE <i>? x nn</i>             | 1   | \$ 53.00               |                |
| 36                   | LOCK CARRIER BRACKET <i>x nn</i>                        | 1   | \$ 154.00              |                |
| 37                   | RHS FRONT RIM <i>x nn</i>                               | S/N | TBC                    |                |
| 38                   | SUNDRIES <i>? x nn</i>                                  |     | \$ 500.00              |                |
| TOTAL SPARE PARTS    |                                                         |     | :                      | \$ 15,419.00   |
| TOTAL LABOUR CHARGES |                                                         |     | :                      | \$ 7,032.00    |
| GRAND TOTAL          |                                                         |     | :                      | \$ 22,451.00   |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Pass - Hp 9001 0068

09/12/22 @ 1650

5 days

Revert

EXCESS: TBA

Resurvey before paint

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT

