

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/01095/2022/EQ
DATE : 7-Dec-22
WIP : 53753

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 9/12/2022

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Rasul
5 days excludue 1 Sunday
Johnny Boo 10 Feb 23

OWNER'S NAME : MS AW SUAT HUAY
ADDRESS : 87 AMBER ROAD
#14-21
SINGAPORE 439897
TELEPHONE : HP +65 96988729
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070109311-01
VEHICLE NO : **SLP 838 Z**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFS
MODEL YEAR : 29/7/2020
ENGINE NO : DEM 024112
CHASSIS NO : WAUZZZF50LA018353
MILEAGE : 14,512
DATE IN : 6-Dec-22
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 6-Dec-22
PLACE OF ACCIDENT : ENTRANCE TO THE SHORE RESIDENCES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLP 838 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	\$ 250.00
3	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR.	S/N \$	280.00	\$ 280.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00	\$ 1,000.00
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND RHS FRONT DOOR.	\$	3,000.00	\$ 1,650.00
TOTAL LABOUR CHARGES		: \$	6,560.00	\$ 3,660.00



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLP 838 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i>		<i>\$ 3,660.00</i>
6	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	<i>\$ 192.00</i>
TOTAL LABOUR CHARGES		:	\$ 7,032.00	<i>\$ 3,852.00</i>

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLP 838 Z

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,493.00	\$	1,994.40
2	FRONT BUMPER SECURING STRIP - LH / RH	2	\$ 79.00		
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 293.00		
4	FRONT BUMPER AIR GUIDE - RH	1	\$ 72.00	\$	57.20
5	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 151.00		
6	FRONT BUMPER OUTER GRILLE HOLE COVER - RH	1	\$ 54.00		
7	FRONT BUMPER GUIDE SECTION - RH	1	\$ 41.00	\$	32.24
8	FRONT BUMPER TOP COVER	1	\$ 143.00		
9	CAUTION SIGN STICKER	1	\$ 16.00		
10	AIR CONDITIONER STICKER	1	\$ 9.00		
11	FRONT PARKING AID SENSOR - OUTER	1	\$ 266.00		
12	FRONT PARKING AID SEAL RING	4	\$ 10.00		
13	FRONT FENDER - RH	1	\$ 1,189.00	\$	951.20
14	FRONT FENDER ATTACHMENT PARTS	1	\$ 55.00		
15	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 83.00	\$	65.84
16	FRONT FENDER BRACKET - RH FRONT	1	\$ 41.00	\$	32.72
17	FRONT FENDER RIVET	6	\$ 23.00	\$	18.24
18	FRONT FENDER BRACE - RH	1	\$ 132.00	\$	105.20
19	FRONT FENDER DEFORMATION ELEMENT BRACKET - RH	1	\$ 55.00		
20	FRONT FENDER BRACKET - RH CENTER	1	\$ 40.00		
SUB TOTAL SPARE PARTS		:	\$ 5,245.00	\$	3,257.04

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLP 838 Z

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY		S/NETT	REMARKS
		c/f			\$ 3,257.04
21	FRONT WHEEL HOUSING LINER - RH	1	\$	299.00	\$ 238.80
22	FRONT WHEEL SPOILER	1	\$	82.00	\$ 65.12
23	FRONT WHEEL SPOILER END PLATE - RH	1	\$	40.00	
24	FRONT WHEEL SPOILER STONE CHIP GUARD - RH	1	\$	57.00	
25	FRONT WHEEL SPOILER TRIM BRACKET - RH	1	\$	27.00	
26	FRONT FENDER CHROME TRIM - RH	1	\$	171.00	\$ 136.40
27	FRONT DOOR CHROME TRIM - RH	1	\$	171.00	\$ 136.40
28	FRONT FENDER LEDGE COVER - LONG	1	\$	40.00	\$ 31.44
29	FRONT FENDER LEDGE COVER - RH SHORT	1	\$	18.00	
30	HEADLIGHT COVER - RH	1	\$	49.00	\$ 38.64
31	HEADLIGHT - RH	1	\$	8,172.00	\$ 6,537.60
32	LIFT CYLINDER - RH	1	\$	217.00	
33	LIFT CYLINDER BRACKET - RH	1	\$	17.00	\$ 12.88
34	LIFT CYLINDER CORRUGATED PIPE	1	\$	107.00	
35	LIFT CYLINDER CORRUGATED HOSE	1	\$	53.00	
36	LOCK CARRIER BRACKET	1	\$	154.00	
37	RHS FRONT RIM	S/N		TBC	
38	SUNDRIES		\$	500.00	
TOTAL SPARE PARTS		:	\$	15,419.00	\$ 10,454.32
TOTAL LABOUR CHARGES		:	\$	7,032.00	\$ 3,852.00
GRAND TOTAL		:	\$	22,451.00	\$ 14,306.32

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-30/12/22



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT