

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1105/2022/EQ
DATE : 9-Dec-22
WIP : 54025

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 9/12/2022

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : M/S KSB SINGAPORE (ASIA PACIFIC) PTE LTD
ADDRESS : 7 WOODLANDS WALK
SINGAPORE 738320

TELEPHONE : HP +65 67056698
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070168460-02
VEHICLE NO : **SMW 6651 G**
MODEL CODE : AUDI A4 2.0 TFSI S-TRONIC
MODEL YEAR : 30/11/2020
ENGINE NO : DEM 025391
CHASSIS NO : WAUZZZF46MN001042
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 4-Dec-22
PLACE OF ACCIDENT : 144 UPPER BUKIT TIMAH ROAD, SINGAPORE 588177
CAR PARK

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMW 6651 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00 250	
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$ 1,400.00 X	
4	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00 X	
5	TO RENEW LHS FRONT FENDER INNER AIRCON PIPE.	S/N \$ 280.00 ?	
6	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,900.00 1000	
TOTAL LABOUR CHARGES		: \$ 8,610.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMW 6651 G

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND BONNET. X	\$	3,000.00 1100	
8	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	
TOTAL LABOUR CHARGES		:	<u>\$ 12,082.00</u>	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 6651 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>de-</i>	1	\$ 2,377.00	
2	FRONT BUMPER FIXING PARTS <i>X?</i>	1	\$ 393.00	
3	FRONT BUMPER SECURING STRIP - LH / RH <i>X</i>	1 <i>X</i>	\$ 79.00	
4	FRONT BUMPER GRILLE - CENTER <i>?</i>	1	\$ 219.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>?</i>	1	\$ 293.00	
6	FRONT BUMPER AIR GUIDE - LH <i>?</i>	1	\$ 51.00	
7	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE <i>?</i>	1	\$ 293.00	
8	FRONT BUMPER AIR GUIDE GRILLE - LH <i>de-</i>	1	\$ 151.00	
9	FRONT BUMPER OUTER GRILLE HOLE COVER - LH <i>?</i>	1	\$ 54.00	
10	RADIATOR GRILLE <i>cm/</i>	1	\$ 1,754.00	
11	FRONT BUMPER FOAM FILLER PIECE <i>?</i>	1	\$ 212.00	
12	FRONT BUMPER REINFORCEMENT BEAM <i>?</i>	1	\$ 899.00	
13	FRONT BUMPER BRACKET - LH <i>X</i>	1	\$ 254.00	
14	FRONT BUMPER GUIDE SECTION - LH <i>?</i>	1	\$ 41.00	
15	FRONT BUMPER TOP COVER <i>X</i>	1	\$ 143.00	
16	CAUTION SIGN STICKER <i>X</i>	1	\$ 16.00	
17	AIR CONDITIONER STICKER <i>X</i>	1	\$ 9.00	
18	FRONT BUMPER BRACKET <i>?</i>	1	\$ 154.00	
19	FRONT BUMPER SUPPORT - LH / RH <i>?</i>	2	\$ 64.00	
20	HORN HIGH TONE - LH <i>?</i>	1	\$ 134.00	
SUB TOTAL SPARE PARTS		:	\$ 7,590.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 6651 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	HORN BRACKET - LH ?	1	\$ 33.00	
22	FRONT PARKING AID SENSOR - INNER / OUTER ?	1	\$ 532.00	
23	FRONT PARKING AID SEAL RING ✓	4	\$ 10.00	
24	FRONT BUMPER WIRING SET ?	1	\$ 642.00	
25	FRONT FENDER - LH ✓	1	\$ 1,227.00	
26	FRONT FENDER ATTACHMENT PARTS X	1	\$ 225.00	
27	FRONT FENDER CLOSING ELEMENT - LH ✓	1	\$ 81.00	
28	FRONT FENDER BRACKET - LH ✓	1	\$ 41.00	
29	FRONT FENDER RIVET ✓	7	\$ 27.00	
30	FRONT FENDER DEFORMATION ELEMENT BRACKET - LH X	1	\$ 55.00	
31	FRONT FENDER BRACKET - LH X	1	\$ 36.00	
32	FRONT FENDER BRACE - LH ?	1	\$ 132.00	
33	FRONT WHEEL HOUSING LINER - LH ?	1	\$ 256.00	
34	FRONT WHEEL SPOILER - LH ✓	1	\$ 82.00	
35	FRONT WHEEL SPOILER END PLATE - LH X	1	\$ 39.00	
36	FRONT FENDER LEDGE COVER - LH LONG ?	1	\$ 35.00	
37	HEADLIGHT COVER - LH ?	1	\$ 49.00	
38	BONNET X	1	\$ 3,425.00	
39	BONNET IMPACT PROTECTION - CENTER / LH / RH X	3	\$ 93.00	
40	BONNET STRIKER - LH X	1	\$ 56.00	
SUB TOTAL SPARE PARTS		:	\$ 7,076.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 6651 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	BONNET LOCK <i>X</i>	1	\$ 228.00	
42	HEADLIGHT - LH <i>ca</i>	1	\$ 8,172.00	
43	HEADLIGHT HOSE <i>?</i>	1	\$ 42.00	
44	HEADLIGHT COMPENSATING PIECE <i>?</i>	1	\$ 45.00	
45	HEADLIGHT COMPENSATING PIECE <i>?</i>	2	\$ 93.00	
46	HEADLIGHT COMPENSATING PIECE <i>?</i>	1	\$ 45.00	
47	LIFT CYLINDER - LH <i>ca</i>	1	\$ 231.00	
48	LIFT CYLINDER BRACKET <i>?</i>	1	\$ 7.00	
49	LIFT CYLINDER CORRUGATED PIPE <i>?</i>	1	\$ 107.00	
50	LOCK CARRIER <i>?</i>	1	\$ 1,478.00	
51	LOCK CARRIER SUPPORT - LH <i>?</i>	1	\$ 43.00	
52	A/C CONDENDER <i>X</i>	1	\$ 683.00	
53	A/C CONDENDER REFRIGERANT LINE <i>X</i>	1	\$ 186.00	
54	A/C CONDENSER REFRIGERANT LINE <i>X</i>	1	\$ 381.00	
55	A/C CONDENSER REFRIGERANT LINE <i>X</i>	1	\$ 277.00	
56	A/C CONDENSER REFRIGERANT PIPE <i>X</i>	1	\$ 585.00	
57	A/C LINE HOLDER BRACKET <i>X</i>	1	\$ 9.00	
58	OUTSIDE TEMPERATURE SENSOR BRACKET <i>X</i>	1	\$ 21.00	
59	CHARGE AIR COOLER <i>X</i>	1	\$ 654.00	
60	CHARGE AIR COOLER PRESSURE PIPE - LH <i>X</i>	1	\$ 496.00	
SUB TOTAL SPARE PARTS		:	\$ 13,783.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 6651 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	READY-MIX COOLANT X	6	\$ 297.00	
62	RADIATOR AIR GUIDE - LH INNER X	1	\$ 51.00	
63	RADIATOR AIR GUIDE - LH / RH OUTER X	2	\$ 38.00	
64	RADIATOR AIR GUIDE - UPPER / LOWER X	2	\$ 44.00	
65	FRONT ALUMINIUM RIM - LH <i>San</i>	1	\$ 1,292.00	
66	FRONT ALUMINIUM RIM RUBBER VALVE <i>nee</i>	1	\$ 4.00	
67	FRONT NO PLATE <i>w /</i>	S/N	\$ 60.00	
68	SUNDRIES ?		\$ 500.00	
TOTAL SPARE PARTS		:	\$ 30,735.00	
TOTAL LABOUR CHARGES		:	\$ 12,082.00	
GRAND TOTAL		:	\$ 42,817.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Rasul - Hp 90010068
 SURVEYED DATE : 09/12/22 @ 1715
 AUTHORISED DATE :
 EXCESS COST : 5 days
 LIABILITY : EXCESS-TBA
 REMARKS : Resurvey before paint

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
 PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
 BODY REPAIR MANAGER

ALLAN WU
 CLAIMS CONSULTANT