

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1105/2022/EQ
DATE : 9-Dec-22
WIP : 54025

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 9/12/2022

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Rasul

6 days & 1 Sunday

Johnny Boo 3 Mar 23

OWNER'S NAME : M/S KSB SINGAPORE (ASIA PACIFIC) PTE LTD
ADDRESS : 7 WOODLANDS WALK
SINGAPORE 738320

TELEPHONE : HP +65 67056698
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070168460-02
VEHICLE NO : **SMW 6651 G**
MODEL CODE : AUDI A4 2.0 TFSI S-TRONIC
MODEL YEAR : 30/11/2020
ENGINE NO : DEM 025391
CHASSIS NO : WAUZZZF46MN001042
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 4-Dec-22
PLACE OF ACCIDENT : 144 UPPER BUKIT TIMAH ROAD, SINGAPORE 588177
CAR PARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMW 6651 G

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	\$	250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$	1,400.00		
4	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$	1,200.00		
5	TO RENEW LHS FRONT FENDER INNER AIRCON PIPE.	S/N \$	280.00		
6	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	4,900.00	\$	1,000.00
TOTAL LABOUR CHARGES		:	\$ 8,610.00	\$	1,730.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMW 6651 G

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i>		\$ 1,730.00
7	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND BONNET.	\$	3,000.00	\$ 1,100.00
8	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	\$ 280.00
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 12,082.00	\$ 3,302.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 6651 G

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,377.00	\$	1,901.60
2	FRONT BUMPER FIXING PARTS	1	\$ 393.00		
3	FRONT BUMPER SECURING STRIP - LH / RH	2	\$ 79.00		
4	FRONT BUMPER GRILLE - CENTER	1	\$ 219.00		
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 293.00	\$	234.00
6	FRONT BUMPER AIR GUIDE - LH	1	\$ 51.00		
7	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE	1	\$ 293.00		
8	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 151.00	\$	120.40
9	FRONT BUMPER OUTER GRILLE HOLE COVER - LH	1	\$ 54.00	\$	42.64
10	RADIATOR GRILLE	1	\$ 1,754.00	\$	1,403.20
11	FRONT BUMPER FOAM FILLER PIECE	1	\$ 212.00		
12	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 899.00		
13	FRONT BUMPER BRACKET - LH	1	\$ 254.00		
14	FRONT BUMPER GUIDE SECTION - LH	1	\$ 41.00	\$	32.24
15	FRONT BUMPER TOP COVER	1	\$ 143.00		
16	CAUTION SIGN STICKER	1	\$ 16.00		
17	AIR CONDITIONER STICKER	1	\$ 9.00		
18	FRONT BUMPER BRACKET	1	\$ 154.00		
19	FRONT BUMPER SUPPORT - LH / RH	2	\$ 64.00		
20	HORN HIGH TONE - LH	1	\$ 134.00		
SUB TOTAL SPARE PARTS		:	\$ 7,590.00	\$	3,734.08

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 6651 G

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	3,734.08
21	HORN BRACKET - LH	1	\$ 33.00		
22	FRONT PARKING AID SENSOR - INNER / OUTER	2	\$ 532.00		
23	FRONT PARKING AID SEAL RING	4	\$ 10.00		
24	FRONT BUMPER WIRING SET	1	\$ 642.00		
25	FRONT FENDER - LH	1	\$ 1,227.00	\$	981.60
26	FRONT FENDER ATTACHMENT PARTS	1	\$ 225.00		
27	FRONT FENDER CLOSING ELEMENT - LH	1	\$ 81.00	\$	64.24
28	FRONT FENDER BRACKET - LH	1	\$ 41.00	\$	32.72
29	FRONT FENDER RIVET	7	\$ 27.00	\$	21.28
30	FRONT FENDER DEFORMATION ELEMENT BRACKET - LH	1	\$ 55.00		
31	FRONT FENDER BRACKET - LH	1	\$ 36.00		
32	FRONT FENDER BRACE - LH	1	\$ 132.00	\$	105.20
33	FRONT WHEEL HOUSING LINER - LH	1	\$ 256.00		
34	FRONT WHEEL SPOILER - LH	1	\$ 82.00	\$	65.12
35	FRONT WHEEL SPOILER END PLATE - LH	1	\$ 39.00		
36	FRONT FENDER LEDGE COVER - LH LONG	1	\$ 35.00	\$	27.52
37	HEADLIGHT COVER - LH	1	\$ 49.00	\$	38.64
38	BONNET	1	\$ 3,425.00		
39	BONNET IMPACT PROTECTION - CENTER / LH / RH	3	\$ 93.00		
40	BONNET STRIKER - LH	1	\$ 56.00		
SUB TOTAL SPARE PARTS		:	\$ 7,076.00	\$	5,070.40

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 6651 G

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	<i>5,070.40</i>
41	BONNET LOCK	1	\$ 228.00		
42	HEADLIGHT - LH	1	\$ 8,172.00	\$	<i>6,537.60</i>
43	HEADLIGHT HOSE	1	\$ 42.00		
44	HEADLIGHT COMPENSATING PIECE	1	\$ 45.00		
45	HEADLIGHT COMPENSATING PIECE	2	\$ 93.00		
46	HEADLIGHT COMPENSATING PIECE	1	\$ 45.00		
47	LIFT CYLINDER - LH	1	\$ 231.00	\$	<i>184.40</i>
48	LIFT CYLINDER BRACKET	1	\$ 7.00		
49	LIFT CYLINDER CORRUGATED PIPE	1	\$ 107.00		
50	LOCK CARRIER	1	\$ 1,478.00		
51	LOCK CARRIER SUPPORT - LH	1	\$ 43.00	\$	<i>33.84</i>
52	A/C CONDENDER	1	\$ 683.00		
53	A/C CONDENDER REFRIGERANT LINE	1	\$ 186.00		
54	A/C CONDENSER REFRIGERANT LINE	1	\$ 381.00		
55	A/C CONDENSER REFRIGERANT LINE	1	\$ 277.00		
56	A/C CONDENSER REFRIGERANT PIPE	1	\$ 585.00		
57	A/C LINE HOLDER BRACKET	1	\$ 9.00		
58	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 21.00		
59	CHARGE AIR COOLER	1	\$ 654.00		
60	CHARGE AIR COOLER PRESSURE PIPE - LH	1	\$ 496.00		
SUB TOTAL SPARE PARTS		:	\$ 13,783.00	\$	<i>11,826.24</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 6651 G

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	<i>11,826.24</i>
61	READY-MIX COOLANT	6	\$	297.00	
62	RADIATOR AIR GUIDE - LH INNER	1	\$	51.00	
63	RADIATOR AIR GUIDE - LH / RH OUTER	2	\$	38.00	
64	RADIATOR AIR GUIDE - UPPER / LOWER	2	\$	44.00	
65	FRONT ALUMINIUM RIM - LH	1	\$	1,292.00	\$ 1,033.60
66	FRONT ALUMINIUM RIM RUBBER VALVE	1	\$	4.00	\$ 2.96
67	FRONT NO PLATE	S/N	\$	60.00	\$ 60.00
68	SUNDRIES		\$	500.00	\$ 68.24
TOTAL SPARE PARTS		:	\$	30,735.00	\$ 12,991.04
TOTAL LABOUR CHARGES		:	\$	12,082.00	\$ 3,302.00
GRAND TOTAL		:	\$	42,817.00	\$ 16,293.04

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bi-07/02/23