

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT
#01-49 SINGAPORE 415875
Tel: +65 64524457
Fax: +65 64524584
Company Reg No: 201929175W

Vehicle number: SGD8688J
Make & Model: Volkswagen Sharan
Chassis number: WVWZZZ7NZHV236734

No.	Description of spare parts	Qty	Amount S\$
1	Front bumper	1	\$ del 2,214.59
2	Front bumper LH side corner parking sensor	1	\$ rm 190.18
3	Front bumper LH side parking sensor	1	\$ x 7 x190.18
4	Front bumper LH centre parking sensor	1	\$ x 7 x190.18
5	Front bumper parking sensor rubber seal	6	\$ x 7 22.35
6	Front bumper LH fog lamp	1	\$ cm 372.13
7	Front bumper LH fog lamp cover	1	\$ art 189.91
8	Front bumper centre grille	1	\$ x 1 221.54
9	Front bumper centre grille chrome moulding	1	\$ x 1 x220.19
10	Front bumper reinforcement	1	\$ x 7 x734.58
11	Front bumper centre bracket	1	\$ x 1 155.32
12	Front bumper RH side retainer	1	\$ x 1 31.35
13	Front bumper LH side retainer	1	\$ cm 31.35
14	Front bumper RH inner bracket	1	\$ x 1 33.19
15	Front bumper LH inner bracket	1	\$ x 1 33.19
16	LH headlamp	1	\$ art 2,669.12
17	LH headlamp nozzle cover	1	\$ art 26.00
18	LH headlamp nozzle	1	\$ cm 235.66
19	LH headlamp upper panel	1	\$ x 1 53.39
20	RH headlamp	1	\$ x 1 2,736.03
21	Front grille	1	\$ cm 606.73
22	Front grille emblem	1	\$ net 115.42
23	Support panel	1	\$ x 1 905.02
24	Aircon condenser	1	\$ x 1 876.95
25	Radiator assy	1	\$ x 1 783.37
26	Front LH fender	1	\$ x 1 872.62
27	Front LH fender splash shield	1	\$ x 1 221.03
			\$ 14,931.57
		Parts less 10%	\$ 1,493.16
		Total	\$ 13,438.41

No.	Special Nett Items	Qty	Amount S\$
1	Front bumper clips	1set	\$ 30.00 ✓ 80.00
2	Front grille clips	1set	\$ 20.00 ✓ 60.00
3	Radiator coolant	1	\$ 80.00 ✓ 80.00
4	Front LH fender splash shield clips	1set	\$ 70.00 ✓ 70.00

Total: \$ 290.00

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	250 \$ 1,300.00
2	Spray painting on affected areas and panels	250 \$ 1,200.00
3	Check wiring and lighting system on affected areas	\$ 30 80.00
4	Apply rust coating chemical on affected areas and panels	\$ X 70.00
5	Refocus and adjust headlamps assy	\$ X 80.00
6	Remove and replace aircon condenser, pipes and hoses to assist repair. To refill gas	\$ X 220.00
7	Remove and replace radiator assy, hoses and fan assy to assist repair. To refill coolant	\$ X 280.00
Total:		\$ 3,230.00

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

7601.12 5583.32

L/S - 6080.89 4466.65
= 6100 4450

Spare Parts: \$ 13,438.41
Special Nett: \$ 290.00
Labour: \$ 3,230.00

Total Amount: \$ 16,958.41

Tan Jiah 97495749

'WP' 13/12/22 5pm

4/5 Resurvey after repair

tanjiah@lkhauto.com

- To check consistency of accident
- To check part prices
• 2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Type text here