

Plate Number	Case Number	Brand	Model Details	Body Type	Insurance company	Export CSV
SNB7799G	-	Hyundai	Tucson	SUV	INDIA INTERNATIONAL	
Technician	SA	Parts Manager				
-	LKK_assignments	-				

Parts

#	Description	OE Number	Part Type	Unit Price	Cost	Mark up/Disc	Qty	Sum
01	LH front door <div>Customized</div>			\$0.00	\$1782.30	-20 %	1	\$1425.84
02	LH front door glass outer moulding <div>Customized</div>			\$0.00	\$192.50	-20 %	1	\$154.00
03	LH front door lower garnish <div>Customized</div>			\$0.00	\$265.00	-20 %	1	\$212.00
04	LH rear door <div>Customized</div>			\$0.00	\$1821.40	-20 %	1	\$1457.12
05	LH rear door glass outer moulding <div>Customized</div>			\$0.00	\$182.30	-20 %	1	\$145.84
06	LH rear door garnish (Back) <div>Customized</div>			\$0.00	\$242.50	-20 %	1	\$194.00
07	LH rear door lower garnish <div>Customized</div>			\$0.00	\$312.00	-20 %	1	\$249.60
								Total :\$3838.40

Labors

Replace / RnR

#	Description	Labor Code	Type	Labor Hour	Unit Price	Mark up/Disc	Sum
01	To remove and rearrange electrical wirings, check lightings. <div>Customized</div>		RnR	0.00	\$20.00	0 %	\$20.00
02	To remove, transfer front and rear door components to new doors. <div>Customized</div>		RnR	0.00	\$120.00	0 %	\$120.00
03	Panel beating <div>Customized</div>		RnR	0.00	\$660.00	0 %	\$660.00
04	Rust proofing on affected portions. <div>Customized</div>		RnR	0.00	\$60.00	0 %	\$60.00
							Total :\$860.00

Paint

#	Description	Labor Code	degree	Labor Hour	Unit Price	Mark up/Disc	Sum
01	Spray painting <div>Customized</div>		Full spray	0.00	\$600.00	0 %	\$600.00
							Total :\$600.00

Remarks 1 remarks

2023-05-23 22:30 Assessor Supervisor-Insurlogic 4 42797773348

FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:

CONCLUDED THE COST OF REPAIR AT \$5,298.40 WITH 5 WORKING DAYS.