Manager Andrews Andrew	
ASS. RECBY: TOUANN REF. CS CT1.27	2012397/Thps
ASSI	GNMENT
Estimated lost: OD / TP VS / TP RES / OD RES / EVA / INV / MV	Veh No: SFG 236 L Yr Regn: 2015 Aug Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Traller or
To Inspect/Vehicle No:	Make: Minda voly85ey. c.c 2356
at Workship m/s	Colour Silver A/C: Insured / Std / Ni / NA
οί	Sp.Reading 245015 T/Radio: Insured Std NI NA
insured:	Eng/No:
Policy No.	C/No: , JHMRC 1890 FG 202541
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum insuled: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Yeh:	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 215/55/97
(Policy Condition)	R: 7 7
Remark: The veh had commenced its N/S 0/S	BS I DUN / EXNOVA / GY I-FS I LIZA / MID) OHTSU I PIR I SUMI /
repair at the time of inspection.	TOYO / YOKO DI
Ball. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 6 mm
GIA / PR Seen:Consistent? : Yes or No	L/Bal. L/Bal. 6 mm
Est. Repairs: days Res.: Yes or No	D.O.A. D.O.I. 15/12/22
Lum Sum: % 3 Val.: Yes or No	Survey held at Nan Mofor Uhi
CA / REV / REP. / 24 HRS Vehicle: IN / OL	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
1	1
Date/Time, File Pass 10? : Prell. Report	Days Of Repair:
final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) Add I	Fee: : Site Insp (\$)s + Rssi_
	: Interview (\$) Photos
Report format :	Tech. Irivs (\$) Others
Lump Sum / LB.4: (%	:Weelend (\$
*	: tope



QUOTATION

Company Ref. No.: S60FC1380G

GST Reg No.: M200050223

Page

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE

3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909

SINGAPORE 07990

Registration No Chassis No : SFG2361L

Model

: JHMRC1890FC202541 : ODYSSEY2.4 EXV-S 15YM NAVI-RES

Owner's Name

: OW CHECK KWONG

Ins Policy No.

Item

:

Date of Accident : 9/12/2022

Document No.

Date

Qty

: SQT22003641

00122000011

: 9. Dec 2022

Customer No. Svc Advisor : WZC008 : YOU PO SOON

Engine No

: K24W71011244 : 9. Dec 2022 5:05:22 PM

Date | Time Surveyor Name

ie ;

Survey Date : Authorisation Date :

Unit Price Disc %

7% GST Amount Amount incld GST

Description
TP DIRECT SETTLEMENT (J/NO:)

OWNER: MR OW

OWNER INSURER: LIBERTY

ACC DATE: 9/12/2022 SURVEYED BY:

DATE: REF NO:

TP INSURER: C/TAIPING

TP VEH: SKG4482Z

	TI VEII. OROTTOLL					
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE	2	19.20	25 New 28.80	2.02	30.82
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER	1	18.10	25 Mel / 13.57	0.95	14.52
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER	1	18.10	25 Net - 13.57	0.95	14.52
73221-SR4-000	SPACERRR.W/SHIELD	4	4.20	25 12.60	0.88	13.48
73225-TM8-000	RUBBER AWINDSHIELD DAM	1	3.90	25 Mel 2.92	0.20	3.12
73226-SZW-000	DAMPERSTD 5X5	2	9.10	25 NCL 13.65	0.96	14.61
76711-T6A-003	CAPPIVOT	1	5.20	25 Net / 3.90	0.27	4.17
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00	nel 60.00	4.20	64.20
75701-T6A-000	EMBLEMH	1	28.20	25 Ne 21.15	1.48	22.63
34150-T6A-003	LIGHT ASSY,R.LID	1	413.40	25 cm 310.05	21.70	331.75
34155-T6A-003	LIGHT ASSYL.LID	1	413.40	25 ma 310.05	21.70	331.75
33500-T6A-003	TAILLIGHT ASSYR.	1	897.20	25 × 672.90	47.10	720.00
33550-T6A-003	TAILLIGHT ASSYL.	1	897.20	25 🗶 672.90	47.10	720.00
74940-TR0-003	BUZZER ASSYSMART	1	64.30	25 🗙 48.22	3.38	51.60
38387-SLE-003	ANTENNA ASSY,L.RR.	1	64.80	25 cm - 48.60	3.40	52.00
84431-T6A-J01ZA	LINING ASSYTAILGATE LOWER	1	220.80	25 dl 165.60	11.59	177.19
84441-T6A-J01ZA	POCKETTAILGATE LINING PULL	1	11.50	25 🗙 8.62	0.60	9.22
84640-T6A-003ZA	LINING ASSYRR.PANEL	1	110.90	25 06 83.17	5.82	88.99
04715-T6A-900ZZ	FACERR.BUMPER	1	608.30	25 de 156.22	31.94	488.16
						The second second

Printed on 9/12/2022 5:27:48 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



QUOTATION

Company Ref. No.: S60FC1380G

GST Reg No.: M200050223

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838 Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

: CHINA TAIPING INSURANCE (S'PORE) PTE Customer

> 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909

Registration No : SFG2361L

Chassis No : JHMRC1890FC202541

Model

Owner's Name

Ins Policy No. **Date of Accident**

: ODYSSEY2.4 EXV-S 15YM NAVI-RES

: OW CHECK KWONG

: 9/12/2022

Document No.	: SQT22003641	Page	2
Date	: 9. Dec 2022		
Customer No.	: WZC008		
Svc Advisor	: YOU PO SOON		
Engine No	: K24W71011244		

: 9. Dec 2022 5:05:22 PM Date | Time

Surveyor Name **Survey Date Authorisation Date**

Date of Accident						7% GST	Amount
Item	Description	Qty	Unit Price	Disc %	Amount	Amount	incld GST
71593-T6A-003	SPACERR.RR.BUMPER SIDE	1	20.40	25 🗶	15.30	1.07	16.37
71598-T6A-003	SPACERL.RR.BUMPER SIDE	1	20.40	25 🗶	15.30	1.07	16.37
91505-TM8-003	CLIP,BUMPER	7	2.30	25 Nel-	12.07	0.84	12.91
66100-T6A-Q01ZZ	PANEL COMP, REAR	1	493.20	25 ht	369.90	25.89	395.79
04656-T6A-310ZZ	PAN SET,3RD SEAT	1	361.70	25 RY	271.27	18.99	290.26
68100-T6A-Q10ZZ	TAILGATE COMP	1	1146.20	25 bt-	859.65	60.18	919.83
74440-T6A-003	WEATHERSTRIPTAILGATE	1	125.70	25 lut	94.27	6.60	100.87
74891-T6A-003	MOLDING ASSYRR.LICENSE GARN	1	187.90	25 ?	140.92	9.86	150.78
74800-TF0-J01	LOCKTAILGATE	1	200.40	25 X	150.30	10.52	160.82
74890-T6A-J01	GARNISH ASSYRR.LICENSE	1	246.70	25 7	185.02	12.95	197.97
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00	nur	320.00	22.40	342.40
72841-SH3-315	OILSHEET	1	43.50	25 X	32.62	2.28	34.90
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00	X	45.00	3.15	48.15
				Sum Item	5458.11	382.04	5,840.15
BOSUN	SUNDRIES	1	50.00	20.	50.00	3.50	53.50
BOSUN	INSPECT RR LIGHTING MECHANISMS. PERFORM						
BML02I	WATER	1	180.00	150	180.00	12.60	192.60
BA02R	REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	200.00		200.00	14.00	214.00
BOJSE	BODY JOINT SEALANT.	1	200.00	100	200.00	14.00	214.00
BOBC	BODY UNDERSIDE COATING (N)	1	200.00	100	200.00	14.00	214.00
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	450.00	250	450.00	31.50	481.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	650.00	350		45.50	695.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	450.00	350		31.50	481.50
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	450.00	350	450.00	31.50	481.50
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR.(N)	1	450.00	X	450.00	31.50	481.50
BMF00D	REMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	650.00	X	650.00	45.50	695.50
BMI02D	REMOVE & INSTALL RR SEATS TRUNK LININGS GARNISHES	1	650.00	X	650.00	45.50	695.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	650.00		650.00	45.50	695.50

Printed on 9/12/2022 5:27:48 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Customer

Website: www.honda.com.sg

: CHINA TAIPING INSURANCE (S'PORE) PTE

3 ANSON ROAD #16-00 SPRINGLEAF TOWER

SINGAPORE 079909

: JHMRC1890FC202541

For 24-hours Roadside Assistance, Call 98203838

Document No.

: SQT22003641

Page 3

Amount

QUOTATION

Company Ref. No.: S60FC1380G

GST Reg No.: M200050223

Date

: 9. Dec 2022

: WZC008

Svc Advisor

: YOU PO SOON

Engine No

Customer No.

: K24W71011244

Date | Time

: 9. Dec 2022 5:05:22 PM

70/ CST

Surveyor Name

Survey Date

: OW CHECK KWONG

: ODYSSEY2.4 EXV-S 15YM NAVI-RES

Ins Policy No. Date of Accident

Registration No

Owner's Name

Chassis No

Model

: 9/12/2022

: SFG2361L

Authorisation Date

Item	Description	Qty	Unit Price	e Disc %	Amount	Amount	incld GST
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00	/	650.00	45.50	695.50
BKRP02B	CUT & RENEW RR FLOOR PANEL.STRAIGHTEN 65^o FENDERS ALIG	1	5500.00	3250	5500.00	385.00	5885.00
BP08R	SPRAY PAINTING ON REPAIRED OR REPLACED AREA (8P)	S. ₁	4300.00	3120.	4300.00	301.00	4601.00
				Sum Labor	<u>15680.00</u>	1,097.60	16,777.60

Survey By

97495749

62563561

Date & Time

1030

Total Amount 21,138.11 1,479.64

22.617.75

Total (Inclusive of GST)

22,617.75

Excess Status

Signature

ihne Manto.com.

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 9/12/2022 5:27:48 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.

SK0K22C90001 / KAH MOTOR CO SDN BHD [408610] ENTRY DATE & TIME: 09/12/2022 16:47 (SGT) SUBMITTED BY: YOU PO SOON VERSION: 1 (09/12/2022 16:47 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Please report correctly the details of the accident to speed up the claims process.

This Form must be completed by the Policyholder and/or the Actual Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies. policy liability

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Reported by Date of Accident **Exact Location of Accident** Additional Location Information Country/State of Loss

09/12/2022 16:47 (SGT) 09/12/2022 13:00 (SGT) Near 45 Defu Lane 12, Singapore 539140 BARTLEY ROAD EAST TOWARDS AIRPORT ROAD Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SFG2361L

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner NRIC No **Email Address** Mobile Phone No Alternative Phone No

No OW CHECK KWONG SXXXX181D OWCK303@GMAIL.COM (Phone) +65-90119717

VEHICLE PARTICULARS

Manufacturer Model Variant Exact purpose for which vehicle was being used at time of accident Are you claiming under your own insurance policy for repair to your vehicle? Vehicle Category Transmission CC

Private use

Honda

Odyssey

No - Claiming third party

Private car Auto 2400

INSURANCE COMPANY

Name of Insurance Company Policy Number / Cover Note Number Liberty Insurance Pte Ltd

DRIVER

Name of Driver NRIC No Date Of Birth Occupation

OW CHECK KWONG SXXXX181D 17/11/1959 Indoor

Date Of Driving Pass Driving experience

Gender Mobile Number Alt. Phone Number

Email Address Address

Address complement

Postcode

Is the driver the policyholder?

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions

Road Surface

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 No Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Yes Was any other vehicle or property damaged? Number of Passengers (Including Driver) 1 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

Translator's name Translator's ID Translator's phone number Translator's email

Original language used in the statement

DETAILS OF POLICE ACTION

Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHED STATEMENT

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera? Yes Yes

02/06/1982

Male

#09-162

550310

Yes

No

Clear

Dry

40 YEARS AND 6 MONTHS

(Phone) +65-90119717

OWCK303@GMAIL.COM

Collision - Head to Rear

BLK 310 SERANGOON AVENUE 2

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number Vehicle Manufacturer

Vehicle Model

Vehicle Variant Vehicle Colour

Vehicle Category

Name of Driver Contact Number SKG4482Z

Private car

(Phone) +65-96536695

Address	177
Address complement	-
Postcode	-
Insurance Company Name	(-)
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SECTORISAN

IMPORTANT NODE

- 1. Please report threetly the details of the arcident to spend up the claims process.
- 2. This I am must be completed by the Policyholder and/or the Authorisid Driver
- Information provided most be as truthful and accurate as possible. Any wiful misrepresentation in extribiolding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be locusated by the insurers of the GIA Raccads Management Centre established by the General insurance
- By the ludgment of this report to the insurers, you kendby consent to the archiving of this report at the centre and to copies of the report being made evaluable aforesaid.
- Consent under the Personal Data Protection Act (PDPA) | Lucderstand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (callectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident fall insurer(s) who have insured vehicle(s) awaived in this accident shall be collectively referred to as the "lesseers"), the insurers lay/yers/law tirms, the Monetary Authority of Singapore and any relevant government againsy/authority (such as the police), for the nureasets) of t
 - (i) upoccessing, hamfling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me:
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me. which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this actident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes;
 - my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of
 - (d) my Personal information will also be collected and used to compile claims history for the purpose of traud detection. investigation and management in present and all future claims.
 - [e] the information so collected under (d) above may be shared / disclosed:
 - (ii) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.


Origer's Signature-(if driver is not the policyholder) Date & Time:

NAMES A RESIDENCE

4

vehicle Number: SF6 2361 L

SKETCHPLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

	On 9 12/2022 at about 1pm. I was thinky along
Ü.c.1	tley pour Fost towards Abjort Roads
	Wear the stip road to turn lett. I starbuary
-te	theck in country vehicle to from my Eget side
	Suchdanting the victicle B was colleted disto the back
34	may car.
N.	
1.5	Vivo de clare the foregoing particulars are true in every respect.

Down's Signature (if driver is not the policylinider)