

JDM AUTOCARE

BLK 1 KAKI BUKIT AVENUE 6, #01-51, AutoBay@Kaki Bukit Singapore 417883
UEN NO : 53060650W

DATE : 08/12/2022

VEHICLE NO : SLS2091G MAZDA 6 2.5

ITEMS	QTY	Amount
1 FRONT BUMPER <i>new</i>	1	\$1,211.90 <i>+</i>
2 RH FRONT HEADLAMP <i>2x</i>	1	\$3,369.80 <i>2</i>
3 RH FRONT BUMPER SIDE RETAINER <i>new</i>	1	\$17.10 <i>+</i>
4 RH FRONT FENDER <i>Dented</i>	1	\$383.70 <i>✓</i>
5 RH FRONT FENDER INNER COWLING <i>Def Not new</i>	1	\$114.30 <i>+</i>
6 RH FRONT DOOR <i>Dented</i>	1	\$975.20 <i>✓</i>
7 RH FRONT DOOR HINGE @\$37.80 <i>new</i>	1	\$75.60 <i>+</i>
8 RH FRONT DOOR CHECKER <i>Not new</i>	1	\$65.70 <i>+</i>
9 RH FRONT DOOR STICKER <i>new</i>	1	\$15.50 <i>✓</i>
10 RH FRONT DOOR OUTER HANDLER <i>Not new</i>	1	\$224.60 <i>+</i>
11 RH FRONT DOOR POWER WINDOW REGULATOR GEAR <i>new</i>	1	\$266.70 <i>+</i>
12 RH FRONT DOOR POWER WINDOW MOTOR <i>Not new</i>	1	\$316.70 <i>+</i>
13 RH FRONT DOOR GLASS INNER RUBBER <i>Not new</i>	1	\$155.80 <i>+</i>
14 RH FRONT MIRROR <i>Dented</i>	1	\$475.90 <i>✓</i>
15 RH FRONT MIRROR COVER <i>at</i>	1	\$111.30 <i>✓</i>
16 RH REAR DOOR <i>Dented</i>	1	\$1,312.10 <i>✓</i>
17 RH REAR DOOR HINGE @\$37.80 <i>new</i>	1	\$75.60 <i>+</i>
18 RH REAR DOOR CHECKER <i>Not new</i>	1	\$65.70 <i>+</i>
19 RH REAR DOOR STICKER <i>new</i>	1	\$15.50 <i>✓</i>
20 RH REAR DOOR OUTER HANDLER <i>Not new</i>	1	\$224.60 <i>+</i>
21 RH REAR DOOR POWER WINDOW REGULATOR GEAR <i>Dented</i>	1	\$266.70 <i>2</i>
22 RH REAR DOOR POWER WINDOW MOTOR <i>Not new</i>	1	\$316.70 <i>+</i>
23 RH REAR DOOR GLASS INNER RUBBER <i>Not new</i>	1	\$155.80 <i>+</i>
24 RH FRONT LOWER ARM <i>Best</i>	1	\$503.90 <i>2</i>
25 RH FRONT SHOCK ABSORBER <i>Not new</i>	1	\$392.10 <i>+</i>
26 RH FRONT KNUCKLER ARM <i>Not new</i>	1	\$407.10 <i>+</i>
27 RH FRONT KNUCKLER ARM BEARING <i>Dented</i>	1	\$566.70 <i>+</i>

7996.30
6397.04

DISCOUNT 20%
TOTAL

\$12,082.30

\$2,416.46

\$9,665.84

SPECIAL NETT ITEM

- 1 FRONT BUMPER CLIPS *Not for*
 2 RH FRONT FENDER INNER COWLING CLIPS *new*
 3 RH ROCKER PANEL SIDESKIRT (KENSTYLE) *schnd*
 4 RH FRONT SPORT RIM *lit*
 5 RH FRONT TYRE *lit*

1430

QTY	Amount
1	\$80.00 <i>+</i>
1	\$60.00 <i>-30</i>
1	\$850.00 <i>-650</i>
1	\$950.00 <i>-350</i>
1	\$380.00 <i>-200</i>

\$2,320.00**\$11,985.84****Labour charges**

- 1 TO REMOVE, REINSTALL ALL ELECTRICAL WIRING, LIGHTING
 2 TO SUPPLY LABOUR, WORKMANSHIP TO REMOVE AND REINSTALL AFFECTED AREAS
 3 TO SPRAY PAINT AND RESPRAY ACCIDENT AFFECTED AREAS
 4 TO APPLY TUFF COAT
 5 LABOUR FOR REMOVE & RENEW RH FRONT UNDER CARRIAGE *2170*
 6 TO CONDUCT WHEEL ALIGNMENT
 7 LABOUR FOR REMOVE / REFIT AND TRANSFER RH BOTH DOORS FITTING

\$80.00 <i>-30</i>
\$1,400.00 <i>-800</i>
\$1,200.00 <i>900</i>
\$300.00 <i>-50</i>
\$400.00 <i>-150</i>
\$150.00 <i>-80</i>
\$400.00 <i>-160</i>

\$3,930.00**\$15,915.84**

Adrian Lj
H/S 13/12/22

07 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*total: 9997.04**L/S: 8K.*