

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS22012405/TNY3M4**Date:** 09/05/2023**REFERENCE**

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : FBJ5942Y **Insured Vehicle No :** SLH3410X

Date of Loss: 29/11/2022 Nature of Claim: TP Claim No: DMPC2200599H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBJ5942Y**

Make & Model: KYMCO XCITING 400I, 399cc Engine No: SK803300136

Reg. Date: 01/08/2014 (Man. Year: 2014) Chassis No: RFBD60010E3300127

Colour: Orange Odometer: 0 km

Engine Capacity: 399 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70R15 Rear Tyre Size: 150/70R15

Front Left Side: Maxxis 5 mm Rear Left Side: Maxxis 5 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,973.00	2,540.70	432.30	14.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	790.00	610.00	180.00	22.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,763.00	3,150.70	612.30	16.27
+ GST 8.00/8.00% (S\$)	301.04	252.06	48.98	16.27
Nett Amount (S\$)	4,064.04	3,402.76	661.28	16.27

INSPECTION

Date of Assignment: 12/12/2022

Date Inspected: 13/12/2022 Inspected At: Motor Sport Pte Ltd - Ubi (HQ)
BLK 3007 UBI ROAD 1 #01-446
Singapore 408701

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 09 May 2023)	
Parts:	N/A	KYMCO XCITING 400I 399cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBJ5942Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT COVER	Cut	253.00 F	*253.00 FL
2	1		*FRONT LH HEADLAMP COMPLETE	Cut	412.00 F	*412.00 FL
3	1		*HANDLE BAR	Bent	94.00 F	*94.00 FL
4	1		*LH BRAKE LEVER	Cut	33.00 F	*33.00 FL
5	1		*LH MIRROR	Cut	126.00 F	*126.00 FL
6	1		*LH BAR END	Cut	14.00 F	*14.00 FL
7	1		*LH SIDE SKIRT TOP	Cut	85.00 F	*85.00 FL
8	1		*LH SIDE SKIRT BOTTOM	Cut	134.00 F	*134.00 FL
9	1		*LH SIDE SKIRT REAR	Cut	122.00 F	*122.00 FL
10	1		*FRONT FENDER	Cracked	108.00 F	*108.00 FL
11	1		*LEG SHIELD	Cut	103.00 F	*103.00 FL
12	1		*RH SIDE COVER	Cracked	279.00 F	*279.00 FL
13	1		*LH SIDE COVER	Cut	279.00 F	*279.00 FL
14	1		*LH REAR HOLDER	Distorted	152.00 F	*152.00 FL
15	1		*LH ENGINE COVER	Cracked	117.00 F	*117.00 FL
16	1		*LH ENGINE COVER GRILL	Cracked	30.00 F	*30.00 FL
17	1		*AIR FILTER COVER	Cracked	53.00 F	*53.00 FL
18	1		*LH WINKER LAMP (LED)	Cut	184.00 F	*184.00 FL
19	1		*METER COVER	Cut	35.00 F	*35.00 FL
20	1		*REAR TOP BOX	Cut	210.00 F	*210.00 FL
21	1		*RH BRAKE LEVER	Not Necessary	45.00 F	*- FL
22	1		*LH FLOOR PANEL	Not Necessary	58.00 F	*- FL
23	1		*SKIRT L SIDE	Not Necessary	33.00 F	*- FL
24	7		*CLIP PLASTIC	Not Necessary	14.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,973.00	2,823.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	282.30
Total Parts (\$\$)	2,973.00	2,540.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING	New	450.00	350.00
2	TOWING	New	60.00	60.00
3	LABOR	New	280.00	200.00
Gross Labour Cost (S\$)			790.00	610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >