



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)

Ref: CS3/SPF22012407/Gvy3e2

ACCIDENT CLAIMS SECTION (SPORE POLICE
FORCE) POLICE LOGISTICS BASE (PLB) 1
HEMMANT ROADSINGAPORE 438675

Date: 27/02/2023

ATTN: HAFIZUL FARHAN

Code: SPF

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	QX 1209G	Veh. Inspected	SLQ 3540G
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2022/110	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	12/12/2022

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL HYBRID	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	RU31249576	Colour	WHITE
Odometer	85079 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R18	BRIDGESTONE	6 mm
L/H Front Tyre	225/45 R18	BRIDGESTONE	6 mm
R/H Rear Tyre	225/45 R18	NEXEN	5 mm
L/H Rear Tyre	225/45 R18	NEXEN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/12/2022	Inspect Date / Time	13/12/2022 (06:25 PM)
Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------