

1

of 2 ?

<

>

↺

↻

100%

▼

📄

🖨

Find | Next

LKK

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CS3/SMO21011930/Kny3-1

SOMPO INSURANCE SINGAPORE PL

50 RAFFLES PLACE #03-03

SINGAPORE LAND TOWERSINGAPORE 048623

Ref: ~~CS3/SMO21011930/Kny3-1~~

Date: ~~24/11/2021~~ 08/12/2022

Code: SMO

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	GBH 7600G	Veh. Inspected	CB 6361Y
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2103464/THE	Excess (\$)	0.00
Assign From	GRACE TEO THELMA CHOO	Assign Date	24/11/2021 08/12/2022

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	23/11/2021	Inspection Date	24/11/2021
Survey held at	EM SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--