

DATE : 12.12.2022

TO : India International
VEHICLE NO : SMU 6168X
MODEL : HONDA CIVIC
DATE OF ACCIDENT : 09.12.2022
CHASSIS : MRHFC5650LT000010
DATE OF ACCIDENT : 11.01.20

Xiao Tony

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>3 new</i>	1	\$ 792.50	\$ 792.50
2	FRONT BUMPER FOGLAMP <i>1 new</i>	1	\$ 273.30	\$ 273.30
3	FRONT BUMPER FOGLAMP COVER GARNISH <i>1 new</i>	1	\$ 65.80	\$ 65.80
4	FRONT BUMPER TOP RUBBER <i>2</i>	1	\$ 138.20	\$ 138.20
5	FRONT BUMPER TOP BEAM <i>1 new</i>	1	\$ 169.20	\$ 169.20
6	FRONT BUMPER REINFORCEMENT <i>1 new</i>	1	\$ 425.80	\$ 425.80
7	FRONT BUMPER RETAINER <i>1</i>	1	\$ 65.80	\$ 65.80
8	FRONT FENDER <i>Dented</i>	1	\$ 536.90	\$ 536.90
9	FRONT FENDER SIGNAL LAMP <i>3 new</i>	1	\$ 89.60	\$ 89.60
10	FRONT FENDER INNER SPONGE <i>1 new</i>	1	\$ 95.20	\$ 95.20
11	FRONT FENDER COWLING <i>1 new</i>	1	\$ 156.30	\$ 156.30
12	HEADLAMP (LED) <i>1 new</i>	1	\$ 894.90	\$ 894.90
13	HEADLAMP LOWER BRACKET <i>1 new</i>	1	\$ 69.20	\$ 69.20
14	HEADLAMP TOP GARNISH (CHROME) <i>1 new</i>	1	\$ 144.20	\$ 144.20
15	BONNET <i>1 new</i>	1	\$ 658.90	\$ 658.90
16	BONNET HINGE <i>1 new</i>	1	\$ 84.20	\$ 84.20
17	BONNET STOPPER <i>3 new</i>	1	\$ 25.00	\$ 25.00
18	FRONT SUPPORT PANEL <i>1 new</i>	1	\$ 597.60	\$ 597.60
19	FRONT DOOR PILLAR (OUTER) <i>1</i>	1	\$ 879.40	\$ 879.40
20	FRONT DOOR SIDE MIRROR RH <i>1</i>	1	\$ 1,264.50	\$ 1,264.50
21	FRONT DOOR <i>Dented</i>	1	\$ 1,694.80	\$ 1,694.80
22	FRONT DOOR OUTER HANDLE <i>1 new</i>	1	\$ 277.60	\$ 277.60
23	FRONT DOOR KEY LOCK LH <i>1 new</i>	1	\$ 169.40	\$ 169.40
24	FRONT DOOR STOPPER <i>3 new</i>	2	\$ 25.00	\$ 50.00
25	FRONT DOOR TOP MOULDING <i>1 new</i>	1	\$ 145.20	\$ 145.20
26	FRONT DOOR HINGE LH <i>2 new</i>	2	\$ 52.70	\$ 105.40
27	FRONT DOOR CHECKER LH <i>1 new</i>	1	\$ 98.40	\$ 98.40
28	FRONT DOOR SPEAKER LH <i>1</i>	1	\$ 196.30	\$ 196.30
29	FRONT DOOR GLASS SIDE GARNISH LH <i>1 new</i>	1	\$ 110.70	\$ 110.70

640
895

TO : India International
 VEHICLE NO : SMU 6168X
 MODEL : HONDA CIVIC
 DATE OF ACCIDENT : 09.12.2022
 CHASSIS : MRHFC5650LT000010
 DATE OF ACCIDENT : 11.01.20

30	FRONT DOOR WIRE HARNESS LH <i>new</i>	1	\$ 471.40	\$ 471.40	+
31	FRONT DOOR INNER TRIM LH <i>cluded</i>	1	\$ 498.10	\$ 498.10	✓
32	FRONT DOOR SWITCH BUTTOM PANEL <i>new</i>	1	\$ 597.40	\$ 597.40	+
33	FRONT DOOR INNER LOCK LH <i>new</i>	1	\$ 299.10	\$ 299.10	+
34	FRONT DOOR LOCK CATCH LH <i>new</i>	1	\$ 38.20	\$ 38.20	+
35	FRONT DOOR WEATHER STRIP LH <i>2nd</i>	1	\$ 158.20	\$ 158.20	✓
36	FRONT DOOR OUTER STRIP LH <i>new</i>	1	\$ 135.80	\$ 135.80	+
37	FRONT DOOR LOWER INNER RUBBER LH <i>new</i>	1	\$ 59.60	\$ 59.60	+
38	FRONT DOOR GLASS CHANNEL LH <i>new</i>	1	\$ 85.30	\$ 85.30	+
39	SIDE SKIRT <i>new</i>	1	\$ 485.20	\$ 485.20	+
40	SIDE MIRROR <i>Replaced</i>	1	\$ 589.60	\$ 589.60	+
41	FRONT WHEEL SPORT RIM LH <i>lit</i>	1	\$ 985.74	\$ 985.74	680/sr
42	FRONT SHOCK ABSORBER LH <i>new</i>	1	\$ 385.60	\$ 385.60	+
43	FRONT KNUCKLE ARM LH <i>2nd</i>	1	\$ 398.50	\$ 398.50	✓
44	FRONT LOWER ARM LH <i>Best</i>	1	\$ 439.30	\$ 439.30	291
45	FRONT WHEEL HUP BEARING LH <i>2nd</i>	1	\$ 425.30	\$ 425.30	285

3859

TOTAL PRICE \$ 16,326.64

3087.20

LESS 20% \$ 3,265.33

SUB TOTAL PRICE \$ 13,061.31

S.N: 680

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT BUMPER CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	+
2	FRONT FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	+
3	FRONT GRILLE CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	+
4	FRONT SUPPORT PANEL SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	+
5	SIDE SKIRT CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
6	FRONT TYRE LH <i>new</i>	1	\$ 250.00	\$ 250.00	+

TOTAL \$ 500.00

30

TO : India International
VEHICLE NO : SMU 6168X
MODEL : HONDA CIVIC
DATE OF ACCIDENT : 09.12.2022
CHASSIS : MRHFC5650LT000010
DATE OF ACCIDENT : 11.01.20

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	500
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,800.00	500
3	WIRING CHECK ON HEADLAMP	\$ 80.00	x
4	TRANSFER FRONT DOOR MECHANISM	\$ 80.00	✓
5	FOUR WHEEL ALIGNMENT	\$ 120.00	80
6	TO REMOVE/ INSTALL FRONT UNDERCARRIAGE	\$ 180.00	✓
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x
TOTAL		\$ 4,240.00	

ESTIMATE REPORT

TOTAL PARTS COST : \$ 13,561.31
TOTAL LABOUR COST : \$ 4,240.00
TOTAL REPAIR COST : \$ 17,801.31

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L

4/s 13/12/22

05 hrs

Total 5137.20

4/s 4.1K

4.1K

1340