



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: KHOR SAW THENG		Ref: CS/ASM22012426/Kqp3e2 Date: 27/03/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 3832K	Veh. Inspected	SLN 9445A
Policy No.	VFX/P2419138	Coverage (\$)	0.00
Claim No.	S2M04G9S	Excess (\$)	0.00
Assign From	KHOR SAW THENG	Assign Date	12/12/2022
2. Vehicle Particulars & Condition			
Make & Model	HONDA JAZZ (A)	c.c	1318
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JHMGK3850HX200350	Colour	METALLIC GREY
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	175/65 R15	YOKOHAMA	8 mm
L/H Front Tyre	175/65 R15	YOKOHAMA	8 mm
R/H Rear Tyre	175/65 R15	YOKOHAMA	8 mm
L/H Rear Tyre	175/65 R15	YOKOHAMA	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR, FRONT N/S PORTION AND FRONT WINDSCREEN CRACKED. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	08/12/2022	Inspection Date	12/12/2022
Survey held at	EM SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		16 Working Days	