

ASS. REQ. BY:

REF:

ASM / 220124261/KCP3

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

1.5 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLN 9445A

Yr Regn:

05, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda

Jazz

c.c

1318

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JHMGK3850HX 200350

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

175/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

Battery flat, Tailgate & Bonnet jammed
EM not ready

7/3

11 Pm @ 17,800. Cncl 16/3/23 (Red & 24922.70, 58%)

Date/Time, File Pass to?

☐

: Prell. Report

1) 7/3 typist

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

16

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format:

Smart Claims - TP

Lump Sum / I.B.L. (\$

17800

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

755F

Vehicle Details

Vehicle No.:

SLN9445A

Vehicle to be Exported:

No

Intended Deregistration Date:

10 Dec 2022

Vehicle Make:

HONDA

Vehicle Model:

JAZZ 1.3 CVT ABS D/AIRBAG 2WD

Primary Colour:

Silver

Manufacturing Year:

2016

Engine No.:

L13B11020260

Chassis No.:

JHMGK3850HX200350

Maximum Power Output:

73.0 kW (97 bhp)

Open Market Value:

\$16,707.00

Original Registration Date:

23 May 2017

First Registration Date:

23 May 2017

Transfer Count:

0

Actual ARF Paid:

\$11,707.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

22 May 2027

PARF Rebate Amount:

\$8,194.00

Intended COE Rebate Details

COE Expiry Date:

22 May 2027

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$51,600.00

COE Rebate Amount:

\$22,956.00

Total Rebate Amount:

\$31,150.00

The information contained herein is correct as at 09 Dec 2022

OK

EM Solution Pte Ltd

160 Sin Ming Drive, (Sin Ming Autocity), #03-18/19, Singapore 575722

H/P: 9004 2254 (Derek Keh) Tel: 6456 0226 Fax: 6458 4500

Email: emautosolution@singnet.com.sg

Not Authorized
11 May 817, 800h
Recovery After Rainy
16 days

Vehicle number: SLN9445A

Vehicle Made & Model: HONDA JAZZ

Qty	List Items	Amount \$
1	Tailgate 910	Pr 931.60 ✓
1	Tailgate glass 810.50	Shorten 899.50 ✓
1 set	Tailgate glass moulding	Me 121.30 ✓
1	Tailgate wiper arm	In 86.90 X
1	Tailgate wiper motor	Tm 431.20 ✓
1	Tailgate outer garnish	Wap 282.60 ✓
1	Tailgate outer handle	In 48.60 X
2	Tailgate licence lamps @ 42.20	In 84.40 X
1	Tailgate logo	Me 48.20 —
1	Tailgate emblem "JAZZ"	Me 68.60 —
2	Tailgate lamps - L/R @ 281.60	CM 563.20 ✓
1	Tailgate inner lock	Tm 280.90 ✓
1	Tailgate inner trim board 288.90	Bu 381.90 —
1	Tailgate lock striker	R 41.20 X
1	Tailgate w/strip	na/CM 196.90 502 In 98.45 In
2	Tailgate dampers @ 141.20	Pr 282.40 ✓
2	Tailgate hinges @ 68.50	R 137.00 X
1	Tailgate inner pull pocket	In 69.60 X
2	Tailgate stoppers @ 12.60	In 25.20 X
2	Taillamps - L/R @ 441.50 c372.80	CM 883.00 ✓
2	Taillamp panels - L/R @ 211.60 c176.20	Pr 423.20 ✓
4	Taillamp side clips @ 8.50	Me 34.00 —
1	Rear bumper 535	Pr 712.20 —
2	Rear bumper side cover	In 89.60 X
42	Rear bumper PDC sensors @ 283.60 c230.20	Short 1,134.40 LTT
1	Rear bumper PDC sensor wire harness	Pr 241.60 X
2	Rear bumper side retainers - L/R @ 58.60	Pr 117.20 ✓
1	Rear end panel 355	Pr 483.90 ✓
1	Rear end panel garnish	Pr 155.60 ✓
1	Rear exhaust silencer	Pr 571.60 ✓

Vehicle number: SLN9445A

Vehicle Made & Model: HONDA JAZZ

1	Rear exhaust insulator		DL	120.30	✓
4	Rear exhaust mountings @ 18.90		Sn	75.60	X
1	Rear exhaust CTR pipe		R	590.60	X
1	Rear floor board 315.30		Deform	391.60	✓
1	Rear floor tool tray		CM	291.60	—
1	Rear floor compartment panel 781.90		BT/Rn	796.30	—
2	Rear fenders - L/R @ 891.60	NLSN	o/s Bu	1,783.20	LT
2	Rear fender glass mouldings - L/R @ 86.90	NLSN	o/s Bu	173.80	LT
2	Rear fender inner top trims - L/R @ 211.40	Sn	Ag Bu	422.80	X
2	Rear fender inner trim boards - L/R @ 485.90	0185.40	mg CM	971.80	✓
1	Rear smart keyless antenna		Sn	192.60	X
1	Rear smart keyless buzzer		Sn	181.60	X
1	Rear side chassis member - RH		R	516.90	X
2	Rear shock absorbers - L/R @ 280.60		Sn	561.20	X
1	Rear speaker board		Sn	580.90	X
1	Front bonnet 633		Bu	720.60	✓
1	Front bonnet lock cable		De	89.60	X
1	Front bonnet lock		Di	131.80	✓
1	Front bonnet seal - CTR		Sn	61.50	X
1	Front bonnet seals - L/R @ 48.60		NLSN	97.20	LT
1	Front bonnet insulator		Sn	120.60	X
8	Front bonnet insulator clips @ 5.50		Nn	44.00	X
2	Front bonnet hinges - L/R @ 58.60		NLSN	117.20	LT
1	Front bumper 538		Bu	723.50	✓
1	Front bumper lower grille		Sn	221.30	X
1	Front bumper side grille - LH		Sn	81.50	X
2	Front bumper beams - L/R @ 68.80		NLSN	137.60	LT
1	Front bumper reinforcement		R	395.60	X
2	Front bumper side retainers - L/R @ 42.20		NLSN	84.40	LT
1	Front fender - LH		Bu	484.60	✓
1	Front fender undercover - LH		Sn	141.20	X
1	Front fender wheel housing - LH		R	681.50	X
1	Front fender inner apron panel		Bu	481.60	✓
1	Front grille		CM	361.90	—
1	Front grille logo		Nn	54.60	—
1	Front grille moulding		Sn	110.20	X
2	Front headlamps - L/R @ 1140.90	NLSN Bu @ 585.90		2,281.80	LT

Vehicle number: SLN9445A

Vehicle Made & Model: HONDA JAZZ

2	Front headlamp lower brackets @ 48.60	NLS CM	97.20	✓
1	Front licence plate garnish	Pr	86.90	X
1	Front support panel	Pr	571.60	✓
1	Front support top garnish	Pr	121.20	X
1	Front shock absorber - LH	Pr	421.20	X
1	Front lower arm	Pr	370.60	X
1	Front knuckle arm	Pr	381.90	X
1	Front wheel bearing	NLS	192.60	X
1	Front side chassis frame member - LH	Pr	591.90	X
1	Front wiper panel garnish	Pr	281.90	X
1	Front windscreen	CM	1,481.50	✓
1	Front windscreen moulding	Pr	121.60	✓
1	Front pillar 1/4 glass - LH	CM	280.60	✓
1	Front pillar 1/4 glass moulding	Pr	81.50	✓
1	Air con condenser	Pr	790.60	✓
1	Air cleaner intake duct	Pr	110.20	X
1	Air cleaner box assy	CM	341.50	✓
1	Air cleaner resonator	CM	121.30	✓
1	Radiator assy 1348-20	71/Pr	1,407.80	✓
1	Radiator fan assy	CM	481.90	✓
1	Radiator spare tank	Pr	86.90	✓
1	Battery tray	Pr	89.90	X
1	E.C.U control unit	Pr	1,895.90	X
1	Engine mounting - RH	Pr	291.60	X
1	Engine mounting - LH	Pr	261.90	X
1	Engine mounting - Rear	Pr	210.50	X
1	Main fuse box assy	Pr	491.60	X
1 set	Main fuse box wire harness	Pr	1,695.60	X
Sub-total			38,461.50	
Less 20%			7,692.30	
Total List			30,769.20	

Vehicle number: SLN9445A

Vehicle Made & Model: HONDA JAZZ

Special Nett Items

1 set Tailgate glass sealant
1 Tailgate glass foam tape
1 Tailgate glass solar film
1 Rear recorder camera
1 Rear reverse camera
1 set Rear bumper clip
1 set Rear no. plate with holder
1 set Rear passenger leather seat cover
1 set Rear fender glass sealant
1 set Front bumper clip
1 set Front fender inner shield clip
1 set Front windscreen sealant
1 set Front windscreen foam tape
1 Front windscreen solar film
1 set Front pillar 1/4 glass sealant
1 Battery
1 bot A/C oil
1 Front tyre - LH
1 I.U bracket
1 bot Radiator coolant

Mr	80.00	405N
Mr	65.00	305N
Mr	280.00	X
Sn	550.00	X
Mr	450.00	300N
Mr	35.00	—
Mr	60.00	455N
Sn	800.00	X
Mr	80.00	405N
Mr	45.00	—
Mr	45.00	X
Mr	80.00	405N
Mr	65.00	305N
Mr	280.00	X
Mr	60.00	305N
Sn	300.00	X
Sn	65.00	X
Sn	200.00	X
Mr	28.00	265N
Mr	65.00	305N

Total Special Nett 3,633.00

Vehicle number: SLN9445A

Vehicle Made & Model: HONDA JAZZ

Labour charges

To check front and rear electrical wiring	100.00	40%
To remove, refix tailgate glass / fender glass	450.00	160%
To vacuum, eaxing & cleaning interior	180.00	60%
Transfer and refix tailgate components to new tailgate	150.00	60%
To remove, refix rear interior trims to assist repair	120.00	✓
To remove, refix rear exhaust systems	180.00	60%
To remove, refix A/C condenser & refill A/C gas	120.00	100%
To remove, refix front windscreen / pillar glass	300.00	180%
To remove, refix front undercarriage	~ 250.00	X
To check wheel alignment	~ 120.00	X
Reinstall, remove & refix main fuse box / wire harness	~ 450.00	X
To respray undercoating	200.00	180%
To respray painting and etc	2,200.00	200%
Panel beating, cut, weld remove & replacing above parts	3,500.00	280%
Total Labour	8,320.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 42,722.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: