



HH MOTOR TRADING

BLOCK 3012, BEDOK NORTH AVE 4, #01-2054,
BEDOK INDUSTRIAL PARK E, SINGAPORE 489978
TEL & FAX: 6445 2934 H/P: 8161 6988
Co. Reg. No. 53122819C

X/a/y

Vehicle No : SLQ 824H	Accident Date : 9/12/22
Mileage :	make / Model : RUI-122/423
	CHASSIS : H/vezel
Date :	Fax NO. : 6445 2934

Items		1100
1	Tail gate <i>Dented</i>	✓ \$1193.40
2	Tail gate logo "H" <i>new</i>	+ \$36.30
3	Tail gate logo "Vezel" <i>new</i>	✓ \$39.40
4	Tail gate weatherstrip <i>at</i>	✓ \$175.40
5	Tail gate lock assembly <i>Dented</i>	✓ \$139.10
6	Tail gate lock catch <i>new</i>	+ \$75.20
7	Tail gate trim board new <i>Damage</i>	✓ \$329.10
8	Tail gate trim board clips <i>new</i>	✓ \$40.00
9	Rear End panel <i>Repair</i>	f \$408.70
10	End panel top garnish <i>Rehd</i>	✓ \$254.90
	Rear Bumper <i>Rehd</i>	✓ \$462.50
	Rear Bumper Clips (1 set) <i>new</i>	✓ \$40.00
	Rear Bumper Lower Garnish <i>Rehd</i>	✓ \$285.10
	Rear Bumper Reflector LH <i>new</i>	✓ \$46.00
	Rear Bumper Reflector RH <i>Rehd</i>	✓ \$46.00
	Rear Bumper Reinforcement Beam <i>new</i>	+ \$428.30
	Rear Bumper Side Retainer LH <i>Rehd</i>	✓ \$36.20
	Rear Bumper Side Retainer RH <i>Rehd</i>	✓ \$36.20
	Rear Bumper Bracket LH <i>new</i>	+ \$42.30
	Rear Bumper Bracket RH <i>new</i>	+ \$42.30
	Exhaust Pipe & Box <i>new</i>	+ \$1038.10
	Rear Fender RH inner Garnish <i>new</i>	+ \$262.10
	Rear Fender LH inner Garnish <i>new</i>	+ \$262.10
	Rear Spare tyre board <i>new</i>	+ \$148.20
	Rear Windscreen moulding <i>new</i>	✓ \$180.10
3164		
2531.20.		



HH MOTOR TRADING

BLOCK 3012, BEDOK NORTH AVE 4, #01-2054, SINGAPORE 489978
TEL & FAX: 6445 2934 H/P: 8161 6988
Co. Reg. No. 53122819C

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: *Damaged*
Date: *20/12/22*

20/12/22
20/12/22
20/12/22
20/12/22

Special Net Items

Reverse sensor (1set)

Rear number plate & Casing

Rear windscreen sealant

20/12/22
20/12/22
20/12/22

S.N: 260

To remove & install rear view camera

To remove & install new reverse sensors.

Rewiring to facilitate works.

Transfer of bootlid components

To carry out Anti-rust treatment

To remove & install Exhaust pipe & box

To remove & refit all trims, upholders, garnish, & necessary parts to facilitate repairs.

Labour to remove & replace damaged parts (including refitting & repositioning of replaced parts)

Spray painting materials & respray of replaced & affected parts necessary for paintwork.

Estimated no. of days for repairs & respray

6 days

Total: A\$711.20

A/S: 3.4K

04 Days

Adrian King
H/S 12/12/22
96893735