

Company Reg No: 202136905K

Tel : 6341 6789 Fax: 6341 6778
E-mail: jlperfectautowork@gmail.com



DATE : 28.12.2022

TO : **CHINA TAIPING** MOTOR CLAIMS DEPTS
VEHICLE NO : **SKU6117S**
MODEL : **TOYOTA HARRIER**
DATE OF ACCIDENT : 07.12.2022
TIME OF ACCIDENT : 18:15 HRS

Xiao Chan.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

CLAIM DETAIL : PARTS				
S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Del'd</i>	1	\$ 1,480.10	\$ 1,480.10
2	FRONT BUMPER FOG LAMP <i>Not in</i>	2	\$ 359.10	\$ 718.20
3	FRONT BUMPER FOG LAMP COVER <i>cracked RH</i>	2	\$ 110.10	\$ 220.20
4	FRONT BUMPER LOWER LIP <i>Not in</i>	1	\$ 378.10	\$ 378.10
5	FRONT BUMPER CENTER BEAM <i>Bent</i>	1	\$ 276.10	\$ 276.10
6	FRONT BUMPER SIDE BEAM RH <i>Not in</i>	1	\$ 59.40	\$ 59.40
7	FRONT BUMPER SIDE SPONGE RH. <i>cracked</i>	1	\$ 108.60	\$ 108.60
8	FRONT BUMPER LOWER GRILLE <i>Del'd</i>	1	\$ 365.00	\$ 365.00
9	FRONT BUMPER BOTTOM GARNISH <i>Not in</i>	1	\$ 187.10	\$ 187.10
10	FRONT BUMPER TOWING HOOD <i>Del'd</i>	2	\$ 38.10	\$ 76.20
11	FRONT BUMPER SIDE RETAINER <i>Not in</i>	2	\$ 98.10	\$ 196.20
12	FRONT BUMPER REINFORCEMENT <i>Not in</i>	1	\$ 490.60	\$ 490.60
13	FRONT BUMPER REINFORCEMENT CENTER SPONGE <i>cracked</i>	1	\$ 142.30	\$ 142.30
14	HEADLAMP HID <i>RH cracked</i>	2	\$ 3,530.10	\$ 7,060.20
15	HEADLAMP LOWER BRACKET <i>Not in</i>	2	\$ 51.10	\$ 102.20
16	HEADLAMP LOWER BRACKET SPONGE <i>Not in</i>	2	\$ 108.60	\$ 217.20
17	FRONT FENDER RH <i>Repair</i>	1	\$ 972.50	\$ 972.50
18	FRONT FENDER QUARTER COVER <i>Not in</i>	2	\$ 118.30	\$ 236.60
19	FRONT FENDER COWLING RH <i>Not in</i>	1	\$ 421.10	\$ 421.10
20	CENTER GRILLE <i>cracked</i>	1	\$ 986.30	\$ 986.30
21	FRONT SUPPORT PANEL TOP GARNISH <i>Not in</i>	1	\$ 336.70	\$ 336.70

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SKU6117S
 MODEL : TOYOTA HARRIER
 DATE OF ACCIDENT : 07.12.2022
 TIME OF ACCIDENT : 18:15 HRS

22	FRONT SUPPORT PANEL <i>2nd</i>	1	\$ 796.80	\$ 796.80	<i>+</i>
23	FRONT BRACE PANEL <i>1st</i>	1	\$ 247.70	\$ 247.70	<i>+</i>

6536.40
4802.30

TOTAL PRICE \$ 16,075.40
 LESS 25% \$ 4,018.85
 SUB TOTAL PRICE \$ 12,056.55

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE <i>2nd</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
2	FRONT BUMPER CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00	<i>30</i>
3	FRONT BUMPER BOTTOM GARNISH CLIP (SET) <i>New</i>	1	\$ 30.00	\$ 30.00	<i>+</i>
4	FRONT BUMPER LOWER GRILLE CLIP (SET) <i>New</i>	1	\$ 30.00	\$ 30.00	<i>20</i>
5	FRONT BUMPER LOWER SPOILER (MODELLISTA) <i>cracked</i>	1	\$ 2,800.00	\$ 2,800.00	<i>1600</i>
6	FRONT FENDER COWLING CLIP (SET) <i>New</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
7	FRONT PANEL BOTTOM COVER GARNISH CLIP (SET) <i>New</i>	1	\$ 30.00	\$ 30.00	<i>+</i>
8	RADIATOR GRILLE CLIP (SET) <i>New</i>	1	\$ 30.00	\$ 30.00	<i>✓</i>
9	AIR GUARD GARNISH CLIP (SET) <i>New</i>	1	\$ 40.00	\$ 40.00	<i>+</i>
10	FRONT SUPPORT PANEL TOP GARNISH CLIP (SET) <i>New</i>	1	\$ 30.00	\$ 30.00	<i>+</i>
11	FRONT PANEL BOTTOM COVER GARNISH CLIP (SET) <i>New</i>	1	\$ 30.00	\$ 30.00	<i>+</i>

TOTAL \$ 3,180.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,400.00	<i>400</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,000.00	<i>500</i>
3	REFOCUS HEADLAMP BEAM	\$ 80.00	<i>* 30</i>
4	REMOVE AND REFIX AIRCON COMPRESSOR AND REFILL GAS	\$ 180.00	<i>X</i>
5	REMOVE AND REFIX AIRCON CONDENSOR	\$ 120.00	<i>X</i>

TO : **CHINA TAIPING** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SKU6117S**
 MODEL : **TOYOTA HARRIER**
 DATE OF ACCIDENT : 07.12.2022
 TIME OF ACCIDENT : 18:15 HRS

6	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	X
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

930.

TOTAL 3040

ESTIMATE REPORT

TOTAL PARTS COST : \$ 15,236.55
 TOTAL LABOUR COST : 3040
 TOTAL REPAIR COST : \$ 18,276.55

Adrian L.
 L/S 28/12/22.
 04 Days.

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
 CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
 ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

total: 7512.30

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

L/S: 6K

6K

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: