

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22012437/RQP3E2**Date:** 21/12/2022REFERENCE

Insured/Claimant:	FENELLA TANG OI YOKE	Policy No:	1900171773	
Date of Loss:	09/12/2022	Nature of Claim:	OD	Claim No: 5421613368SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCR17Y		
Make & Model:	AUDI A6, 2.0 TFSI (A)	Engine No:	DLH065750
Reg. Date:	29/10/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF20LN014639
Colour:	Blue	Odometer:	54632 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$175,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45Z R19	Rear Tyre Size:	245/45Z R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,102.00	15,669.00	3,433.00	17.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,792.00	4,142.00	3,650.00	46.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	26,894.00	19,811.00	7,083.00	26.34
+ GST 7.00/7.00% (S\$)	1,882.58	1,386.77	495.81	26.34
Nett Amount (S\$)	28,776.58	21,197.77	7,578.81	26.34

INSPECTION

Date of Assignment:	13/12/2022		
Date Inspected:	12/12/2022	Inspected At:	24 Benoi Sector Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$2,815.00 NETT)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR - RH	Bent	4,489.00 FS	*4,489.00 FS
2	1		*FRONT DOOR OUTER SEAL - RH	Necessary	191.00 FS	*191.00 FS
3	1		*FRONT DOOR CATCH - RH	* Check	134.00 FS	*- FS
4	1		*FRONT DOOR OUTER SEAL - RH LOWER	Necessary	213.00 FS	*213.00 FS
5	1		*FRONT DOOR HANDLE CHROME TRIM PLATE - RH	Scratched	109.00 FS	*109.00 FS
6	1		*FRONT DOOR HANDLE SENSOR - RH	* Check	278.00 FS	*- FS
7	1		*FRONT DOOR SLIDE VALVE - RH	* Check	15.00 FS	*- FS
8	1		*FRONT DOOR HANDLE - RH	* Check	389.00 FS	*- FS
9	1		*FRONT DOOR CHROME PANEL CAP - RH UPPER	Missing	100.00 FS	*100.00 FS
10	1		*REAR DOOR UNDERLAY - RH	Necessary	7.00 FS	*7.00 FS
11	1		*FRONT DOOR UNDERLAY - RH	Necessary	6.00 FS	*6.00 FS
12	1		*FRONT DOOR MOUNTING BAR - RH	* Check	145.00 FS	*- FS
13	1		*FRONT DOOR HANDLE EXTERIOR PERIPHERAL LIGHT - RH	* Check	81.00 FS	*- FS
14	1		*FRONT DOOR LOCK CYLINDER - RH	* Check	581.00 FS	*- FS
15	1		*FRONT EXTERIOR WING MIRROR MOUNTING - RH	Cracked	3,069.00 FS	*3,069.00 FS
16	1		*FRONT WING MIRROR GLASS - RH	Cracked	1,752.00 FS	*1,752.00 FS
17	1		*FRONT WING MIRROR CAP - RH	Missing	348.00 FS	*348.00 FS
18	1		*FRONT WINDOW SLOT SEAL CHROME TRIM STRIP - RH OUTER	Scratched	224.00 FS	*224.00 FS
19	1		*REAR DOOR	Bent	4,489.00 FS	*4,489.00 FS
20	1		*REAR DOOR SEAL BRACKET	Not Necessary	169.00 FS	*- FS
21	1		*REAR DOOR WEATHER STRIP - RH	Necessary	191.00 FS	*191.00 FS
22	1		*REAR DOOR SEAL BRACKET - RH	* Check	169.00 FS	*- FS
23	1		*REAR DOOR STONE CHIP PROTECTION FILM - RH	Not Necessary	138.00 FS	*- FS
24	1		*REAR DOOR OUTER SEAL - RH UPPER	Necessary	206.00 FS	*206.00 FS
25	1		*REAR DOOR OUTER SEAL - RH LOWER	Necessary	166.00 FS	*166.00 FS
26	1		*REAR DOOR CATCH - RH	* Check	134.00 FS	*- FS
27	1		*REAR DOOR HANDLE - RH	* Check	389.00 FS	*- FS
28	1		*REAR DOOR HANDLE CHROME TRIM PLATE - RH	Scratched	109.00 FS	*109.00 FS
29	1		*REAR DOOR CHROME PANEL CAP - RH UPPER	Not Necessary	100.00 FS	*- FS
30	1		*REAR WINDOW SLOT SEAL TRIM STRIP - RH OUTER	Not Necessary	211.00 FS	*- FS
31	1		*SUNDRIES	* Check	500.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 19,102.00 15,669.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	800.00	800.00
2	TO DISMANTLE AND RENEW RHS FRONT DOOR AND RHS REAR DOOR. TO REPAIR RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,800.00	1,250.00
3	TO RESPRAY RHS FRONT DOOR, RHS REAR DOOR, RHS REAR FENDER, FUEL FILLER CAP, TWO DOOR HANDLES AND RHS WING MIRROR COVER	New	4,000.00	1,900.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			7,792.00	4,142.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >