

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/01087/2022/EQ
DATE : 6-Dec-22
WIP : 53435

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 6/12/2022

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR CHOCKALINGAM RAMASAMY
ADDRESS : 372 PASIR PANJANG ROAD
#05-16
SINGAPORE 118709
TELEPHONE : HP +65 97967266
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800088209-04
VEHICLE NO : **SMC 9171 K**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFS
MODEL YEAR : 27/7/2018
ENGINE NO : CVK 062620
CHASSIS NO : WAUZZZF50JA104999
MILEAGE : -
DATE IN : 5-Dec-22
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 3-Dec-22
PLACE OF ACCIDENT : AYE TOWARDS CITY, JUST AFTER ALEXANDRA
ROAD EXIT LAMP POST 300

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMC 9171 K

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O-LINER.	S/N \$	900.00	
2	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$	460.00	
3	TO RENEW BOTH 1/4 GLASS TO FACILLITATE FENDER RENEWAL.	S/N \$	700.00	
4	TO REMOVE AND REINSTALL REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$	380.00	
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,700.00	
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,700.00	
TOTAL LABOUR CHARGES		:	\$ 5,840.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMC 9171 K

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO DISMANTLE AND REINSTALL CENTER CONSOLE. RENEW AIRBAG CONTROL UNIT AND BOTH FRONT SEATBELT.	S/N \$	1,900.00	
8	TO REMOVE AND REINSTALL EXHAUST SYSTEM AND REAR SUSPENSION ASSEMBLY. RENEW ACCORDINGLY	S/N \$	3,300.00	
9	TO REMOVE AND REINSTALL FUEL TANK ASSY.	S/N \$	700.00	
10	TO SETUP VEHICLE ON CAR-O-LINER FOR REPAIR.	S/N \$	2,500.00	
11	TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID.	S/N \$	580.00	
12	TO INSTALL SOLAR FILM FOR ALL THE AFFECTED GLASSES.	S/N \$	500.00	
TOTAL LABOUR CHARGES		:	\$ 9,480.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMC 9171 K

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
13	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$	300.00	
14	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. CUT OUT AND WELD BOTH REAR FENDERS, REAR END PANELLING AND SPARE WHEEL HOUSING. TO RE-ALIGN BOTH REAR CHASSISS INTO POSITION. TO REMOVE AND REINSTALL BOTH SILL PANEL TRIMS. RE-ORGANIZE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	21,000.00	
15	TO CARRY OUT STONE CHIP PRIMER WORK ON REAR PANELLING AND SPARE WHEEL HOUSING.	S/N \$	880.00	
16	TO RESPRAY REAR BUMPER, REAR LID, HINGES, BOTH REAR FENDER, BOTH SILL PANEL, BOTH DRAIN PANEL, BOTH ROOF CHANNEL, BOTH DOOR ENTRANCES, END PANELLING, SPARE WHEEL HOUSING AND BOOT FLOOR. TO CARRY OUT STONE CHIP TREATMENT, CAVITY PRESERVATION AND JOINT SEALER WORKS.	\$	12,000.00	
17	TO CARRRY OUT WHEEL ALIGNMENT.	S/N \$	340.00	
18	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$	280.00	
TOTAL LABOUR CHARGES		:	\$ 34,800.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMC 9171 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
19	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 484.00	
TOTAL LABOUR CHARGES		: \$ <u>50,604.00</u>	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMC 9171 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 3,012.00	
2	REAR BUMPER FIXING PARTS	1	\$ 273.00	
3	REAR BUMPER SECURING STRIP	1	\$ 249.00	
4	REAR BUMPER CHROME TRIM	1	\$ 1,139.00	
5	REAR BUMPER REFLECTOR - LH / RH	2	\$ 92.00	
6	REAR LICENCE PLATE LIGHT - LH / RH	2	\$ 113.00	
7	REAR OUTER TAIL LIGHT - LH / RH	2	\$ 2,538.00	
8	REAR OUTER TAIL LIGHT TRIM - LH / RH	2		
9	REAR INNER TAIL LIGHT - LH / RH	2	\$ 2,270.00	
10	REAR INNER TAIL LIGHT TRIM - LH / RH	2	\$ 68.00	
11	REAR BUMPER REINFORCEMENT BEAM	1	\$ 1,131.00	
12	REAR BUMPER SEAL - LH / RH	2	\$ 32.00	
13	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 98.00	
14	REAR BUMPER GUIDE SECTION - LH / RH UPPER	2	\$ 52.00	
15	REAR PARKING AID SENSOR - INNER / OUTER	4	\$ 1,062.00	
16	REAR PARKING AID SEAL RING	4	\$ 10.00	
17	REAR BUMPER WIRING SET	1	\$ 745.00	
18	REAR BOOT LID OPENING CONTROL UINIT	1	\$ 520.00	
19	REAR TAILGATE OPENIGN SENSOR LINE	1	\$ 228.00	
20	REAR RETAINER CONTROL UNIT	1	\$ 9.00	
SUB TOTAL SPARE PARTS		:	\$ 13,641.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMC 9171 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR AERIAL KEY ACCESS	1	\$ 120.00	
22	REAR AERIAL RETAINER - LH	1	\$ 29.00	
23	REAR TELEPHONE AERIAL	1	\$ 192.00	
24	REAR LID	1	\$ 4,103.00	
25	REAR LID HINGE- LH / RH	2	\$ 510.00	
26	REAR LID ATTACHMENT PARTS	1	\$ 160.00	
27	REAR LID LOCK	1	\$ 301.00	
28	REAR LID LOCK COVER	1	\$ 13.00	
29	REAR LID FLAP GASKET	1	\$ 263.00	
30	REAR LID LOCK ACTUATOR CAMERA PUSHBUTTON	1	\$ 1,478.00	
31	REAR LID STRIKER PLATE	1	\$ 74.00	
32	REAR LID DRIVE UNIT - LH / RH	2	\$ 4,062.00	
33	REAR LID SERVMOTOR	1	\$ 329.00	
34	REAR LID BOWDEN CABLE	1	\$ 64.00	
35	PACKING ADHESIVE	1	\$ 21.00	
36	AUDI EMBLEM	1	\$ 163.00	
37	"A5" INSCRIPTION	1	\$ 104.00	
38	"TFSI" INSCRIPTION	1	\$ 104.00	
39	REAR WINDOW	1	\$ 1,301.00	
40	WINDOW PRIMER	1	\$ 22.00	
SUB TOTAL SPARE PARTS		:	\$ 13,413.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMC 9171 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	REAR ADDITIONAL BRAKE LIGHT	1	\$ 642.00	
42	REAR HIGH MOUNT LAMP GASKET SET	1	\$ 96.00	
43	REAR SIDE PANEL - LH / RH	2	\$ 8,152.00	
44	REAR QUARTER WINDOW - LH / RH	2	\$ 1,596.00	
45	REAR VENT TRIM - LH / RH	2	\$ 149.00	
46	REAR CROSS PANEL	1	\$ 379.00	
47	REAR CROSS PANEL REINFORCEMENT	1	\$ 668.00	
48	REAR SPARE WHEEL WELL	1	\$ 2,477.00	
49	REAR SPARE WHEEL MOUNTING	1	\$ 150.00	
50	REAR BATTERY CLMAPING STRIP	1	\$ 15.00	
51	REAR CROSS PANEL TRIM	1	\$ 399.00	
52	REAR SPARE WHEEL WELL	1	\$ 254.00	
53	REAR LUGGAGE COMPARTMENT FLOOR COVERING	1	\$ 786.00	
54	REAR LID TRIM PANEL	1	\$ 533.00	
55	REAR STOWAGE COMPARTMENT	1	\$ 58.00	
56	REAR SILENCER - LH / RH	2	\$ 1,902.00	
57	EXHAUST SILENCER BRACKET - LH / RH	2	\$ 90.00	
58	REAR CENTRE SILENCER	1	\$ 956.00	
59	EXHAUST TAILPIPES CHROME TRIM SET	1	\$ 153.00	
60	REAR SILENCER HEAT SHIELD - LH / RH	2	\$ 338.00	
SUB TOTAL SPARE PARTS		:	\$ 19,793.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMC 9171 K

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
61	REAR SILENCER HEAT SHIELD - CENTER	1	\$ 76.00	
62	PRIMER	2	\$ 44.00	
63	ATTACHMENT PARTS	2	\$ 272.00	
64	ADHESIVE TAPES	2	\$ 442.00	
65	REAR NO PLATE	S/N	\$ 60.00	
66	ACRYLIC SEALANT	S/N	\$ 180.00	
67	CAVITY WAX	S/N	\$ 140.00	
68	STONE CHIP	S/N	\$ 180.00	
69	METAL FILLER POWDER	S/N	\$ 280.00	
70	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	
71	BOTH REAR 1/4 GLASS SEALANT	S/N	\$ 200.00	
72	SUNDRIES		\$ 600.00	
TOTAL SPARE PARTS		:	\$ 49,521.00	
TOTAL LABOUR CHARGES		:	\$ 50,604.00	
GRAND TOTAL		:	\$ 100,125.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT