



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBT 6240E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT WHEEL AXLE	NOT NECESSARY	85.00	-
2	STEERING STEM BEARINGS @\$45.00	NOT NECESSARY	90.00	-
1	FRONT LEFT FORK ASSY	NOT NECESSARY	385.00	-
1	STEERING STEM ASSY	NOT NECESSARY	220.00	-
1	LEFT FOOTSTEP	CUT	195.00	195.00
1	FRONT RIGHT FAIRING ASSY	* CHECK	195.00	-
1	HANDLE	* CHECK	145.00	-
1	SET VIEW MIRROR	CUT	140.00	140.00
1	SET BALANCER	CUT	95.00	95.00
1	BRAKE LEVER	CUT	65.00	65.00
1	SET FRONT LEFT SIGNAL	CRACKED	125.00	125.00
1	FRONT LEFT FAIRING ASSY	CUT	195.00	195.00
1	SET FRONT LEFT LOWER FAIRING	CUT	155.00	155.00
2	LEFT SIDE STAND	BENT	95.00	95.00
1	MAINSTAND	BENT	280.00	280.00
1	REAR RIGHT SUSPENSION	NOT NECESSARY	250.00	-
1	LEFT REAR FOOT REST	CUT	85.00	85.00
1	REAR EXHAUST COVER	CUT	98.00	98.00
1	EXHAUST ASSY	NOT NECESSARY	480.00	-
1	REAR BRAKE DISK	NOT NECESSARY	135.00	-
1	ENGINE COVER LEFT	DENTED	265.00	265.00
1	AIR BOX COVER ASSY	CUT	215.00	215.00
1	REAR FENDER ASSY	NOT NECESSARY	265.00	-
1	BOX RACK	CUT	65.00	65.00
	LESS 10% DISCOUNT		-432.30	-207.30
			3,890.70	1,865.70
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	BENT	30.00	30.00
1	REAR SPORT RIM (SN)	NOT NECESSARY	395.00	-
			425.00	30.00

Report Ref No. CS/SMR22012440/Tvy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TOWING CHARGES.		100.00	100.00
	REPLACE, REALIGN AND ADJUST ABOVE DAMAGED PARTS, CHECK WIRING AND LIGHTING SYSTEM.		700.00	300.00
	TO REMOVE, REPLACE AND BALANCE REAR WHEEL RIM.	NOT NECESSARY	120.00	-
	TO KNOCK, STRAIGHTEN CHASSIS & BODY BALANCING.	NOT NECESSARY	380.00	-
	TO REMOVE/REFIT, REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FRONT FORK TUBES.	NOT NECESSARY	180.00	-
	SPRAY PAINTING.		300.00	150.00
			1,780.00	550.00
GRAND TOTAL			6,095.70	2,445.70
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$306.00 NETT)				2,445.70

Report Ref No. CS/SMR22012440/Tvy3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.