



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 1734R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BONNET	BUCKLED	774.90	774.90
2	BONNET HINGES	BENT	156.20	156.20
1	BONNET LOCK	BENT	146.10	146.10
2	HEADLAMP	CRACKED	2,181.20	2,181.20
1	FRT SUPPORT PANEL	BUCKLED	1,228.80	1,228.80
1	FRT BUMPER	TORN	643.00	643.00
1	FRT BUMPER LOGO	NECESSARY	73.10	73.10
2	FRT BUMPER RETAINER	NOT NECESSARY	96.20	-
1	FRT BUMPER CENTRE GRILLE	CUT	765.00	765.00
1	FRT BUMPER TOP RUBBER	NOT NECESSARY	23.20	-
15	FRT BUMPER CLIPS	NECESSARY	75.00	30.00
1	FRT BUMPER CENTRE BEAM	BENT	80.70	80.70
1	FRT BRACE PANEL	BENT	132.10	132.10
1	FRT BUMPER REINFORCEMENT	DENTED	343.40	343.40
1	AIR CON CONDENSER	DENTED	1,350.00	1,350.00
1	RADIATOR	NOT NECESSARY	2,266.30	-
1	FRT BUMPER SPONGE	CRACKED	110.30	110.30
1	RADIATOR AIR GUARD TOP	DEFORMED	58.20	58.20
1	RADIATOR AIR GUARD LOWER	NOT NECESSARY	52.50	-
1	RADIATOR AIR GUARD CENTRE	NOT NECESSARY	321.40	-
	LESS 25% DISCOUNT		-2,719.40	-2,018.25
			8,158.20	6,054.75
<u>SPECIAL NETT ITEMS</u>				
1	FRT NO PLATE (SN)	DENTED	40.00	40.00
			40.00	40.00
<u>LABOUR</u>				
	PANEL BEATING.		1,000.00	700.00
	SPRAY PAINTING.		1,000.00	600.00
	TOP UP GAS.		120.00	120.00
	WIRING .		30.00	30.00

Report Ref No. CS/AGI22012442/Awy3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESEAL OPC CAR PLATE.		50.00	50.00
			2,200.00	1,500.00
GRAND TOTAL			10,398.20	7,594.75
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,000.00

Report Ref No. CS/AGI22012442/Awy3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.