

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/TMI22012448/KQP3Q2**Date:** 11/01/2023**REFERENCE**

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MT110660

Claimant Vehicle No : SHC5797R**Insured Vehicle No :** GBD8128T

Date of Loss: 28/11/2022

Nature of Claim: TP Claim No: M2206819

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHC5797R**

Make & Model: TOYOTA PRIUS, 1.5 (A)

Engine No: 2ZR2N51425

Reg. Date: 31/08/2022 (Man. Year: 2021)

Chassis No: JTDKB3FU703096013

Colour: Metallic Pearl White/Red

Odometer: 12744 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Dunlop 9 mm

Rear Left Side: Dunlop 8 mm

Front Right Side: Dunlop 9 mm

Rear Right Side: Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,553.32	1,097.85	4,455.47	80.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,540.00	505.00	4,035.00	88.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,093.32	1,602.85	8,490.47	84.12
+ GST 7.00/7.00% (S\$)	706.53	112.20	594.33	84.12
Nett Amount (S\$)	10,799.85	1,715.05	9,084.80	84.12

INSPECTION

Date of Assignment: 13/12/2022

Date Inspected: 12/12/2022 Inspected At:

Trans-Cab Services Pte Ltd (HQ)
2 Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 11 Jan 2023)
Parts: 144	TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHC5797R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL SUB-ASSY ,FRONT DOOR ,RH	Bent / Warped	1,300.70 FL	*1,300.70 FL
2	1		*FRAME SUB-ASSY ,FRONT DOOR OUTSIDE HANDLE, RH	Repair	193.50 FL	*- FL
3	1		*HANDLE ASSY ,FRONT DOOR ,OUTSIDE RH	Repair	390.60 FL	*- FL
4	1		*MOTOR ASSY ,POWER WINDOW REGULATOR ,RH	Serviceable	926.00 FL	*- FL
5	1		*WEATHERSTRIP ,FRONT DOOR OPENING TRIM RH	Serviceable	321.10 FL	*- FL
6	1		*HINGE ASSY ,FRONT DOOR ,LOWER RH	Repair	110.60 FL	*- FL
7	1		*HINGE ASSY ,FRONT DOOR ,UPPER RH	Repair	97.50 FL	*- FL
8	1		*REGULATOR SUB-ASSY ,FRONT DOOR WINDOW ,RH	Serviceable	238.30 FL	*- FL
9	1		*TAPE ,BLACK OUT,NO.2 ,FRT RH	Necessary	43.50 FL	*43.50 FL
10	1		*TAPE ,BLACK OUT,NO.1 ,FRT RH	Necessary	13.30 FL	*13.30 FL
11	1		*TAPE ,BLACK OUT,NO.3 ,FRT RH	Necessary	26.30 FL	*26.30 FL
12	1		*PANEL SUB-ASSY ,REAR DOOR ,RH	Repair	1,294.90 FL	*- FL
13	1		*PANEL SUB-ASSY ,REAR DOOR OUTSIDE HANDLE RH	Serviceable	193.50 FL	*- FL
14	1		*HANDLE ASSY ,REAR DOOR OUTSIDE ,RH	Serviceable	97.40 FL	*- FL
15	1		*WEATHERSTRIP ,REAR DOOR OPENING TRIM, RH	Serviceable	293.00 FL	*- FL
16	1		*MOTOR ASSY ,POWER WINDOW REGULATOR ,REAR RH	Serviceable	926.00 FL	*- FL
17	1		*REGULATOR SUB-ASSY ,REAR DOOR WINDOW RH	Serviceable	206.70 FL	*- FL
18	1		*TAPE ,BLACK OUT ,NO.2 REAR RH	Not Necessary	34.90 FL	*- FL
19	1		*TAPE ,BLACK OUT ,NO.3 REAR RH	Not Necessary	15.40 FL	*- FL
20	1		*TAPE ,BLACK OUT ,NO.1 REAR RH	Not Necessary	21.90 FL	*- FL
21	1		*HINGE ASSY ,REAR DOOR ,LOWER RH	Repair	87.10 FL	*- FL
22	1		*HINGE ASSY ,REAR DOOR ,UPPER RH	Repair	98.90 FL	*- FL
23	1		*DOOR STICKER TRASCAB	Necessary	100.00 FS	*60.00 FS
24	1		*DOOR STICKER TEL.NO	Not Necessary	100.00 FS	*- FS
25	1		*DOOR TRIM CLIP	Not Necessary	75.00 FS	*- FS
26	1		*DOOR WEATHERSTRIP CLIP	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,286.10	1,443.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,732.78	345.95
Total Parts (\$\$)	5,553.32	1,097.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST -PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	30.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,600.00	200.00
4	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENT TO FACILITATE BODYWORK REPAIR	New	380.00	0.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	260.00
6	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
7	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	15.00
Gross Labour Cost (\$\$)			4,540.00	505.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >