

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5797R*Not Attached
Penny B4pain***AAD2211-118***1602.85*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

12 DEC 2022**SHC5797R**

JTDKB3FU703096013

TOYOTA

PRIUS GEN 4

28/11/2022

GBD8128T/TOKIO

31/08/2022

PART	LIST
1 PANEL SUB-ASSY, FRONT DOOR, RH	\$ <i>Bt/wap</i> 1,300.70 ✓
1 FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, RH	\$ <i>n</i> 193.50 X
1 HANDLE ASSY, FRONT DOOR, OUTSIDE RH	\$ <i>n</i> 390.60 X
1 MOTOR ASSY, POWER WINDOW REGULATOR, RH	\$ <i>sn</i> 926.00 X
1 WEATHERSTRIP, FRONT DOOR OPENING TRIM, RH	\$ <i>sn</i> 321.10 X
1 HINGE ASSY, FRONT DOOR, LOWER RH	\$ <i>n</i> 110.60 X
1 HINGE ASSY, FRONT DOOR, UPPER RH	\$ <i>n</i> 97.50 X
1 REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH	\$ <i>sn</i> 238.30 X
1 TAPE, BLACK OUT, NO.2 FRT RH	\$ <i>nn</i> 43.50 —
1 TAPE, BLACK OUT, NO.1 FRT RH	\$ <i>nn</i> 13.30 —
1 TAPE, BLACK OUT, NO.3 FRT RH	\$ <i>nn</i> 26.30 ✓
1 PANEL SUB-ASSY, REAR DOOR, RH	\$ <i>n</i> 1,294.90 X
1 FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, RH	\$ <i>sn</i> 193.50
1 HANDLE ASSY, REAR DOOR OUTSIDE, RH	\$ <i>sn</i> 97.40
1 WEATHERSTRIP, REAR DOOR OPENING TRIM, RH	\$ <i>sn</i> 293.00
1 MOTOR ASSY, POWER WINDOW REGULATOR, REAR RH	\$ <i>sn</i> 926.00
1 REGULATOR SUB-ASSY, REAR DOOR WINDOW, RH	\$ <i>sn</i> 206.70
1 TAPE, BLACK OUT, NO.2 REAR RH	\$ <i>nn</i> 34.90
1 TAPE, BLACK OUT, NO.3 REAR RH	\$ <i>nn</i> 15.40
1 TAPE, BLACK OUT, NO.1 REAR RH	\$ <i>nn</i> 21.90
1 HINGE ASSY, REAR DOOR, LOWER RH	\$ <i>n</i> 87.10
1 HINGE ASSY, REAR DOOR, UPPER RH	\$ <i>n</i> 98.90
TOTAL	\$ 6,931.10
25%	\$ 1,732.78
	\$ 5,198.33

Trans-cab Auto Services Pte Ltd

AAD2211-118

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5797R

Special Nett

1 DOOR STICKER TRANSCAB	\$	<i>nn</i>	100.00	<i>born</i>
1 DOOR STICKER TEL. NO	\$	<i>nn</i>	100.00	<i>x</i>
1 DOOR TRIM CLIP	\$	<i>nn</i>	75.00	<i>x</i>
1 DOOR WEATHERSTRIP CLIP	\$	<i>nn</i>	80.00	<i>x</i>
TOTAL	\$		355.00	

TOTAL PARTS \$ 5,553.33**LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$		240.00	<i>301</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i>	380.00	<i>x</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		1,600.00	<i>201</i>
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	<i>nn</i>	380.00	<i>x</i>
Putty And Spray Painting Of The Affected Portion.	\$		1,600.00	<i>261</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i>	170.00	<i>x</i>
To Check Electrical Lighting Concerned.	\$		170.00	<i>151</i>
TOTAL	\$		4,540.00	

Over All Total \$ 10,093.33**(PART-BY-PART) Repair Days***02* Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: