

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Reg. No: 19960	7198R GST Reg. No. 1	9-9607	198-R	
		Affiliated to Federation Internation	onale Des Experts En A	Automo	bile	
	AUTO & GENERA	L INSURANCE (S) PL	F	Ref:	CS/AGI22012449/Tqy3m4	
		TINSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	С	Date:	07/03/2023	
			C	Code:	AGI	
1.		Policy Particulars	:- THIRD PARTY	CLAIN	1	
	Insured Veh.	SLP 6824Z	Veh. Inspected		SKW 4276T	
	Policy No.	P10191455R03	Coverage (\$)		0.00	
	Claim No.	C10019059/CD	Excess (\$)		0.00	
	Assign From	FRAULEINE KHOO	Assign Date		13/12/2022	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA ALTIS	c.c		1598	
	Engine No.	HIDDEN	Year of Reg.		2015	
	Chassis No.	MR053REH104540312	Colour		BLUE	
	Odometer	167800 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	205/55 R16	PIRELLI		6 mm	
	L/H Front Tyre	205/55 R16	PIRELLI		6 mm	
	R/H Rear Tyre	205/55 R16	PIRELLI		6 mm	
	L/H Rear Tyre	205/55 R16	PIRELLI		6 mm	
4.	Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	03/12/2022	Inspection Date		14/12/2022	
	Survey held at	FOCUS AUTO PTE LTD	1			
		NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-48 SINGAPORE 417883				
5a.	a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	DJIN ACCORDANG	Estimate Days of Repair				
0.5.		Estimate	-ajo o. Ropan			

5 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: