

**COMFORTDELGRO ENGINEERING PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO **SHA8258X**  
 MAKE **HYUNDAI**  
 MODEL **IONIQ**

DATE: **12.12.22**  
**MVA JUMANI**  
 DOA: **11.12.22**

**INCOME**

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR DOOR ASSY RH			\$2,147.90
1	REAR FENDER RH			\$1,768.30
1	REAR ROCKER PANEL RH			\$290.00
1	REAR DOOR MOULDING RH			\$125.30
	<b>SUB TOTAL</b>			<b>\$4,331.50</b>
	<b>LESS 20% DISCOUNTED TOTAL</b>			<b>\$866.30</b>
				<b>\$3,465.20</b>
	FRT DOOR COMFORT LOGO			\$75.00
	REAR DOOR APPS LOGO			\$80.00
	ADVERTISEMSNT LOGO - FENDER			\$100.00
	ADVERTISEMSNT LOGO - DOOR			\$200.00
	ADVERTISEMENT LOGO - ROCKER PANEL			\$100.00
				<b>\$555.00</b>
	<b>Labour Charge</b>			
	PANEL BEATING			\$1,200.00
	SPRAY PAINT			\$1,100.00
	REMOVE / REFIX DOOR PARTS			\$120.00
	CHECK WIRING			\$50.00
	TUFF KOTE			\$60.00
	<b>TOTAL LABOUR</b>			<b>\$2,530.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$6,550.20</b>

✓DD  
 ✓DD  
 ✓DEF  
 ?

NET/NEC  
 NET/NEC  
 NET/NEC  
 NET/NEC  
 NEC

**LKK Auto Consultants** to notify  
 the Repairer of the damage  
 • To resurvey before painting  
 • To display damaged parts for survey  
 • Parts prices are based on market survey  
 • Third party survey on a "no win no fee" basis  
 • No illegal modifications  
 • Supplemental parts may be required and  
 is subject to the approval of the Insurance Company  
 Acknowledged by Repairer  
 Signature:  
 Date:

850  
~~850~~ 900  
 50  
 30  
 40

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAZ LKE  
 12/12/2022 1559  
 LLS  
 3 DAYS  
 CHECK ITEM PHOTOS  
 AFTER REPAIR PHOTOS