

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO **SHA8258X**
 MAKE **HYUNDAI**
 MODEL **IONIQ**

DATE: **12.12.22**
 MVA **JUMANI**
 DOA: **11.12.22**

INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR DOOR ASSY RH			\$2,147.90
1	REAR FENDER RH			\$1,768.30
1	REAR ROCKER PANEL RH			\$290.00
1	REAR DOOR MOULDING RH			\$125.30
SUB TOTAL				\$4,331.50
LESS 20% DISCOUNTED TOTAL				\$3,465.20
FRT DOOR COMFORT LOGO				\$75.00
REAR DOOR APPS LOGO				\$80.00
ADVERTISEMENTS LOGO - FENDER				\$100.00
ADVERTISEMENTS LOGO - DOOR				\$200.00
ADVERTISEMENT LOGO - ROCKER PANEL				\$100.00
				\$555.00
Labour Charge				
PANEL BEATING				\$1,200.00
SPRAY PAINT				\$1,100.00
REMOVE / REFIX DOOR PARTS				\$120.00
CHECK WIRING				\$50.00
TUFF KOTE				\$60.00
TOTAL LABOUR				\$2,530.00
ESTIMATE TOTAL				\$6,550.20
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

✓DD
 ✓DD
 ✓DEF
 ?XSVL

NET/NEC
 NET/NEC
 NET/NEC
 NET/NEC
 NEC

LKK Auto Consultant to notify
the Repairer of the findings
 • To resurvey before starting
 • To display damage survey
 • Parts prices are subject to insurance
 • Third party survey on a "Witness
 • No illegal modifications
 • Supplemental terms must be reviewed and
 is subject to final approval by the Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

850
~~900~~
 50
 30
 40

NAZ LKK
 12/12/2022 1559
 CCS
 3 DAYS
 CHECK ITEM PHOTOS
 AFTER REPAIR PHOTOS