

Our Job Ref No : 305539471

Date 15.12.22

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr NAZ

Vehicle Reg No. SHA8258X

Date of Accident : 11.12.22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill 703A INCOME --- SMP3041Z
2. The finalized amount shall be:
 - (a) Spare Parts after List discount _____
 - (b) Labour Charges _____
 - Total for Part-By-Part Repair Cost** _____
 - (c) Lumpsum Repair (if applicable)
 Total for Lumpsum repair cost after Less: 20% \$4,600.00
Final Lumpsum Repair cost _____

3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Signature : 

Name : JUMANI

Name : NAZ

Tel : 62148315

Date : 16/12/2022

Fax : 65468156

For Official Use Only

| Item | Amount | Document Attached Yes or No | Confirm By (Signature) | Remarks |
|--|-----------------|-----------------------------|------------------------|---------|
| 1. Rental Rate P/Day | | YES | | |
| 2. Loss of Income Paid | ---- | NO | | |
| 3. Survey Fees | ---- | --- | | |
| LTA Search Fee | \$7.49 / \$2.00 | YES | | |
| 5. Medical Fees (on behalf of driver, if applicable) | | | | |
| 6 Overrun | | | | |

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO **SHA8258X**
 MAKE **HYUNDAI**
 MODEL **IONIQ**

DATE: **12.12.22**
 MVA **JUMANI**
 DOA: **11.12.22**

INCOME

| Qty | Parts Description/ Labour | Type | Unit Price | Amount |
|-------------------------|-----------------------------------|------|------------|-------------------|
| 1 | REAR DOOR ASSY RH | | | \$2,147.90 |
| 1 | REAR FENDER RH | | | \$1,768.30 |
| 1 | REAR ROCKER PANEL RH | | | \$290.00 |
| 1 | REAR DOOR MOULDING RH | | | \$125.30 |
| SUB TOTAL | | | | \$4,331.50 |
| LESS 20% | | | | \$866.30 |
| DISCOUNTED TOTAL | | | | \$3,465.20 |
| | FRT DOOR COMFORT LOGO | | | \$75.00 |
| | REAR DOOR APPS LOGO | | | \$80.00 |
| | ADVERTISEMENTS LOGO - FENDER | | | \$100.00 |
| | ADVERTISEMENTS LOGO - DOOR | | | \$200.00 |
| | ADVERTISEMENT LOGO - ROCKER PANEL | | | \$100.00 |
| \$555.00 | | | | |
| | Labour Charge | | | |
| | PANEL BEATING | | | \$1,200.00 |
| | SPRAY PAINT | | | \$1,100.00 |
| | REMOVE / REFIX DOOR PARTS | | | \$120.00 |
| | CHECK WIRING | | | \$50.00 |
| | TUFF KOTE | | | \$60.00 |
| TOTAL LABOUR | | | | \$2,530.00 |
| ESTIMATE TOTAL | | | | \$6,550.20 |

✓DD
 ✓DD
 ✓DBF
 ? XSVL

NET/NEC
 NET/NEC
 NET/NEC
 NET/NEC
 ✓NEC

850
~~850~~ 900
 50
 30
 40

LKK Auto Consultant to be notified
the Repairer of the following:

- To resurvey before any painting
- To display damage before any survey
- Parts prices are subject to confirmation
- Third party surveys on a "Without prejudice" basis
- No illegal modifications
- Supplemental items must be approved and is subject to final approval by the Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAZ LKE
 12/12/2022 1559
 CCS
 3 DAYS
 CHECK ITEM PHOTOS
 AFTER REPAIR PHOTOS