12/16/22, 1:24 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road, #16-00 Springleaf Tower

Our File No: CS/CTI22012455/GNP3M4

Singapore 079909 **Date:** 16/12/2022

REFERENCE

Insured/Claimant: LIM CHNG KUAN Policy No: DMPCSNW00029052202

Date of Loss: 03/12/2022 Nature of Claim: OD Claim No: SNM22D208723/C01/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMS2042L

Make & Model: BMW 320I, 2.0 SEDAN AT D/AB 4DR ABS HID Engine No:

(A)

Reg. Date: 28/02/2014 (Man. Year: 2013) Chassis No: WBA3B16050NS50421

Colour: Black Odometer: 0 km

Engine Capacity: 1997 cc

Market Value/New Car

Price: S\$54,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Average

CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		48,454.00	27,929.40	20,524.60	42.36
Miscellaneous Items		460.00	410.00	50.00	10.87
Labour		3,143.00	3,143.00	0.00	0.00
Paintwork Labour		1,232.87	1,232.87	0.00	0.00
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	53,289.87	32,715.27	20,574.60	38.61
	- Excess (S\$)	0.00	1,500.00	-1,500.00	
	(S\$)	53,289.87	31,215.27	22,074.60	41.42
	+ GST 7.00/7.00% (S\$)	3,730.29	2,185.07	1,545.22	41.42
	Nett Amount (S\$)	57,020.16	33,400.34	23,619.82	41.42

INSPECTION

Date of Assignment: 12/12/2022 Present Location: Auto Insure Pte Ltd (HQ) (Woodlands)

Auto Insure Pte Ltd (HQ) (Woodlands)

A6530579N20B20B

Date Inspected: 13/12/2022 Inspected At: 6 Marsiling Lane

Singapore 739145

Estimated Period of Repair: 15.0 days

Adjuster: XING GUO QIANG Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(EXCLUDE CHECK ITEMS S\$19,399.60 NETT)

TOTAL LOSS ASPECT

\$54,000.00 Market Value : OMV: \$35,862.00 PARF Rebate (1): \$17,713.00 Quota Premium Paid: \$75,300.00 COE Rebate (2): \$9,066.00 Total Rebate (1) + (2) = : \$26,779.00

The total amount incurred will be Market Value \$54,000.00 minus Total Rebate \$26,779.00 = \$27,221.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Adjuster Report

REPAIR DETAILS

Reference

12/16/22, 1:24 PM

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Dec 2022)

Parts: 143 BMW 320I 2.0 SEDAN AT D/AB 4DR ABS HID (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMS2042L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No. Qty Part No.	Particulars	Condition	Repairer's	Amount
1 1 F=Franchise part.	*PARTS		48,454.00 F	*27,929.40 F
i –i randiise part.		Total Parts (S\$)	48,454.00	27,929.40
	Repo	ort was unsubmitted during this print-o	out.	

Recommended Miscellaneous Items

No Qty Particulars		Repairer's	Amount
Miscellaneous Items			
1 1 EXTRAS	_	460.00	410.00
	Sub Total (S\$)	460.00	410.00
Recommended Labour			
No Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour			
1 LABOUR FOR SPRAY PAINTING	New	1,232.87	1,232.87
<u>Labour Items</u>			
2 LABOUR FOR PANEL BEATING	New	3,143.00	3,143.00
	Gross Labour Cost (S\$)	4,375.87	4,375.87
Report w	/as unsubmitted during this print-out.		

< END OF ESTIMATES >